

Clifton Park Trustees Annual Project Summaries

Summary for 2010

1. Women's restroom remodeled by CBIA with tile walls, granite countertops, and stainless partitions.
2. Unlocked unisex/handicapped restroom during normal hours.
3. New cabinets, sink & counter tops, in southwest corner of big room.
4. New fiber glass roof on the patio pavilion, prepped and painted the wood pavilion.
5. Beach Rake purchased by CBIA, tractor leased by CPTs.
6. May 7th storm damaged the beach house, the patio pavilion, and trees.
7. Five new trees were planted at the west end in replacement of trees lost on May 7.
8. Shady Lane maintenance.
9. Rule enforcement with respect to park closing overnight, stickers on windshields, guest lists, and limits on picnic table crowd size.
10. Pump House floor replaced and leveled in the northwest quarter of the building.
11. Platform tennis maintenance (\$400) and we committed \$1,000 to match \$2,000 to be raised by the platform tennis players group for a deck heater. This has not been undertaken as yet.
12. No paving repairs were undertaken, the budget was \$5,000.

Summary for 2011

1. Sliding doors were installed in the north center window opening.
2. The John Deere tractor was purchased to pull the Beach Rake.
3. The pump house roof was replaced using insurance money due to damage from the May 2010 hail storm.

4. Maintenance was undertaken to reclaim or reassert CPT ownership of land at 892 Beach Road in front of the Rozakis house.
5. Five new oak trees were planted and three birch trees were relocated along Beach Road approaching the guard house.

Summary for 2012

1. Installed computer system for management of the picnic table reservations in accordance with the newly instituted rules for beach use.
2. Removed obsolete play ground equipment, specifically the pirate ship and large climber structure with the slide, and replaced them with a new “fitness structure” in accordance with a 2004 CBIA plan.
3. Enhanced the “Grove” area to encourage better use of picnic tables there, by cutting the telephone barrier wall north of the playground to a lower uniform height, and by limbing up low branches of trees.
4. Planted two new red maples and relocated two butterfly bushes (from in front of the beach house) to form a row along the boardwalk south of the playground. Also planted four spruce trees on Banks Park to fill in gaps along Clifton Blvd., and one spruce on triangle at Strang’s house to replace one that fell during hurricane Sandy storm.

Summary for 2013

1. Painted center line on Beach Road to attempt to slow traffic.
2. Painted Beach House inside and outside, water sealed the deck handrail.
3. Paved Beach Road around the Lagoon with partial funding, 20% of the total cost, from the Lagoon Trustees in accordance with a Memorandum of Understanding.
4. Friends of the Beach undertook “The Grove Project” to extend the picnic area to the east of the beach house onto the beach by removing a weed patch, installing a limestone perimeter, filling, and sodding. CPTs entered into a MoU with FoB detailing financial arrangements.
5. Installed second toilet and new toilet partitions in the mens restroom.
6. Made maintenance repairs to the platform tennis court with partial assistance from that user group.

7. Inspected the storm drain from the catch basin south of the guard house and found a missing length of 6-inch pipe on Lagoon Trust property. New section of pipe was be installed to drain thru the bulkhead into the boat house boat well at 852 Beach Road.
8. Entered into a MoU with the Lagoon Trustees and the City of Lakewood regarding the docking of a Fire Department boat at the lagoon docks.
9. Surveyed and staked the corral and pump house yard in preparation for the installation of a fence to screen these areas from the lagoon neighbors. Also installed brackets onto the Weber's dock structure to allow the installation of fence posts along the dock.
10. Planted four spruces and four hemlocks on the Clifton Road lot at the Sloan Subway. The spruces on the eastern portion of the lot were planted to hide the brick wall and chain link fence from view.
11. Installed new outdoor-safe electrical panel for platform tennis court lights.

Summary for 2014

1. In April, a sink hole along the river bulkhead approximately 10 x 18 x 5 feet deep, was filled with beach rocks picked up by the rake and sand scraped off roadway.
2. The sink hole re-appeared after a heavy rain on May 13, 2014, in the same location along the river bulkhead but three times larger at approximately 10 x 50 x 8+ feet deep. The cause seemed to be that the muddy river bottom was washed away from the bottom of the sheet piling. The existing sheets were installed by Shoreline Construction in 1990, in accordance with engineering specifications dated September 20, 1989 from Matrix Engineering. The existing sheets are alternating lengths of 15- and 17-feet and were designed to be set into the muddy river bottom, then at a depth of 8- to 12-feet, which was scoured away over time. Thus the sheets did not reach the shale which is at a depth of 22-feet. Approximately 150 lineal feet of bulkhead was replaced with sheet piling pounded to resistance at 22-feet by Shoreline Contractors, Inc., which finished the project on September 24, 2014. [The sheets were pounded into the shale about one foot to assure tightness necessary to prevent another sink hole. The shale at the north end of the replaced bulkhead is approximately two feet higher than at the south end where it is about 22 feet deep.]
3. The playground was improved with the addition of the new pirate ship, the re-arrangement of the stepping pods, painting and updating the large swing set, etc.

The effort was directed by resident Tony Petromica, undertaken with volunteer workers, and was completed before Memorial Day.

4. A wood fence was planned for installation along the pump house and corral property line to screen those areas from the lagoon neighbors' view and to provide safety for users of the Weber's dock which in part has encroached on CPT property since the 1930's. Due to the Weber's concerns about using the brackets attached to their dock for the installation of the fence posts, the fence was completed only in the rear yard of the pump house installed on posts in the ground. The fence on the south edge of the corral was not installed due to the inability to install the fence posts in the ground because of the under ground fill debris in this area. Instead gravel was placed to the same elevation as the dock on CPT property to eliminate a hazardous condition along that section of the dock, and nine cedar arborvitae were planted in a bed placed on top of the existing grade to provide the desired visual screen.
5. In November, a river birch tree was planted centered between two white birch trees to the north of the tennis court, and two scarlet oaks were planted at the point along the river. In addition, the cedar/arborvitae were planted as noted in #4 above.
6. The Beach Road pavement around the lagoon was repaired by filling the cracks with a "hot rubber" compound to prevent water/ice damage.
7. On June 16 repairs were made to the Beach House chimney flashing, to cracks in the dri-vit chimney surface, and to the sanitary vent stack and exhaust fan penetrations of the roof after a leak caused a ceiling tile to fall.