
start = 0/ i = 0
rst_n = 0/i =0
IDLE
00
start = 1 / i = 0
LOAD
01
1 posedge clk / latch sin, cos;
done = 1
1 posedge clk / x = K,
y = 0, z = foled angle
SAMPLE
11
RUN
10
i = 7
i < 7/ i = i + 1