

Product Model: Samsung Digital Inverter 275L

Safety Instructions:

- Disconnect power before inspection.
- Avoid using sharp objects to remove ice.

Issue: Water leakage inside refrigerator

Possible Causes:

- Blocked drain pipe
- Ice buildup near evaporator

Troubleshooting Steps:

1. Check drain hole for blockage.
2. Flush drain pipe with warm water.
3. Ensure refrigerator is levelled properly.

Issue: Unusual noise during operation

Possible Causes:

- Loose internal components
- Fan motor obstruction

Troubleshooting Steps:

1. Inspect fan area for debris.
2. Tighten loose screws if accessible.
3. If noise persists, schedule service.

Escalation:

- Service visit required if fan motor is faulty.