Manufacturing/Build Issues:

Mech 328

Mechanical Engineering

Design Project


DFM: General Issues in the Manufacturing of a Design

©Markus Fengler, All Rights Reserved

Over the Wall

- A design is "finished" (e.g. functional prototype or on-paper design) then "thrown over the wall" to Manufacturing to work out how to actually produce it cost effectively.
- Advantages
 - Don't get bogged in details/constraints; get something to work
 - Focus on function first before worrying about manufacturability may waste fewer resources
 - Experts focus solely on their own area well-defined responsibilities
 - Clarity on responsibility- clear cut-offs between groupsand hand-offs

©Markus Fengler, All Rights



Over the Wall

- · Disadvantages:
 - Slower to market
 - Re-engineering often req'd for manufacturing, cost, regulatory and service issues
 - Long communication chain (delays, risk of misinterpreting)
 - Changes may not maintain design intent (conflicting requirements resolved with bias favouring the maker of changes)
 - As-builts don't match specification documentation making service and upgrades a potential nightmare
 - Wasted resources (time, effort)

Over the Wall





©Markus Fengler, All Rights Reserved

Concurrent Engineering

- Benefit: Overall reduction in time to market/completion with a viable product/installation; capitalize on "window of opportunity"/benefit of early implementation.
- *"First to Market" critical for market position and profitability in new product markets
 - #1 market position is making money
 - #2 market position is breaking even (me too)
 - #3 market position is losing money
- Downsides: inefficiencies; slack times; danger of running fast in the wrong direction; high burn-rate – easier to make fatal mistake
 - *Source: Amos Michelson former CEO Creo products

©Markus Fengler, All Rights Reserved

Concurrent Engineering

- · Simultaneous launch of effort in all departments
- Manufacturing/construction, regulatory, service, product end-of-life issues considered during <u>initial</u> design (people included in the list of stakeholders; needs assessed; requirements and ECs include consideration of manufacturing, installations, service, disposal)
- Start work with incomplete information e.g. begin tooling design for a part that is not yet fully designed
- Feedback between designers, manufacturing/contractors, marketing, distribution and service helps to ensure that the overall profitability of the result is maximized.

©Markus Fengler, All Rights

Part Count

- Every additional part requires
 - Validation
 - Unique part number
 - Inventory space
 - Supplier management
 - Tooling
 - Procedures
 - Handling during manufacture and service
 - Alternate sources identified, etc.
- And adds
 - potential failures
 - requirements for interface
 - contributions to tolerance stack-up
 - can be installed correctly...etc.

Parts: Off-the-Shelf vs. Custom-made

- Advantages
 - · Low cost due to economies of scale
 - · Multiple sources
 - Low lead times possible
 - · Engineering risk low
 - · Installation tools and practices familiar to many
- Disadvantages
 - · Required performance may not be available
 - · Dependency on suppliers
 - · Limited ability to optimize: may pay for unnecessary features
 - Customer can source own replacement parts and possibly own service
 - · Require knowledge of standard parts
 - · Profit on part-making lost

©Markus Fengler, All Rights Reserved

Buy vs. Make: Summary

- In most cases it is very difficult to beat offthe-shelf parts on performance/cost, so it is often best to begin with using them in a design and refining for cost later, unless cost is of very high importance
- Designer needs an "encyclopedic knowledge" of available parts in order to work efficiently

©Markus Fengler, All Rights Reserved

Parts: Off-the-Shelf vs. Custom-made

- Advantages of Custom-made
 - Total control over features (optimize)
 - May increase profitability
 - Cost reduction
 - Replacement parts and service business
 - Retain profit on making of the part
- Disadvantages
 - Development and production cost (money, time, effort)
 - Full risk of design and manufacturing (no part application history)
 - May be single source if special technology req'd (availability and bandwidth)
 - managing the making of the part may be outside of expertise

©Markus Fengler, All Rights Reserved

Options for Making Parts

- · Sometimes you have no choice but to make it.
- Options include making it yourself (in-house) or have it made (contract out):

Make Parts In-house

- Advantages:
 - Total control of quality, cost, proprietary information (core technology)
 - · Optimization possible
 - · Talent, skills stay inside company
 - · Shorter and more secure communication path
- Disadvantages:
 - Investment in workforce, equipment and supplies may not be core to company (distraction of resources, capital)
 - Design constrained by in-house capability

©Markus Fengler, All Rights Reserved

Contract Out: Qualifying Suppliers

- Qualify = ensure supplier is able to deliver what is needed and when
- Typically have to visit site to inspect capabilities, be able to randomly sample regular operation
- Written contract is almost worthless if you can't trust your supplier to deliver when you need your parts.

©Markus Fengler, All Rights Reserved

Contract Out

- Advantages
 - · Lower investment in equipment (focus on core business)
 - Multiple sources (can "Wal-Mart" suppliers)
 - · Access to expertise, capability not available in-house
 - · Costs are very evident
- Disadvantages
 - · Risk of information leaks (know-how, production plans)
 - Risk with less control (how is their business doing?)
 - Loyalty risk
 - · Contractor retains some profit
 - Changes somewhat more difficult to communicate and implement (contractual obligations)

©Markus Fengler, All Rights Reserved

Other Issues...

Complexity of Geometry

More features often =
 higher development
 and production cost,
 higher risk, higher
 service cost, but can
 reduce assembly cost if
 part is replacing
 multiple other parts



©Markus Fengler, All Rights Reserved

Raw Materials

- Availability
 - Preferred sizes, grades, form processing
- At low production volumes with high complexity material costs can become insignificant
- Lowest cost material is not necessarily bestconsider processing costs, joining, need for finishing (plating?), life, reliability, etc.
- Economies of scale don't apply in small

©Markus Fengler, All Rights Reserved

Materials Choice

Typically constrains processing

- · Machining:
 - -e.g. cutting speeds for 1018 steel, 316 stainless and 6061 aluminum are 90, 45 and 200 SFPM respectively (HSS cutter)
- Welding: alloying elements, HAZ
- Forming: ductility
- Finishing requirements: protective coatings







Where to Find Process Descriptions

- Talk to the folks who do it!
- MECH 392©
- References: Machinery's Handbook, Knovel
- Equipment manufacturer sites
- E-funda, Eng-tips, Practical Machinist, CNC Zone, American Machinist
- Engineering and trade magazines: Machine Design, Design News
- https://www.sheldonbrown.com/bridgestone/1994/ind ex.htm
- Youtube

Processing

Wider variety of processes = increased cost + risk due to wider variety of equipment, skill-sets and increased time

©Markus Fengler, All Rights Reserved

Design Issues Affecting Assembly and Installation of Parts

- Part Fit
- Tool Access
- Complexity of Assembly
- · Assembly Processes required
- Size (handling)

©Markus Fengler, All Rights Reserved

Machining Costs

- · Very volume dependent
 - Small volume and high variety =High cost/part
 - Large volume and low variety = low cost/part
- Compare relative costs by number and variety of size, location orientation of features, relative machinability of material, size, measure the amount of chips removed.

©Markus Fengler, All Rights Reserved

Assembly

- Part Fit
 - Larger tolerances on interfacing features make assembly easier but are constrained by performance requirements


(may be need for adjustment to optimize performance; can assembly be put together yet be not meet requirement?)

Assembly

· Assembly Tool Access

· Assembly Sequence





• See Machinery's Handbook (e-books, UBC Library)

Assembly

- Complexity
 - Increase in Assembly Complexity = increase in:
 - · assembly time
 - · risk of error
 - · constraint of access for assembling and servicing
 - · part inventory, tracking costs
 - Higher complexity justified by increase in performance needed to meet a requirement or overall reduction cost

©Markus Fengler, All Rights Reserved

Assembly

- Assembly Tool Access
 - Requires familiarity with tools used for assembly/disassembly
 - Reduce requirement with fewer parts
 - Solid modeling makes this much easier to evaluate prior to build

©Markus Fengler, All Rights Reserved

Assembly

- DFMA
 - Minimize the number and the variation in fasteners and other small components
 - Assemble from one side or top using gravity
 - Minimize re-orientation, tools, possible incorrect installation, etc.
- Evaluate complex parts vs. complex assemblies

Assembly Conditions

- Field assembly site conditions (outside, in the rain?)
- Handling: assembly sequence (e.g. press fit supports, tool access, routing of wiring)



©Markus Fengler, All Rights Reserved

• Size

Assembly



https://encryptedtbn1.gstatic.com/images?q=tbn:ANd9 GcQS7PIKnAXaCJGnnYRfqXsG0OSI UJD4_Ii-q7yDnoOEKSdUqnFN-Q



©Markus Fengler, All Rights Reserved https://encryptedtbn1.gstatic.com/images?q=tbn:A Nd9GcTCsl6Gbqg82o9SS0eRLIT a0GVykz2mlPhVSVMlwWqKdiBX

Installation



Service




- In the field servicing can be difficult if:
 - Parts are large or heavy or extremely small
 - Many tools or supplies are required
 - Special equipment is required
 - Assemblies can be adjusted out of spec
 - Diagnostic features absent
- This may be ok if your customer is willing to pay for service and you are making money (Finning, Heidelberg Druckmaschine)

- Cost of replacing faulty part during initial assembly \$
- Cost of replacing before shipping \$\$\$
- Cost of replacing after shipping \$\$\$\$\$

©Markus Fengler, All Rights

Service

 Service tool access and service personnel sightlines




Service

- In the field servicing can be difficult if:
 - Parts are large or heavy or extremely small
 - Many tools or supplies are required
 - Special equipment is required
 - Assemblies can be adjusted out of spec
 - Diagnostic features absent
- This may be ok if your customer is willing to pay for service and you are making money (Finning, Heidelberg Druckmaschine)

©Markus Fengler, All Rights Reserved

Design Issues Affecting **Service**

- · Disassembly possible without damage
- Sometimes damage can't be avoided:
 - Design for in-the-field replacement



EoL

- Don't forget End of Life costs!
 - E.g. a more expensive material should be selected if doing so reduces cost of decommissioning, disposal or recycling and net costs are reduced

©Markus Fengler, All Rights Reserved

Summary:

 In very general terms, the best design often consists of a minimal number of mostly standard parts, is easy to assemble and disassemble quickly, easy to transport, install and service and (more recently) is easy to decommission for recovery and recycling.

> ©Markus Fengler, All Rights Reserved

DFx: Impact on Overall Cost is Important

- Don't blindly reduce costs in one area while overlooking costs added in other areas
 - a lower cost material may require higher finishing costs
 - a lower cost component may increase warranty costs
 - a higher cost production process may be much faster, more reliable, more accurate, etc. thereby saving money in the long term