
Ask



Best answer (via GerZ on 29-11-2018 23:33)



Chris_82

Wednesday, November 28, 2018 4:14 PM

@ GerZ Have you seen this post from @ Oxellaar

Oxellaar in "Air/Water heat pump for heating and cooling #5"

14.4kWp, Loria Duo 6010, VWTW, DWTW, full electric.

All comments



Tunda


Tweakers uses cookies

When visiting the forum, Tweakers only places functional and analytical cookies for optimization and analysis to improve the website experience. No tracking cookies are placed on the forum. We ask for your permission to view videos and graphics from third parties, we use external tooling that may place cookies.


More information can be found in our cookie policy.

accept all

Only necessary







Tweakers uses cookies


When visiting the forum, Tweakers only places functional and analytical cookies for optimization and analysis to improve the website experience. No tracking cookies are placed on the forum. We ask for your permission to view videos and graphics from third parties, we use external tooling that may place cookies.

More information can be found in our cookie policy.

accept all

0

Only necessary



This is how you can fix this problem "for free"

Removing skewers below 4 degrees doesn't help. Eventually the whole sensor freezes and goes way below 0.

I've even seen -10 with the sensor in the original spot.

In fact, the Elga didn't even get to a defrost, but turned on the boiler.

Slowly Elga thawed and came back in, only to play the same song again.

Reported this error to Techneco.... But they didn't know the problem, very strange, because everyone suffers from it.

[Edited for 64% by Oxellaar on 28-11-2018 17:08]

Samsung A3050/AR7000 - Elga 3.0

Tweakers uses cookies

When visiting the forum, Tweakers only places functional and analytical cookies for optimization and analysis to improve the website experience. No tracking cookies are placed on the forum. We ask for your permission to view videos and graphics from third parties, we use external tooling that may place cookies.

More information can be found in our cookie policy .

accept all

Only necessary

2/16/22, 2:57 PM Elga "outdoor sensor" - Renewable energy and installations - GoT Incidentally, my Elga through p62 happily continues to -10 and I have never seen that on the thermostat. 3120WP Omnik, 4825WP SolarEdge and heating with an Elga. Oxellar 0 Sunday, December 2, 2018 10:50 PM @ Aziraphale you don't have to disassemble much to get to it, 4 screws loose from the top cover. You cannot run with this depending on the weather, you really need the outdoor sensor on the indoor unit for that. P62 is on me - 4 I thought. And -4 was already measured above 0 at the old position of the sensor after a 20 minute run. [Edited for 22% by Oxellaar on 02-12-2018 22:53]

Aziraphale

Monday, December 3, 2018 09:43

Samsung A3050/AR7000 - Elga 3.0

0

Okay, thanks! That problem does not occur with me, on the thermostat I just keep seeing the outside temperature that my other thermometer also indicates.

3120WP Omnik, 4825WP SolarEdge and heating with an Elga.



hansengriettina

Wednesday, January 30, 2019 20:41

0

the sensor has also been moved. Techneco previously indicated that this was not possible, but they say that the problem is known.

[Edited 57% by hansengriettina on 01-02-2019 12:23 PM]



Tweakers uses cookies

When visiting the forum, Tweakers only places functional and analytical cookies for optimization and analysis to improve the website experience. No tracking cookies are placed on the forum. We ask for your permission to view videos and graphics from third parties, we use external tooling that may place cookies.

accept all

Only necessary

Adjust preferences

More information can be found in our cookie policy.

temperature jump in the measured outside temperature. As an example: I see on the thermostat that the outside temperature is +3 degrees. Then I set the P63 value slightly differently, eg from 4 degrees to 2 degrees. As soon as I confirm the setting and the thermostat returns to normal mode, the measured outside temperature suddenly stands at +6 degrees.

All this in 2 minutes! It cannot be the case that the outside temperature differs so much in such a short period of time. My suspicion is therefore that the electronics that transmit the measured value are very unstable. This could be caused by an alternating supply voltage (DC) of the print electronics in the outdoor unit.

If someone has a good schematic of the PCB in the outdoor unit of the ELGA I would like to have that too. It is also interesting to hear if more ELGA users recognize this problem?





I have made a schedule for those who are interested.

Outrageously expensive for next to nothing


Tweakers uses cookies

When visiting the forum, Tweakers only places functional and analytical cookies for optimization and analysis to improve the website experience. No tracking cookies are placed on the forum. We ask for your permission to view videos and graphics from third parties, we use external tooling that may place cookies.

More information can be found in our cookie policy .

accept all
Only necessary

The sensor is an SMT172, the rest of the circuit is only for protection against incorrect connection.





ELGAAVDS

Wednesday, February 17, 2021 6:45 PM

0

Well done. I am curious if you see a stable reading on your thermostat. In my case, the reading swayed over a range of 3-4 degrees.



HMvdSilks

Thursday, February 25, 2021 20:27

0

I use the Elga with my own control, separate from the boiler and without the thermostat. I therefore do not control based on the outside temperature sensor of the elga, I use my own sensors. I needed the outdoor sensor because the elga is difficult to control without the outdoor sensor and it keeps freezing and thawing because it has no idea of the outside temperature. He needs his own outdoor sensor to allow him to follow the correct heating curve.



Tweakers uses cookies

When visiting the forum, Tweakers only places functional and analytical cookies for optimization and analysis to improve the website experience. No tracking cookies are placed on the forum. We ask for your permission to view videos and graphics from third parties, we use external tooling that may place cookies.

accept all

Only necessary

Adjust preferences

More information can be found in our cookie policy.