

Sprint Review_Test





Alarms Dist.

,	Acknowledge			
	Labels	Count	Percentage	
	acknowledged	12	-	1%
	not acknowledged	2014		99%
	Total:	2026		



Severity

Argument	Value
AC Surge Protector Fault	36
ALD Maintenance Link Failure	81
Automatic Version Rollback	10
BBU CPRI Optical Module or Electrical Port Not Ready	44
BBU Fan Stalled	2
Board Clock Input Unavailable	5
Board Hardware Fault	2
Board Not In Position	166
Board in Wrong Slot	6
Burglar Alarm	102

Labels	Count	Percentage	
	19		1%
Allunghari	65	•	3%
BSC	7		0%
Bakau Newtown	9		0%
Banjul Tower	1		0%
Banjulinding	24		1%
Bato Kunku	2		0%
Bijilo II	14	-	1%
Brikama Cow	5		0%

Enodebs

