



Republic of the Philippines
Department of Education
Region VII, Central Visayas
SCHOOLS DIVISION OF TOLEDO CITY

SCHOOL RISK ASSESSMENT REPORT SY 2025-2026

School Name: **Ibo Elementary School**
School ID: **120745**
Address: Ibo, Toledo City
Date of Assessment: April 17, 2026
Prepared by: Hannah P. Abasa
Designation: Administrative Officer

SCHOOL PROFILE

Total Land Area 4488 square meters

No. of Buildings 4

No. of Classrooms 18 FUNCTIONAL
(16 used for learners' classroom,
1 converted to principal office/semi library)
1 converted to a school canteen/faculty room)

0 NON FUNCTIONAL

Enrollment 307 Male
257 Female
564 Learners: SY 2025 - 2026

Personnel 20 Teaching
2 Non-Teaching

SPED Learners None


SUMMARY OF HAZARDS IDENTIFIED

Quick Guide

	LOW - SAFE / NOT urgent
	MEDIUM - Needs Attention
	HIGH - Act immediately




Republic of the Philippines
Department of Education
 Region VII, Central Visayas
SCHOOLS DIVISION OF TOLEDO CITY

AREA / LOCATION	TYPE OF HAZARD	DESCRIPTION OF HAZARD	RISK LEVEL	POSSIBLE IMPACT	EXISTING MEASURES	RECOMMENDED ACTION	TIME LINE
School Clinic	The school clinic is exposed to structural hazards due to its deteriorated and rusted roofing, as well as flood and coastal hazards caused by high tide, heavy rains, and the school's low-lying coastal location.	deteriorating condition of its roofing materials. The roof has already become heavily rusted and weakened over time.	 Yellow	vulnerable to leaks, possible damage during strong winds, and potential safety risks to learners and school personnel using the facility.	Though usable but we opt to close first the clinic for learners safety	It is recommended that the roofing of the school clinic be immediately repaired or replaced to prevent leaks, further deterioration, and possible safety hazards to learners and school personnel. Additionally, flood mitigation measures such as elevation of the clinic flooring, improvement of drainage systems, installation of water barriers, and relocation or elevation of medical supplies and equipment should be implemented to minimize the impact of flooding during high tide and heavy rains. Regular monitoring and maintenance of the clinic facility should also be conducted to ensure the safety, sanitation, and continuous delivery of health services within the school.	To Be Determined A proposal for the renovation of the school clinic has already been identified and endorsed by the Schools Division Engineer; however, the implementation schedule and timeline are still subject to approval and availability of funds.



Republic of the Philippines
Department of Education
 Region VII, Central Visayas
SCHOOLS DIVISION OF TOLEDO CITY

School Sea Wall	Structural Hazard / Coastal Hazard / Flood Hazard	The school seawall has already been damaged and weakened due to continuous exposure to strong waves, coastal erosion, high tide, and severe weather conditions. Portions of the seawall show visible cracks and deterioration, reducing its ability to protect the school premises from seawater intrusion and flooding	 Red	The damaged seawall may result in flooding of the school grounds during high tide and heavy rains, soil erosion, and further damage to classrooms, school facilities, and properties. It also poses safety risks to learners, teachers, and personnel, especially during storms and coastal disturbances.	Continuous monitoring of the seawall condition is being conducted by the school. Temporary precautionary measures and coordination with the barangay and concerned offices are also being undertaken during severe weather conditions and high tide occurrences.	Although there is already an existing proposal for the relocation of the school due to its vulnerability to coastal hazards and flooding, continuous monitoring of weather conditions and regular coordination with the Local Government Unit (LGU) and other concerned government agencies shall serve as immediate short-term measures to ensure the safety and preparedness of learners, teachers, and school personnel. Additionally, disaster preparedness activities, early warning mechanisms, and temporary protective measures should be strengthened while awaiting the implementation of the proposed school transfer.	To Be Determined A proposal for school relocation.
-----------------	---	--	--	--	---	--	---




Republic of the Philippines
Department of Education
 Region VII, Central Visayas
SCHOOLS DIVISION OF TOLEDO CITY

DPWH BOD Building	Structural Hazard / Coastal Hazard / Flood Hazard	The BOD Building is located in a low-lying area near the coast, making it highly vulnerable to flooding caused by high tide, strong waves, and heavy rains. Due to its low elevation, floodwaters can easily enter the building during severe weather conditions. Continuous exposure to seawater, moisture, and strong coastal	 Yellow	Possible impacts include flooding inside the building, damage to school property and learning materials, disruption of classes and school activities, weakening of the building structure, and safety risks to learners, teachers, and personnel during heavy rains, high tide, and storm surges.	The school continuously monitors weather conditions and tidal levels, implements precautionary measures during heavy rains and high tide, and coordinates with barangay officials and DRRM personnel to ensure the safety of learners and school personnel.	Although there is already an existing proposal for the relocation or improvement of vulnerable school facilities, continuous monitoring of weather conditions and regular coordination with the Local Government Unit (LGU), DRRM offices, and other concerned government agencies shall serve as immediate short-term measures. Elevating important materials and equipment, strengthening disaster preparedness activities, and conducting regular structural assessments are also recommended while awaiting long-term solutions.	To Be Determined. Proposed rehabilitation, elevation, or relocation measures remain subject to technical assessment, approval, and availability of funds from concerned agencies.
-------------------	---	--	---	--	--	---	--



Republic of the Philippines
Department of Education
 Region VII, Central Visayas
SCHOOLS DIVISION OF TOLEDO CITY


		winds may also contribute to the gradual deterioration of the building structure and facilities.					
National Highway Road	Vehicular Accident Hazard / Highway Road Hazard	The school is located near the national road/highway, exposing learners, teachers, and school personnel to possible vehicular accidents caused by passing vehicles, traffic congestion, and speeding motorists. The	 Red	Possible impacts include injuries or accidents involving learners, teachers, parents, and school personnel, disruption of classes and school activities, and threats to the overall safety and security	The school continuously reminds learners to observe road safety precautions and coordinates with barangay officials and concerned authorities during school activities and peak traffic hours. Teachers and	It is recommended to strengthen road safety measures by installing warning signs, pedestrian lanes, barriers, and traffic control devices near the school premises. Coordination with the Local Government Unit (LGU), barangay officials, and traffic management authorities should also be intensified to ensure proper traffic regulation and learner safety, especially during arrival and dismissal periods.	Immediate and continuous implementation while awaiting additional support and long-term road safety improvements from concerned agencies.



Republic of the Philippines
Department of Education
Region VII, Central Visayas
SCHOOLS DIVISION OF TOLEDO CITY

		continuous movement of vehicles near the school premises increases the risk of road-related incidents, especially during arrival and dismissal times of learners.		of individuals within the school premises	school personnel also assist in monitoring learners near the roadside area.		
--	--	---	--	---	---	--	--

Prepared by:


HANNAH P. ABASA
School DRRM Coordinator

Reviewed and Checked by:


MAIDA A. PAÑARES
School Head



Republic of the Philippines
Department of Education
 Region VII, Central Visayas
SCHOOLS DIVISION OF TOLEDO CITY

SCHOOL WATCHING CHECKLIST

✓	Broken window	✓	Broken/dilapidated ceiling
✓	Slippery pathway		Open/incomplete perimeter fence
	Blocked corridor		Presence of stray animals inside the school campus
	Heavy objects mounted on top of cabinets/shelves		Presence of electrical post/transformer near or within the school perimeter
✓	Flooded area		No system of release to parents during emergencies
✓	Busted plugs/light bulbs/electrical facilities		No posted emergency hotlines around the school
✓	Exposed electrical wires	✓	Garbage Area (Segregation of Biodegradable and Non-Biodegradable)
✓	Protruding nails in chairs and tables		Detached or peeled off GI sheet
	Broken door knobs	✓	Broken toilet bowl and/or sinks
✓	Warning sign: Slippery pathways/corridors	✓	Broken chairs/desks/tables
	Plants mounted on the building railings		Blocked/no emergency exits
✓	Flooding	✓	Unmounted cabinets/shelves
	Exposed chemicals and liquids		Medical kits in every classroom
✓	Lack/absence of storage for equipment		Bells / alarms
	Unlabeled chemicals	✓	Condemnable building (i.e. very old structure, collapsing building and/or prominent cracks on classroom walls)
✓	Dripping ceiling		Open/Clogged canals
	Open pit	✓	No ramps for elevated school buildings or other facilities
	Stagnant water		Swing-in doors
	Unpruned trees/bushes/shrubs		