## **Purchase Order**

Brigham Young University BRIGHAM YOUNG UNIVERSITY

BRIGHAM YOUNG UNIVERSITY PURCHASING DEPT ASB C-40 PROVO UT 84602-1116 United States

> Supplier: 0000003582 LAB PRODUCTS 2225 PULASKI HWY ABERDEEN MD 21001

Dispatch via Print

Purchase Order	Date	Revision	Page	
BYU-0000038502	06/30	/1999 1 - 06/3	30/1999 1	
Payment Terms	Freight Terms		Ship Via	
NET 30	FOB Origin, Bu	yer Bears Frt	. Roadway	
			Express	
			(Collect)	
Buyer	Phone	/Email	Currency	
Hatch, Steven Ne	elson 801/4	22-7014	USD	
	steve	steve_hatch@fscpy.byu.edu		

Ship To: RECEIVING

BRIGHAM YOUNG UNIVERSITY CENTRAL RECEIVING 685 E UNIVERSITY PKWY PROVO UT 84602-1830 United States

Attention: Not Specified

BIII To: BRIGHAM YOUNG UNIVERSITY

FINANCIAL SERVICES

A-153 ASB

PROVO UT 84602-1128

**United States** 

Tax Exempt? Y Tax Exempt ID: N10020	Replenishment Option: Standard				
Line-Sch Item/Description	Mfg ID	Quantity UOM	PO Price	Extended Amt	Due Date
1- 1 REPAIR OF DAMAGED MODIFIED BIOCLEAN RCS #H-5020		1.00EA	3,000.00	0.00	CLOSED
		Schedule Total	_	0.00	
		Item Total	_	0.00	

THIS UNIT WAS ORDERED FROM LAB PRODUCTS (INV# 051423 AND PO# BYU0000029218) AND WAS DAMAGED DURING SHIPPING. WE ARE SENDING THE UNIT IN TO GET IT REPAIRED. PLEASE CALL US WITH AN ESTIMATE PRIOR TO DOING ANY WORK.

SHIP ROADWAY FOB ORIGIN - COLLECT LESS THAN TRUCKLOAD (LTL) ONLY. SHOW BYU PURCHASE ORDER NUMBER ON THE FREIGHT BILL. THE USE OF ANY OTHER METHOD WILL RESULT IN A CHARGE BACK FOR ANY ADDITIONAL FREIGHT COSTS INCURRED. VENDOR ACCEPTS LIABILITY FOR DAMAGES IF ABOVE DIRECTIONS ARE NOT FOLLOWED.

CHANGE ORDER #1

LAB PRODUCTS CALLED WITH REPAIR EXTIMATE AND I CHANGED PRICE FROM \$0 TO \$3,000 FOR THE REPAIR. WE ARE GOING TO FILE A CLAIM WITH ROADWAY BECAUSE THE ITEM WAS DAMAGED UPON ARRIVAL.

\*\*PLEASE CONTACT STEVE HATCH (801) 378-7014 TO ARRANGE SHIPPING METHOD BACK TO BYU. WE WILL ARRANGE FOR ALLIED VAN LINE/COLLECT TO PICK UP.\*\*

Total PO Amount	0.00