## **Purchase Order**

Brigham Young University BRIGHAM YOUNG UNIVERSITY

BRIGHAM YOUNG UNIVERSITY PURCHASING DEPT ASB C-40 PROVO UT 84602-1116 United States

> Supplier: 0000017743 TEAC AMERICA TASCAM ATTN: FACTORY SERVICE 7733 TELEGRAPH RD MONTEBELLO CA 90640

Dispatch via Print

| Purchase Order   | Date          |           | Revision     | Page     |  |
|------------------|---------------|-----------|--------------|----------|--|
| BYU-0000034959   | 03            | 3/05/1999 | 9 1 - 03/05/ | 1999 1   |  |
| Payment Terms    | Freight Terms | 3         |              | Ship Via |  |
| NET 30           | FOB Origin    | , Buyer E | Bears Frt.   | UPS Red, |  |
|                  |               |           |              | Next Day |  |
| Buyer            | Phone/Email   |           |              | Currency |  |
| Whitney, Kristir | na R.         |           |              | USD      |  |

Ship To: RECEIVING

BRIGHAM YOUNG UNIVERSITY CENTRAL RECEIVING 685 E UNIVERSITY PKWY PROVO UT 84602-1830 United States

Attention: Not Specified

Bill To: BRIGHAM YOUNG UNIVERSITY

FINANCIAL SERVICES

A-153 ASB

PROVO UT 84602-1128

**United States** 

| Tax Exempt? Y Tax Exempt ID: N10                            | 020    | Replenishment  | rd       |              |          |
|---|--------|----------------|----------|--------------|----------|
| Line-Sch Item/Description                                   | Mfg ID | Quantity UOM   | PO Price | Extended Amt | Due Date |
| 1- 1 REPAIR TASCAM CD-401MKII C<br>PROBLEM: WON'T SPIN UP I |        | 1.00EA         | 273.92   | 0.00         | CLOSED   |
|   |        | Schedule Total | _        | 0.00         |          |
|   |        | Item Total     | _        | 0.00         |          |

PLEASE RUSH CLAIM# 215640 ADVISE THE BUYER WHO SIGNED THIS ORDER OF REPAIR COST PRIOR TO PROCEEDING SHIP UPS RED, NEXT-DAY FOB ORIGIN. SHOW ACCOUNT # 890028776 AND PO NUMBER. TO SCHEDULE PICK-UP CALL (800) 742-5877. THE USE OF ANY OTHER METHOD WILL RESULT IN A CHARGE BACK FOR ANY ADDITIONAL FREIGHT COSTS INCURRED. VENDOR ACCEPTS LIABILITY FOR DAMAGES IF ABOVE DIRECTIONS ARE NOT FOLLOWED.

UNIT SENT BACK IN FOR REPAIR. NEW CLAIM# 217293. 5/20/99 KRW

CHANGE ORDER #1
PRICE PUT INTO SYSTEM TO REFLECT VENDOR ESTIMATE FOR REPAIR PER KIM 323-727-7627. CLAIM#215640.
SHOULD BE COMPLETED AND SHIPPED BY NEXT WEEK. 3/4/99 KRW