
Critical Buckling Temperature vs. a/h for Different Porosities
Solid Plate (e0 = 0)
Low Porosity (e0 = 0.2)
Med Porosity (e0 = 0.4)
High Porosity (e0 = 0.6)
ΔT_{cr} [°C]
Slenderness ratio a/h
0
200
400
600
800
1000
1200
0
20
40
60
80
100
120