



Harry Lo &lt;harrykhlo@gmail.com&gt;

## Missed or Concerned Items: Construction of 2 Rapere Street, Rolleston.

1 message

Harry Lo &lt;harrykhlo@gmail.com&gt;

To: Ricky Wong <jsrconstruction.nz@gmail.com>  
 Cc: Sze Ping Jessica Lo <jlee2609@yahoo.com.hk>


Tue, Feb 28, 2023 at 12:59 AM

Hi Ricky,


Thank you for your effort in building our house.

However, we are concerned about the following 35 items when they will be correctly in place. We have photo records for those items. Please do not hesitate to check with our photo records if you could not identify any of the items according to the descriptions below.


- 1) Strip drain
- 2) CCTV socket exposed to weather (e.g. raining) and got painted. Please make sure the connectors can conduct properly and will not damage the connector socket at the cameras.
- 3) Missing safety double switch bathroom power socket opening in ENS of Bedroom 2
- 4) Replacement of incorrect shelf board on top of wardrobe in the WIR of Bedroom 2 with which your subcontractor has agreed
- 5) Either one of the ph/internet, power and TV sockets in Bedroom 2 is missed



- 6) Power points for heated tower rail and bathroom heater are missed in the ENS of Bedroom 2



- 7) Either one of the ph/internet, power and TV sockets in Master Bedroom is missed




- 8) Either one of the ph/internet, power and TV sockets in Bedroom 4 is missed





- 9) Either one of the ph/internet, power and TV sockets in Bedroom 3 is missed

missed  
either one



10) Does hot water cylinder need safety tray?


11) Rail for guest hanging clothes inside the small storage near main entrance is missed



14) Heatpump duct damaged at the ceiling manhole


15) Lossnay Ventilation system is missed. It should have at least one air fresh air outlet in each room. See the screenshot below extracted from the Lossnay guide.

- EXTRACTS STALE AIR  
Extracts stale air removing toxins and reducing humidity.
- SUPPLIES FRESH AIR  
Supplies fresh air increasing the oxygen levels in the home and assists with managing the build up of moisture.
- ☒ HEAT ENERGY RECOVERY  
Recover up to 86% of the heat energy from the outgoing air to preheat the incoming air, saving you money.




- 16) 3 phases cable is wrong
- 17) Manhole ladder is incorrect (the length of ladder has not yet be adjusted correctly)
- 18) Either one of the phone/internet or double switch power sockets is missed in the garage
- 19) Supporting brackets of the sink in laundry are missed
- 20) Supporting brackets of the sink in kitchen are missed
- 21) Silicon seal at the bottom of wall at the back of washing and dryer machine in the laundry is missed


silicon seal  
missed



- 22) Skirts next to both end of the bench in the storage next to the WIP are missed




23) Double switch power socket and phone/internet socket at the back of kitchen bench top are missed




24) TV antenna is missed

25) Either one of the phone/internet, power and TV sockets in Living Room is missed



- 26) Either one of the phone/internet, power and TV sockets in Lounge is missed

One of 3 is missed



27) Have you added the double switch power socket, internet socket, two lights and light switch for the attic truss storage? (see email on Oct 9, 2022, 7:26 PM)

Additional items at attic truss storage in the roof,


- Double switch power socket
- Internet socket
- two lights
- Its light switches at garage

Additional Strip LED light under Overhang Cabinet


CCTV Camera




28) Have you move the phone/internet socket from WIP to the study room in the lounge? It was agreed with electrician during the site walk in September 2022.



29) Light switch at the back door of the lounge is missed



30) Light switch at the toilet of lounge is missed



- 31) Fridge water tap is missed
- 32) When should we provide you the CCTV system?
- 33) When should we provide you the outdoor waterproof power sockets?
- 34) All indoor lighting is missing
- 35) All extracted fans in bathroom and showers are missed.

Please do not hesitate to contact us if there is any incorrect information or are any problems.

Thank you for your attention.

Kind regards,

Harry