

MRPL INCIDENT REPORT - INC-2023-09 (Flange F-104 Gas Leak)

Date of Incident: 2023-09-14 | Severity: HIGH | Classification: CONFIDENTIAL

Root Cause Summary:

Maintenance crew used obsolete torque specifications from SOP-CRU-401 v1.0 (220 Nm instead of 300 Nm required by current v3.2).

Corrective Action: AI Workbench must enforce version policy before permit release.