TECHNICAL IMPROVEMENT No-SC/CV/TI/14-15_393 Dt.-12.02.2015

SUB GROUP: DSL FL

Model: Optima & Maxima

To:


All vehicle Dealer-CV
All Authorized service centers-CV

IMPROVEMENT: .MODIFIED FRONT MUDGAURD- MAXIMA & OPTIMA DSL

Reason for Change: To improve quality- better resistance to corrosion

Modification details: FRONT MUDGAURD- ZINC COATED SHEET-

- 1. Material changed to cold rolled steel sheet/strip,
- 2. Hemming region Improved.



Part No Details: Serviceable part no: BB161099-Front mudguard remains same & is interchangeable. ED coated part no is **52BB0075**

Implementation cut-off details:

Model Name	Chassis/Engine No	Impl. date
RE Maxima	MD2A41AZ2FWK01488	10.01.2015
RE Optima DSL	MD2A28AZ5FWK00088	10.01.2015

Please bring this information to the notice of your concerned staff. Kindly make Copies as required for circulating to your branches spares division etc.

Please confirm the improvement after modification appropriately.

Thanking You,

SERVICE SUPPORT –CV BAJAJ AUTO LIMITED

CC : All Area Service Managers

: All Regional Training Heads / Technical Service/ All Area Sales Managers

Ref ECR: - U14AACHA0240