

TILSTANDSVURDERING

LAND ROVER FREELANDER 2

Rapport generert av Munin OBD-II AI System

28. juni 2026

Eier	Petter Hartmann
Adresse	Myrane 5
Reg.nr	KB 35350
VIN	SALFA28B17H007407
Kilometerstand	196 290 km

Kjøretøyinformasjon

Parameter	Verdi
Merke	LAND ROVER
Modell	FREELANDER 2
Reg.nr	KB 35350
VIN	SALFA28B17H007407
Motor	224DT — 2179cc Diesel 118.0 kW (160 hk)
Girkasse	Manuell
Euroklasse	Euro 4
Partikkelfilter (DPF)	Nei
Kilometerstand	196 290 km

Munin Overvåking

Overvåket siden	2026-03-13
-----------------	------------

On these few drives the engine presents as a healthy, high-mileage 2.2 diesel: it starts cleanly, warms up at a normal rate, builds and holds fuel rail pressure properly, and shows no stored or pending fault codes. The two things worth a closer look are a coolant temperature that settles a touch cool and an EGR valve that is commanded hard with loose tracking — both consistent with this engine's well-known EGR/cooler weak spot rather than anything alarming. For a car at ~196,000 km this is a reassuring first impression of the powertrain, with the EGR/cooling circuit the area to verify before buying.

2007 Land Rover Freelander 2, 2.2 diesel (224DT / TD4) — Vurdert 2026-06-28

Hva er vurdert

This reads only engine and drivetrain signals the ECU reports over OBD (fuelling, rail pressure, airflow/boost, EGR, temperatures, voltages); it says nothing about the body, suspension, brakes, chassis, gearbox internals, Haldex/AWD, DPF condition or anything the engine does not report.

Turer analysert: 3

Ser bra ut

- Cold start and idle: cranks and settles to a steady ~750 rpm idle with stable fuelling and no rough-running signature.
- Fuel system: common-rail pressure idles around 250 bar and climbs cleanly to ~1630 bar under hard load — well within normal range for this engine, with no pressure collapse or hunting.
- Warm-up behaviour: coolant climbs from 16°C to ~77°C at about 11°C/min and reaches normal operating temperature — no sign of a stuck-open thermostat preventing warm-up.
- Charging/electrical: control voltage holds a steady 13.8–14.2 V throughout, indicating a healthy alternator and battery under load.
- Fault status: no active, pending or stored diagnostic codes and zero distance with the MIL on — the ECU is not flagging anything.

Verdt et nærmere blikk

Coolant settles slightly cool of expected [WATCH]

Once warm, coolant stabilises around 74–78°C, roughly 5–10% below the ~82°C this engine's thermostat should hold. It warms up normally and reaches temperature, so this is a mild offset rather than a failure, but a persistently cool engine points at a lazy or partially-open thermostat.

Sjekk: Confirm steady-state coolant temperature on a longer run and check for a worn thermostat; also inspect for any coolant loss given this engine's known EGR-cooler weakness.

EGR commanded hard with loose tracking [INSPECT]

The EGR valve is commanded aggressively and its tracking error swings widely (offsets reaching roughly -14 to +18 percentage points with large variability) instead of settling tightly on target. On this 224DT that pattern typically reflects a sooted/sticking EGR valve or a tired EGR cooler — a documented weak point on this engine.

Sjekk: Have the EGR valve and cooler inspected/cleaned and check coolant for contamination, as a failing EGR cooler on this engine leaks coolant internally.

Boost and airflow wander at low rpm / light load and through transitions [WATCH]

Boost (MAP) and MAF show short transient excursions at low rpm under light load and during load changes, larger than the steady-state scatter elsewhere. Values recover and sit within normal range, so this reads as turbo/EGR transient hunting rather than a hard boost fault.

Sjekk: Drive under steady boost and inspect the turbo-to-intercooler hoses for splits — a common cause of intermittent boost loss and limp mode on this model.

Kjente svakheter for modellen

- EGR valve/cooler is the headline weak point on the 2.2 (224DT) — the cooler can crack and leak coolant internally, often first seen as a 'low coolant' message. The drive data's hard EGR commanding, loose EGR tracking and slightly-cool coolant all sit in this same area and warrant a direct EGR/cooler inspection and coolant check.
- Turbo-to-intercooler boost hose splits are commonly reported and cause sudden power loss / limp mode. The mild low-load boost wander seen here is not proof of this but makes a physical hose inspection worthwhile.
- DPF clogging affects town-only / short-trip cars; the OBD data here does not directly report DPF soot load, so verify DPF condition and service history separately.
- Haldex coupling and power-steering high-pressure hose leaks are documented but sit entirely outside what the OBD engine data can see — check physically.

Datagrunnlag

Three drives totalling roughly 12 minutes including a full cold-to-warm cycle and a hard variable-load pull give a solid first look at fuelling, boost and warm-up, but with no learned baseline for this specific car the assessment leans on general diesel norms and this engine's documented behaviour.