

FusionSolar Troubleshooting Report

Date: 20-04-2026
Generated At: 20-04-2026 09:47:03
Prepared By: TERA SPMS

Executive Summary

Metric	Value
Total plant analysed	31
Total low-performing plants	31
Total alarms	28
Total high-temperature inverters	61

Low-performing Plants

Plant Name	Plant PSH	City Average PSH	Deviation
ASHITA COMMUNICATION	0.00	3.46	-100.00
BIMB Bdr Penawar - 1st Floor	0.00	1.97	-100.00
BJC FOOD (MALAYSIA) SDN. BHD.	3.00	3.58	-16.24
CHYE JOO HIANG SDN. BHD. (Meter 1)	0.41	2.75	-85.07
DSG Malaysia Sdn. Bhd	2.66	3.66	-27.39
FOX ONE MARKETING SDN BHD	3.84	4.31	-10.96
IOI Mall Puchong (New Wing) Phase 2	2.90	3.77	-23.04
IOI Mayang Development	3.14	4.13	-23.89
Jaya Nets	3.09	3.79	-18.40
KISWIRE CORD PHASE 1 (DATA)	0.00	2.50	-100.00
Kwang Hua Persendirian meter 2-3-4-5-6	2.79	3.46	-19.38
LKW FROZEN SDN BHD	3.68	4.13	-10.80

Plant Name	Plant PSH	City Average PSH	Deviation
Lau and Tan Pharmacy (1st Floor)	0.71	1.68	-57.61
Lian Teck Seng Lot 11	0.00	3.46	-100.00
MARINE GOLD SDN BHD	0.00	2.42	-100.00
MENARA PKNS PJ	0.00	2.13	-100.00
PKT 12 WAVES	3.04	3.81	-20.28
Pleasure Latex Phase 2	0.00	1.96	-100.00
QL TAWAU FEEDMILL	1.38	2.54	-45.78
REDANG LAGOON RESORT	0.00	2.72	-100.00
SABAH CHINESE HIGH SCHOOL (CANTEEN)	1.97	2.54	-22.59
SABAH CHINESE HIGH SCHOOL (CULTURE AND EDUCATION)	1.88	2.54	-26.13
SUPERMICRO COMPUTER SDN BHD	1.85	2.27	-18.32
San Soon Seng Food Industries Sdn Bhd	3.08	3.58	-14.00
TIMURIKAN TRENGGANU MARINE PRODUCTS SDN BHD	0.67	1.86	-64.08
Teong Huat Medical	4.05	4.54	-10.79
Toa Paint Kepong Warehouse	0.00	1.86	-100.00
UC BLASTING PAINTING	0.00	3.46	-100.00
UCS_Block A	3.55	4.13	-13.95
VISKO INDUSTRIES SDN BHD	2.65	3.46	-23.42
WEIDA MARKETING SDN. BHD.	4.03	4.85	-16.91

Active Alarms

Plant Name	Device Name	Device SN	Alarm Name	Severity	Occurrence Time
BIMB Bdr Penawar - 1st Floor	Dongle- INV1	BT24C0060244	Network Connection Error	Major	15-04-2026 18:07
C0102_QL batang kali	102140076076	102140076076	Network Connection Error	Major	31-03-2026 13:53

Plant Name	Device Name	Device SN	Alarm Name	Severity	Occurrence Time
CHYE JOO HIANG SDN. BHD. (Meter 1)	INV-TA2470005979	TA2470005979	Abnormal Residual Current	Major	17-04-2026 17:27
FUJI M3	Inverter(COM2-12)	ES2480078272	Upgrade Failed or Version Mismatch	Minor	14-04-2026 21:25
Fibertex Phase 2	Inverter 2 L3 Old	6T2379019735	Upgrade Failed or Version Mismatch	Minor	18-07-2025 15:24
IOI Mall Puchong (New Wing) Phase 2	Inverter 4	GR2569071069	Grid Loss	Major	16-04-2026 09:37
Lian Teck Seng Lot 11	Dongle-BT24C0060275	BT24C0060275	Network Connection Error	Major	29-01-2026 15:54
MARINE GOLD SDN BHD	Dongle-TA2340293153	TA2340293153	Network Connection Error	Major	26-03-2026 15:55
MARINE GOLD SDN BHD	Dongle-TA2340293476	TA2340293476	Network Connection Error	Major	26-03-2026 15:55
MARINE GOLD SDN BHD	Dongle-TA2340291437	TA2340291437	Network Connection Error	Major	26-03-2026 15:55
MARINE GOLD SDN BHD	Dongle-HV2310776105	HV2310776105	Network Connection Error	Major	26-03-2026 14:56
MARINE GOLD SDN BHD	Dongle-HV2310776109	HV2310776109	Network Connection Error	Major	26-03-2026 14:55
MARINE GOLD SDN BHD	Dongle-HV2310773587	HV2310773587	Network Connection Error	Major	26-03-2026 14:54
MENARA PKNS PJ	Logger-102466288020	102466288020	Network Connection Error	Major	11-04-2026 01:01
Pleasure Latex Phase 2	Logger-102347282208	102347282208	Network Connection Error	Major	19-02-2026 03:00
REDANG LAGOON RESORT	Dongle-2102312EHS10N9115979	2102312EHS10N9115979	Network Connection Error	Major	30-01-2026 19:29
REDANG LAGOON RESORT	INV-ES22A0089681	ES22A0089681	Grid Loss	Major	30-01-2026 07:23
SIME KANSAI PAINT SDN BHD	INV-ES2550146111	ES2550146111	Upgrade Failed or Version Mismatch	Minor	19-11-2025 21:35
THP MEDICAL	VASOLAR INV 3	6T2279009018	Upgrade Failed or Version Mismatch	Minor	15-02-2026 20:22
THP MEDICAL	VASOLAR INV 2	6T2279008977	Upgrade Failed or Version Mismatch	Minor	15-02-2026 20:22
THP MEDICAL	VASOLAR INV 1	6T2279009011	Upgrade Failed or Version Mismatch	Minor	15-02-2026 20:22
Toa Paint Kepong Warehouse	Dongle-TA2340293160	TA2340293160	Network Connection Error	Major	15-04-2026 08:02
UC BLASTING PAINTING	Dongle-HV2310775381	HV2310775381	Network Connection Error	Major	16-04-2026 20:26
WASCO PIPE SDN BHD (COATING)	Logger-102516002786	102516002786	Network Connection Error	Major	14-04-2026 16:31
WASCO PIPE SDN BHD (MILL)	Inverter 4	GR2459039441	Grid Loss	Major	19-03-2026 12:46

Plant Name	Device Name	Device SN	Alarm Name	Severity	Occurrence Time
WASCO PIPE SDN BHD (MILL)	Inverter 1	GR2569103020	Grid Loss	Major	19-03-2026 12:45
WASCO PIPE SDN BHD (MILL)	Inverter 2	GR2569101664	Grid Loss	Major	19-03-2026 12:45
WASCO PIPE SDN BHD (MILL)	Inverter 3	GR2569101626	Grid Loss	Major	19-03-2026 12:44

High-temperature Inverters

Plant Name	Inverter Name	Inverter SN	Temperature
ASIA WIRE STEEL MESH MANUFACTURERS SDN BHD	Inverter(COM3-15)	ES2550064258	71.0
ATS AIR SOLUTION	INV-HV22A0242778	HV22A0242778	73.1
BJC FOOD (MALAYSIA) SDN. BHD.	60KTL-M0(COM1-3)	ES2180084797	71.7
BOILERMECH LOT 873	TERA INV 2	ES2550000079	72.1
BP PLASTICS HQ	Inverter_11	6T2499023013	77.7
BP PLASTICS HQ	Inverter_2	ES2440060550	82.0
BP PLASTICS HQ	Inverter_3	6T2489015626	75.9
BP PLASTICS HQ	Inverter_4	ES2460076787	70.7
BP PLASTICS HQ	Inverter_5	ES2460076788	71.0
BP PLASTICS HQ	Inverter_6	6T2499021622	82.7
BP PLASTICS HQ	Inverter_8	6T2499021624	77.0
BRC INDUSTRIES	VASOLAR INV 2	ES2410011610	70.0
BUNCHO (M) SDN BHD	INV-6T2519005159	6T2519005159	72.0
C0172_ATRIA SOUTH	Inverter 4(COM2-1)	HV22A0105615	74.6
CHAN KAH WHYE	INV-NS249G082061	NS249G082061	80.9
CIC CONTRACT SDN BHD	INV-HV22A0242777	HV22A0242777	75.4
Dong Sing Food Link Sdn Bhd	Inverter(COM2-1)	ES2570023845	72.6
Durasafe Sdn. Bhd.	INV 1-6T2479002464	6T2479002464	79.7

Plant Name	Inverter Name	Inverter SN	Temperature
Durasafe Sdn. Bhd.	INV 2-6T2469038783	6T2469038783	73.9
FURUTEC	VASOLAR INV 1	BN2441064527	70.4
Fibertex Phase 2	Inv. CarPark Roof A	ES2420001055	75.3
Fibertex Phase 2	Inverter 1 L3	6T23A9016283	74.5
Fibertex Phase 2	Inverter 4 L3	6T2379019613	70.9
Fibertex Phase 2	Inverter 8 L3	6T2379019736	70.7
Fibertex Phase 2	Inverter 9 L3	6T2379019637	71.7
Fibertex Phase 2	Roof 2C Bridge R1	6T2469046697	75.4
Fungiculture	Inverter 1 (M1)	ES22B0022924	70.1
Fungiculture	Inverter 1 (M3)	ES22B0022997	70.4
Fungiculture	Inverter 1 (M4)	ES22B0007042	82.4
Fungiculture	Inverter 2 (M3)	HV22B0337400	81.2
Fungiculture	Inverter 2 (M4)	HV22B0004571	76.1
Fungiculture	Inveter 2 (M1)	HV22B0337398	82.7
GLASS PLASTIC PACKAGING	INV 2 - (No.23)	6T2489010546	82.2
GLASS PLASTIC PACKAGING	INV 3 - (Lot 65999)	6T2489010635	79.1
GLASS PLASTIC PACKAGING	INV 4 - (Lot 65999)	6T2489010593	78.2
Hoon Yuen Furniture	Inverter 1	ES22B0024091	73.1
IOI Mall Puchong (New Wing)	Inverter 16 - TERA	6T2449030262	72.8
Jiann Lih safety product	40KTL-M3(COM1-15)	ES2290059762	87.3
Jiann Lih safety product	40KTL-M3(COM1-16)	ES2290059727	89.0
Kamma Klang Enterprise	Inverter 1	ES22A0088766	72.9
Kamma Klang Enterprise	Inverter 2	HV22A0153968	73.9
Komplex PKNS Bangi	40KTL-M3(COM1-13)	ES22A0040484	74.7

Plant Name	Inverter Name	Inverter SN	Temperature
Kwang Hua Persendirian meter 2-3-4-5-6	Block B2-Inverter 6 - Meter 6	6T21C9025214	70.9
LAM SOON EDIBLE OILS	INV-2	6T2449022953	72.3
Maxtwo Engineering (Factory)	INV-6T24A9018040	6T24A9018040	76.1
Mitsui Copper Foil P3	Inverter 3 (AREA A)	6T24A9009773	76.0
Mitsui Copper Foil P3	Inverter 4 (AREA A)	6T24A9013004	76.9
Multi Choice (M) Sdn Bhd	TERA INV 3	ES2560208616	72.2
P.A Food Sdn Bhd 2ATKT	INV-ES2420001275	ES2420001275	74.0
P.A Food Sdn Bhd Lot 10	INV-6T2449029469	6T2449029469	78.0
P.A Food Sdn Bhd Lot 12	INV-6T2449029471	6T2449029471	81.8
P.A. Food Warehouse No. 9	INV-HV2290797189	HV2290797189	71.1
PKT THE SHIP	Inverter_8 R1	ES24C0173071	70.6
QL PAJAM PHASE 2	INV 5	6T2559006722	73.5
RS POLY INDUSTRY	VASOLAR INV 1	ES2420000999	78.4
RS POLY INDUSTRY	VASOLAR INV 2	ES2420001084	71.6
SJK (C) WU TECK	INV 1	6T25B9000135	73.4
SP Logistics Sdn Bhd	INV-6T23B9005457	6T23B9005457	70.5
SWEE CHEONG WATCH SDN BHD (Meter 1)	INV-TA2470383341	TA2470383341	70.9
SWEE CHEONG WATCH SDN BHD (Meter 2)	INV-TA2470383489	TA2470383489	71.7
VISKO INDUSTRIES SDN BHD	VASOLAR_INV_8	ES2180084993	71.3