
5. Avoiding inconstant collapse

Metal buildings designed as per applicable codes may not have rapid response to inconsistent collapse if the following conditions are met:

- Horizontal ties in general shall be placed in a way that achieves continuity, durability and stability as much as possible, and be placed in each floor and roof in perpendicular directions.
- The load shall be transferred to the columns through connections between bridge/beam and column unless the steel structure is totally continuous in at least one direction. All column overlaps shall be able to resist This is a system to resist horizontal force reaction from applicable and dead load, or dead lead forces; it may have a shorter name oads, loaded on the column on a single floor level between the column below it.
- [Ties and other systems resisting horizontal forces] shall be distributed as recommend
 in the applicable code in perpendicular directions; it is not permissible to for any part of
 the building to connect with the [horizontal forces resistance system] in one point only.
- In case of precast concrete or other heavy systems, they shall be firmly tied on their levels by tying them together at the support or directly to the supports as recommended by the applicable code.



 In case the above conditions are not met each floor shall be inspected -each one at a time- to ensure that inconsistent collapses will not occur due to a presumed demolition/ dismantle. Each member of the horizontal resistance system and part prone to collapse