Chronometer/chronoCircuit/struct

### Package List

LIBRARY ieee;
USE ieee.std\_logic\_1164.all;
USE ieee.numeric\_std.all;
LIBRARY gates;
USE gates.gates.all;

## **Buttons**



## 12 o'clock Sensor



# Clock & Reset



## Testmode only for simulation




### **Declarations**

### Ports:

clock : std\_ulogic
reset : std\_ulogic
restart : std\_uLogic
sensor : std\_uLogic
start : std\_uLogic
stop : std\_uLogic
testMode : std\_uLogic
coil1 : std\_uLogic
coil2 : std\_uLogic
coil3 : std\_uLogic
coil4 : std\_uLogic
testOut : std\_uLogic

**Diagram Signals:** 

# **Stepper Motor Coils**



# Debug Signal (Leds)



Printed by uadmin on 04.11.2013 at 10:48:10