PRODUCTION SUPPLY

	SOP 903068	PG 8	DESCRIPTION Status Check at NOF	ACTION PP, St Chk at NOF, Scan HU Lv1, Chk PO is correct, OK, Scan all HU Lv1, Check = Success, Proceed, OK
	903068	10	Move from NOF to Line	PP, Move Pallet, Scan HU, Scan Line - then just scan each Hu and the line for subsequent pallets
- (a)	903068	13	Move Whole Pallet of Shippers to line	PP, Hsk, Cr & Con HU Task; Scan HJ Lv1, 9999, OK, Enter Line, OK, Scan Line again, OK
	903 0 68	17	To Split a Pallet of Shippers	PP, Housek, Repack Product , Scan HU Lv1, Enter Qty, OK, Enter Line, Scroll HU Create, Pickcontainer, OK, OK, OK, Label is now printed
	903068	20	Move a single Coldform to line	PP, Hsk, Cr & Con HU Task, <u>Scan HIJ Lv2</u> , 9999, OK, Enter Line, OK, Enter Line again
		20	Move Last Coldform	To Move the LAST Coldform - as above, however, <u>Scan the Level 1</u> not the Level 2
d	CHECK MA	TERIA	LS FOR THE ORDER	/n/scwm/pmr - Manufacturing (rder = enter order No Click on jigsaw - Warehouse Task
	VIEW MAT	ERIAL	S YET TO CONSUME	/n/scwm/mon - Stock & Bin - S orage Bin - Physical Stock - Storage Bin = A1
	TO RE-PRINT A HU LABEL		IU LABEL	SAP - WHS Label Printer - Reprint HU Label - MAC1 - double click HU Number - Print HU
	LOG ONTO PAS-X ON ANOTHER LINE		ON ANOTHER LINE	Click on internet Explorer - http://yourapps.emea.astrazeneca.net
	CHANGE YOUR PRINTER ON EWM		RINTER ON EWM	Log onto EW3 - systems - user profile - own data, defaults, output, Enter Printer No. E.g. PA1
	CHECK OR	DER ST	FATUS IN EWM	ZMR271061 - mac1 - v0005 - Select Line A1 - Execute Allow Continue