10/12/20 - Return Delayed Ferry Must Return to Shipyard - Engines Overheating

10/12/20 - Return Delayed

Ferry Must Return to Shipyard - Engines Overheating

The ferry had been on its way but the engines began over-heating and they have had turn to turn back.

A specialist is confirmed to address the problem with the engines tomorrow morning. The engine supplier is on the same waterway as Stabbert Maritime and should be able to repair at the dock.

More information will be shared as we become aware.