Valeo	PART NAME : Overmolded body	marca 04, 2021	10:53
	DRAWING REV: F	DRAWING No: V29123229_001	STATS COUNT : 1
	MEASUREMENT MADE BY : PAM_Jakubiec S.	COMMENT :	

```
Current Temperatures: X=20.854 Y=20.657 Z=21.032 P=20.524
Temperature Compensation is ON

#### SHEET 1/2
### Left view
## <T-C6>
DIM POS3= POSITION OF PLANE PLN_H3  UNITS=MM
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
Z      30.380                                      30.134     -0.246
TP        RFS      0.500                 0.000      0.492      0.492      0.000 --------#

## <T-C15> (x2)
DIM POS1= POSITION OF PLANE PLN_S1  UNITS=MM
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
Z     -17.720                                     -17.815     -0.095
TP        RFS      0.500                 0.000      0.191      0.191      0.000 ---#-----

DIM POS2= POSITION OF PLANE PLN_S2  UNITS=MM
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
Z     -17.720                                     -17.593      0.127
TP        RFS      0.500                 0.000      0.254      0.254      0.000 ----#----

## <T-C12>
DIM PLAN1= FLATNESS OF PLANE PLN_N  UNITS=MM
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
M        0.000      0.200      0.000      0.087      0.087      0.000 ---#-----

## <T-C13>
DIM POS4= POSITION OF PLANE PLN_N  UNITS=MM
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
Y       3.620                                       3.526     -0.094
TP        RFS      0.400                 0.000      0.188      0.188      0.000 ----#----


### Section view A-A
## <A-C5> (x3)
DIM POS18= LOCATION OF CIRCLE CIR_D48.8_GX_1  UNITS=MM
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
D       48.800      0.100     -0.100     48.888      0.088      0.000 --------#

DIM POS5= LOCATION OF CIRCLE CIR_D48.8_GX_2_F  UNITS=MM
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
D       48.800      0.100     -0.100     48.903      0.103      0.003 -------->

DIM POS19= LOCATION OF CIRCLE CIR_D48.8_GX_3  UNITS=MM
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
D       48.800      0.100     -0.100     48.907      0.107      0.007 -------->

## <A-F10>
DIM POS22= POSITION OF CIRCLE CIR_D48.8_GX_2_F  UNITS=MM
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
Z     -34.300                                     -34.327     -0.027
TP        RFS      0.200                 0.000      0.055      0.055      0.000 --#------

## <A-F11>
DIM PERP1= PERPENDICULARITY OF CYLINDER CYL_D48.8_F,RFS TO LINE LIN_B,RFS EXTENDLENGTH=0.000  UNITS=MM
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
M        0.000      0.100      0.000      0.030      0.030      0.000 --#------
```

```
## <A-F12>
DIM POS94= POSITION OF CIRCLE CIR_D48.8_GX_2_F  UNITS=MM
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
X       0.000                                       0.028      0.028
TP        RFS      0.200                 0.000      0.056      0.056      0.000 --#------

## <A-C3>
DIM POS6= LOCATION OF CYLINDER CYL_D55  UNITS=MM
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
D       55.000      0.200     -0.200     54.879     -0.122      0.000 -#-------

## <A-C13>
DIM CILTÁ1= CYLINDRICITY OF CYLINDER CYL_D55  UNITS=MM
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
M        0.000      0.400      0.000      0.188      0.188      0.000 ----#----

## <A-C14>
DIM POS95= POSITION OF CYLINDER CYL_D55  USE AXIS=AVERAGE  REF LENGTH=0.000  UNITS=MM
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
X       0.000                                       0.042      0.042
Z     -52.620                                     -52.740     -0.120
TP        RFS      0.500                 0.000      0.253      0.253      0.000 ----#----

## <A-F18>
DIM POS7= LOCATION OF CIRCLE CIR_D26  UNITS=MM
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
D       26.000      0.100     -0.100     26.118      0.118      0.018 -------->

## <A-F19>
DIM CONCEN1= CONCENTRICITY FROM CIRCLE CIR_D26 TO LINE LIN_B  UNITS=MM
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
M        0.000      0.100      0.000      0.135      0.135      0.035 -------->

## <A-C20>
DIM POS72= POSITION OF CIRCLE CIR_D48.8_GX_2_F  UNITS=MM
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
X      53.180                                      53.365      0.185
Y     -27.780                                     -27.796     -0.016
TP        RFS      2.000                 0.000      0.372      0.372      0.000 -#-------

## <A-C21>
DIM POS172= POSITION OF CYLINDER CYL_D55  USE AXIS=AVERAGE  REF LENGTH=0.000  UNITS=MM
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
X      53.180                                      53.402      0.222
Y     -27.780                                     -27.629      0.151
TP        RFS      2.000                 0.000      0.537      0.537      0.000 --#------


### Section view B-B
## <B-C4>
DIM POS8= POSITION OF PLANE PLN_N1'  UNITS=MM
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
Z     -10.000                                      -9.994      0.006
TP        RFS      2.000                 0.000      0.012      0.012      0.000 #--------

## <B-F2>
DIM PERP2= PERPENDICULARITY OF CYLINDER CYL_M6-6H_Q,RFS TO PLANE PLN_N,RFS EXTENDLENGTH=0.000  UNITS=MM
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
M        0.000      0.200      0.000      0.134      0.134      0.000 ------#--

## <B-C3>
DIM POS9= POSITION OF CIRCLE M6-6H_Q  UNITS=MM
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
PR      60.000                                      60.196      0.196
PA      80.000                                      80.135      0.135
TP        RFS      0.600                 0.000      0.483      0.483      0.000 -------#-
```

```
### Section view C-C
## <C-C3> (x2)
# H2
DIM POS12= POSITION OF PLANE PLN_H2  UNITS=MM
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
Z     -20.320                                     -19.916      0.404
TP        RFS      0.500                 0.000      0.809      0.809      0.309 -------->

# H5
DIM POS11= POSITION OF PLANE PLN_H5  UNITS=MM
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
Z     -20.320                                     -19.916      0.404
TP        RFS      0.500                 0.000      0.808      0.808      0.308 -------->

## <C-F1> (x2)
# H2 - cylinder
DIM POS10= LOCATION OF CYLINDER CYL_D9.15_H2  UNITS=MM
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
D        9.150      0.050     -0.050      9.176      0.026      0.000 ------#--

## 1.5 mm from plane S
DIM POS99= LOCATION OF CIRCLE CIR_D9.15_H2_1.5  UNITS=MM
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
D        9.150      0.050     -0.050      9.108     -0.042      0.000 #--------

## 10 mm from plane S
DIM POS100= LOCATION OF CIRCLE CIR_D9.15_H2_10  UNITS=MM
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
D        9.150      0.050     -0.050      9.161      0.011      0.000 -----#---

## 18.5 mm from plane S
DIM POS101= LOCATION OF CIRCLE CIR_D9.15_H2_18.5  UNITS=MM
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
D        9.150      0.050     -0.050      9.254      0.104      0.054 -------->

# H5 - cylinder
DIM POS13= LOCATION OF CYLINDER CYL_D9.15_H5  UNITS=MM
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
D        9.150      0.050     -0.050      9.183      0.033      0.000 -------#-

## 1.5 mm from plane S
DIM POS102= LOCATION OF CIRCLE CIR_D9.15_H5_1.5  UNITS=MM
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
D        9.150      0.050     -0.050      9.110     -0.040      0.000 #--------

## 10 mm from plane S
DIM POS103= LOCATION OF CIRCLE CIR_D9.15_H5_10  UNITS=MM
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
D        9.150      0.000     -0.050      9.181      0.031      0.031 -------->

## 18.5 mm from plane S
DIM POS104= LOCATION OF CIRCLE CIR_D9.15_H5_18.5  UNITS=MM
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
D        9.150      0.000     -0.050      9.250      0.100      0.100 -------->

## <C-C2> (x2)
# H2
DIM POS14= POSITION OF CYLINDER CYL_D9.15_H2  USE AXIS=AVERAGE  REF LENGTH=0.000  UNITS=MM
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
X      80.580                                      80.946      0.366
Y     -59.620                                     -59.728     -0.108
TP        RFS      0.400                 0.000      0.763      0.763      0.363 -------->

# H5
DIM POS15= POSITION OF CYLINDER CYL_D9.15_H5  USE AXIS=AVERAGE  REF LENGTH=0.000  UNITS=MM
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
X      28.660                                      28.801      0.141
Y       6.320                                       6.422      0.102
TP        RFS      0.400                 0.000      0.348      0.348      0.000 -------#-
```

```
### Section view J-J
## <J-F2> - cylinder
DIM POS16= LOCATION OF CYLINDER CYL_D8.19_H3  UNITS=MM
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
D        8.160      0.040     -0.040      8.359      0.199      0.159 -------->

## <J-F2> (x3)
## 1.5 mm
DIM POS96= LOCATION OF CIRCLE CIR_D8.19_1  UNITS=MM
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
D        8.160      0.040     -0.040      8.287      0.127      0.087 -------->

## 6 mm
DIM POS97= LOCATION OF CIRCLE CIR_D8.19_2  UNITS=MM
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
D        8.160      0.040     -0.040      8.285      0.125      0.085 -------->

## 12 mm
DIM POS98= LOCATION OF CIRCLE CIR_D8.19_3  UNITS=MM
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
D        8.160      0.040     -0.040      8.276      0.116      0.076 -------->

## <J-C3>
DIM POS17= POSITION OF CYLINDER CYL_D8.19_H3  USE AXIS=AVERAGE  REF LENGTH=0.000  UNITS=MM
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
X      24.760                                      24.913      0.153
Y     -58.710                                     -58.974     -0.264
TP        RFS      0.400                 0.000      0.610      0.610      0.210 -------->

## <J-F5>
DIM POS171= LOCATION OF CIRCLE CIR_D9.7  UNITS=MM
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
D        9.700      0.150     -0.150      9.840      0.140      0.000 --------#


### Section view AE-AE
## <AE-C4>
DIM POS20= POSITION OF PLANE PLN_N2'  UNITS=MM
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
Z     -10.000                                      -9.989      0.011
TP        RFS      0.500                 0.000      0.022      0.022      0.000 #--------

## <AE-C2>
DIM POS21= POSITION OF CYLINDER CYL_M6-6H_R  USE AXIS=AVERAGE  REF LENGTH=0.000  UNITS=MM
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
X      84.680                                      84.794      0.114
TP        RFS      1.000                 0.000      0.229      0.229      0.000 --#------
```

```
#### SHEET 2/2
### Detail F
## <F-V1>  (GG) x3
DIM POS23= LOCATION OF CIRCLE CIR_D12.03_3  UNITS=MM
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
D       12.030      0.042     -0.042     12.130      0.100      0.058 -------->

DIM POS105= LOCATION OF CIRCLE CIR_D12.03_2  UNITS=MM
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
D       12.030      0.042     -0.042     12.141      0.111      0.069 -------->

DIM POS106= LOCATION OF CIRCLE CIR_D12.03_1  UNITS=MM
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
D       12.030      0.042     -0.042     12.180      0.150      0.108 -------->

## <F-V8>
DIM CONCEN2= CONCENTRICITY FROM CIRCLE CIR_D12.03_3 TO LINE LIN_B  UNITS=MM
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
M        0.000      0.050      0.000      0.140      0.140      0.090 -------->

## <F-F7> (x2)
DIM POS24= LOCATION OF CIRCLE CIR_D8.5_3  UNITS=MM
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
D        8.500      0.100     -0.100      8.629      0.129      0.029 -------->

DIM POS25= LOCATION OF CIRCLE CIR_D8.5_4  UNITS=MM
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
D        8.500      0.100     -0.100      8.623      0.123      0.023 -------->

## <F-F12>(x2)
DIM CONCEN3= CONCENTRICITY FROM CIRCLE CIR_D8.5_3 TO LINE LIN_B  UNITS=MM
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
M        0.000      0.100      0.000      0.180      0.180      0.080 -------->

DIM CONCEN4= CONCENTRICITY FROM CIRCLE CIR_D8.5_4 TO LINE LIN_CZ_B  UNITS=MM
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
M        0.000      0.100      0.000      0.156      0.156      0.056 -------->

## <F-F9>
DIM POS107= POSITION OF POINT PNT_7.2  UNITS=MM
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
Z      -7.200                                     -7.151      0.049
TP        RFS      0.300                  0.000      0.098      0.098      0.000 --#------

## <F-F13>
DIM POS108= LOCATION OF CIRCLE CIR_D18.1  UNITS=MM
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
D       18.100      0.150     -0.150     18.105      0.005      0.000 ----#----

## <F-F14>
DIM CONCEN15= CONCENTRICITY FROM CIRCLE CIR_D18.1 TO LINE LIN_B  UNITS=MM
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
M        0.000      0.200      0.000      0.042      0.042      0.000 -#-------

## <F-F11>
DIM POS109= POSITION OF PLANE PLN_16.7  UNITS=MM
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
Z     -16.700                                    -16.710     -0.010
TP        RFS      0.100                  0.000      0.020      0.020      0.000 -#-------


### Detail Q
## <Q-F2>
DIM POS26= LOCATION OF CIRCLE CIR_D14.2  UNITS=MM
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
D       14.200      0.100     -0.100     14.372      0.172      0.072 -------->
```

Section view D-D

<D-F7> (x6)

DIM PLAN2= FLATNESS OF PLANE PLN_A1 UNITS=MM

AX	NOMINAL	+TOL	-TOL	MEAS	DEV	OUTTOL	
M	0.000	0.200	0.000	0.029	0.029	0.000	-#-------

DIM PLAN3= FLATNESS OF PLANE PLN_A2 UNITS=MM

AX	NOMINAL	+TOL	-TOL	MEAS	DEV	OUTTOL	
M	0.000	0.200	0.000	0.047	0.047	0.000	--#------

DIM PLAN4= FLATNESS OF PLANE PLN_A3 UNITS=MM

AX	NOMINAL	+TOL	-TOL	MEAS	DEV	OUTTOL	
M	0.000	0.200	0.000	0.044	0.044	0.000	-#-------

DIM PLAN5= FLATNESS OF PLANE PLN_A4 UNITS=MM

AX	NOMINAL	+TOL	-TOL	MEAS	DEV	OUTTOL	
M	0.000	0.200	0.000	0.012	0.012	0.000	#--------

DIM PLAN6= FLATNESS OF PLANE PLN_A5 UNITS=MM

AX	NOMINAL	+TOL	-TOL	MEAS	DEV	OUTTOL	
M	0.000	0.200	0.000	0.060	0.060	0.000	--#------

DIM PLAN7= FLATNESS OF PLANE PLN_A6 UNITS=MM

AX	NOMINAL	+TOL	-TOL	MEAS	DEV	OUTTOL	
M	0.000	0.200	0.000	0.050	0.050	0.000	--#------

<D-F8>

DIM PLAN8= FLATNESS OF PLANE PLN_A UNITS=MM

AX	NOMINAL	+TOL	-TOL	MEAS	DEV	OUTTOL	
M	0.000	0.350	0.000	0.386	0.386	0.036	-------->

<D-V1> (x3)

DIM POS27= LOCATION OF CIRCLE CIR_D13.945_1 UNITS=MM

AX	NOMINAL	+TOL	-TOL	MEAS	DEV	OUTTOL	
D	13.945	0.042	-0.042	14.118	0.173	0.131	-------->

DIM POS28= LOCATION OF CIRCLE CIR_D13.945_2 UNITS=MM

AX	NOMINAL	+TOL	-TOL	MEAS	DEV	OUTTOL	
D	13.945	0.042	-0.042	14.094	0.149	0.107	-------->

DIM POS29= LOCATION OF CIRCLE CIR_D13.945_3 UNITS=MM

AX	NOMINAL	+TOL	-TOL	MEAS	DEV	OUTTOL	
D	13.945	0.042	-0.042	14.056	0.111	0.069	-------->

<D-F10>

DIM CILTÁ2= CYLINDRICITY OF CYLINDER CYL_D13.945 UNITS=MM

AX	NOMINAL	+TOL	-TOL	MEAS	DEV	OUTTOL	
M	0.000	0.050	0.000	0.107	0.107	0.057	-------->

<D-F5>

DIM PERP4= PERPENDICULARITY OF LINE LIN_CZ_B,RFS TO PLANE PLN_A,RFS EXTENDLENGTH=0.000 UNITS=MM

AX	NOMINAL	+TOL	-TOL	MEAS	DEV	OUTTOL	
M	0.000	0.300	0.000	0.347	0.347	0.047	-------->

<D-V6>

DIM RETTIL1= STRAIGHTNESS OF LINE LIN_CZ_B UNITS=MM

AX	NOMINAL	+TOL	-TOL	MEAS	DEV	OUTTOL	
M	0.000	0.150	0.000	0.043	0.043	0.000	--#------

<D-V2> (x2)

DIM POS30= LOCATION OF CIRCLE CIR_D10.945_1 UNITS=MM

AX	NOMINAL	+TOL	-TOL	MEAS	DEV	OUTTOL	
D	10.945	0.042	-0.042	11.063	0.118	0.076	-------->

DIM POS31= LOCATION OF CIRCLE CIR_D10.945_2 UNITS=MM

AX	NOMINAL	+TOL	-TOL	MEAS	DEV	OUTTOL	
D	10.945	0.042	-0.042	11.060	0.115	0.073	-------->

```
## <D-F11>
DIM CILTÁ3= CYLINDRICITY OF CYLINDER CYL_D10.945  UNITS=MM
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
M       0.000      0.050      0.000      0.039      0.039      0.000 ------#--

## <D-F9>
DIM POS32= POSITION OF PLANE PLN_H  UNITS=MM
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
Z     -86.920                                    -87.020     -0.100
TP       RFS      0.260                 0.000      0.201      0.201      0.000 ------#--

## <D-F12>
DIM POS110= POSITION OF PLANE PLN_J  UNITS=MM
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
Z     -79.520                                    -79.523     -0.003
TP       RFS      0.300                 0.000      0.005      0.005      0.000 #--------


### Detail G
## <G-F3> (x2)
DIM POS33= LOCATION OF CIRCLE CIR_D8.2_1  UNITS=MM
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
D       8.500      0.100     -0.100      8.620      0.120      0.020 -------->

DIM POS34= LOCATION OF CIRCLE CIR_D8.2_2  UNITS=MM
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
D       8.500      0.100     -0.100      8.608      0.108      0.008 -------->

## <G-F15> (x2)
DIM CONCEN5= CONCENTRICITY FROM CIRCLE CIR_D8.2_1 TO LINE LIN_B  UNITS=MM
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
M       0.000      0.100      0.000      0.082      0.082      0.000 -------#-

DIM CONCEN6= CONCENTRICITY FROM CIRCLE CIR_D8.2_2 TO LINE LIN_B  UNITS=MM
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
M       0.000      0.100      0.000      0.126      0.126      0.026 -------->

## <G-V1> - cylinder (GG)
DIM POS35= LOCATION OF CYLINDER CYL_D21  UNITS=MM
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
D      21.000      0.050     -0.050     21.173      0.173      0.123 -------->

## <G-V1> (GG) x3
DIM POS111= LOCATION OF CIRCLE CIR_D21_1  UNITS=MM
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
D      21.000      0.050     -0.050     21.186      0.186      0.136 -------->

DIM POS112= LOCATION OF CIRCLE CIR_D21_2  UNITS=MM
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
D      21.000      0.050     -0.050     21.161      0.161      0.111 -------->

DIM POS113= LOCATION OF CIRCLE CIR_D21_3  UNITS=MM
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
D      21.000      0.050     -0.050     21.150      0.150      0.100 -------->

## <G-V12>
DIM CONCEN7= CONCENTRICITY FROM CYLINDER CYL_D21 TO LINE LIN_B  UNITS=MM
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
M       0.000      0.100      0.000      0.197      0.197      0.097 -------->

## <G-F13>
DIM CILTÁ4= CYLINDRICITY OF CYLINDER CYL_D21  UNITS=MM
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
M       0.000      0.050      0.000      0.114      0.114      0.064 -------->

## <G-F2>
DIM POS36= LOCATION OF CIRCLE CIR_15.2  UNITS=MM
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
D      15.500      0.100     -0.100     15.644      0.144      0.044 -------->
```

```
## <G-F14>
DIM CONCEN8= CONCENTRICITY FROM CIRCLE CIR_15.2 TO LINE LIN_B  UNITS=MM
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
M       0.000      0.100      0.000      0.022      0.022      0.000 -#-------

## <G-F16>
DIM POS37= POSITION OF PLANE PLN_M  UNITS=MM
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
Z       2.450                                     2.391     -0.059
TP        RFS      0.200                 0.000      0.117      0.117      0.000 -----#---

## <G-F17>
DIM POS38= POSITION OF PLANE PLN_7.5  UNITS=MM
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
Z       7.500                                     7.380     -0.120
TP        RFS      0.100                 0.000      0.239      0.239      0.139 -------->

## <G-F18>
DIM POS39= POSITION OF PLANE PLN_3.8  UNITS=MM
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
Z      -3.800                                    -3.752      0.048
TP        RFS      0.200                 0.000      0.096      0.096      0.000 ----#----


### Section view E-E
## <E-F8>
DIM POS40= POSITION OF CIRCLE CIR_D5_TMP  UNITS=MM
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
Z      -5.150                                    -5.071      0.079
TP        RFS      0.400                 0.000      0.158      0.158      0.000 ---#-----

## <E-F1> (x3)
DIM POS41= LOCATION OF CIRCLE CIR_D4.955_1  UNITS=MM
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
D       4.955      0.029     -0.029      5.054      0.099      0.070 -------->

DIM POS42= LOCATION OF CIRCLE CIR_D4.955_2  UNITS=MM
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
D       4.955      0.029     -0.029      5.065      0.110      0.081 -------->

DIM POS43= LOCATION OF CIRCLE CIR_D4.955_3  UNITS=MM
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
D       4.955      0.029     -0.029      5.056      0.101      0.072 -------->

## <E-F5>
DIM POS44= POSITION OF CIRCLE CIR_D4.955_2  UNITS=MM
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
X      32.050                                    32.141      0.091
TP        RFS      0.120                 0.000      0.182      0.182      0.062 -------->

## <E-F6>
DIM PERP5= PERPENDICULARITY OF LINE LIN_C,RFS TO PLANE PLN_K,RFS EXTENDLENGTH=0.000  UNITS=MM
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
M       0.000      0.200      0.000      0.075      0.075      0.000 ---#-----

## <E-F2>
DIM POS45= LOCATION OF CIRCLE CIR_D5.15  UNITS=MM
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
D       5.150      0.050     -0.050      5.242      0.092      0.042 -------->

## <E-F7>
DIM CONCEN9= CONCENTRICITY FROM CIRCLE CIR_D5.15 TO LINE LIN_C  UNITS=MM
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
M       0.000      0.100      0.000      0.036      0.036      0.000 ---#-----
```

```
### Section view N-N
## <N-F8>
DIM POS46= POSITION OF PLANE PLN_L  UNITS=MM
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
Z      -1.600                                      -1.655     -0.055
TP        RFS      0.300                 0.000      0.110      0.110      0.000 ---#-----

## S1 ##
## <N-V4> (x2)
DIM POS47= LOCATION OF CIRCLE CIR_D3.7_L1_1  UNITS=MM
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
D        3.200      0.050     -0.050      3.298      0.098      0.048 -------->

DIM POS48= LOCATION OF CIRCLE CIR_D3.7_L1_2  UNITS=MM
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
D        3.200      0.050     -0.050      3.310      0.110      0.060 -------->

## <N-V7> (x2)
DIM POS49= POSITION OF CIRCLE CIR_D3.7_L1_1  UNITS=MM
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
PR     20.400                                      20.468      0.068
PA     75.000                                      74.980     -0.020
TP        RFS      0.200                 0.000      0.138      0.138      0.000 ------#--

DIM POS50= POSITION OF CIRCLE CIR_D3.7_L1_2  UNITS=MM
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
PR     20.400                                      20.393     -0.007
PA     75.000                                      74.952     -0.048
TP        RFS      0.200                 0.000      0.037      0.037      0.000 -#-------

## S2 ##
## <N-V4> (x2)
DIM POS51= LOCATION OF CIRCLE CIR_D3.7_L2_1  UNITS=MM
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
D        3.200      0.050     -0.050      3.311      0.111      0.061 -------->

DIM POS52= LOCATION OF CIRCLE CIR_D3.7_L2_2  UNITS=MM
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
D        3.200      0.050     -0.050      3.308      0.108      0.058 -------->

## <N-V7> (x2)
DIM POS53= POSITION OF CIRCLE CIR_D3.7_L2_1  UNITS=MM
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
PR     20.400                                      20.512      0.112
PA    -90.000                                     -90.034     -0.034
TP        RFS      0.200                 0.000      0.225      0.225      0.025 -------->

DIM POS54= POSITION OF CIRCLE CIR_D3.7_L2_2  UNITS=MM
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
PR     20.400                                      20.459      0.059
PA    -90.000                                     -89.996      0.004
TP        RFS      0.200                 0.000      0.118      0.118      0.000 -----#---


### Back view (J7)
## <V-F2>
DIM POS56= LOCATION OF CIRCLE CIR_D4.98  UNITS=MM
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
D        4.980      0.050     -0.050      5.197      0.217      0.167 -------->

## <V-F12>
DIM POS55= POSITION OF POINT PNT_D  UNITS=MM
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
PR     52.500                                      52.568      0.068
PA     64.900                                      64.851     -0.049
TP        RFS      0.200                 0.000      0.163      0.163      0.000 -------#-
```

```
### Detail P
## <P-V4> (x3)
## 49.3 mm from plane L
DIM POS57= LOCATION OF CIRCLE CIR_D9.975_1  UNITS=MM
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
D       9.975      0.025     -0.025     10.282      0.307      0.282 -------->

## 50.3 mm from plane L
DIM POS58= LOCATION OF CIRCLE CIR_D9.975_2  UNITS=MM
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
D       9.975      0.025     -0.025     10.257      0.282      0.257 -------->

## 51.3 mm from plane L
DIM POS59= LOCATION OF CIRCLE CIR_D9.975_3  UNITS=MM
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
D       9.975      0.025     -0.025     10.226      0.251      0.226 -------->

## <P-V4> cylinder (GX)
DIM POS60= LOCATION OF CYLINDER CYL_D9.975_GX  UNITS=MM
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
D       9.975      0.025     -0.025     10.225      0.250      0.225 -------->

## <P-F1>
DIM POS61= LOCATION OF CIRCLE CIR_D11.1  UNITS=MM
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
D      11.100      0.150     -0.150     11.190      0.090      0.000 -------#-


### Section view L-L
## <L-V3>
DIM POS62= LOCATION OF CIRCLE CIR_D34.1  UNITS=MM
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
D      34.100      0.050     -0.050     34.562      0.462      0.412 -------->

## <L-V13>
DIM POS63= POSITION OF LINE LIN_E  UNITS=MM
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
X      24.100                                     24.110      0.010
TP        RFS      0.100                 0.000      0.020      0.020      0.000 -#-------

## <L-F15>
DIM POS64= POSITION OF LINE LIN_E  UNITS=MM
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
X      24.100                                     24.110      0.010
Y       0.000                                     -0.051     -0.051
TP        RFS      0.100                 0.000      0.105      0.105      0.005 -------->

## <L-F14>
DIM PERP6= PERPENDICULARITY OF LINE LIN_E,RFS TO PLANE PLN_A,RFS EXTENDLENGTH=0.000  UNITS=MM
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
M       0.000      0.150      0.000      0.123      0.123      0.000 -------#-

## <L-F20>
DIM RETTIL2= STRAIGHTNESS OF LINE LIN_CZ_E  UNITS=MM
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
M       0.000      0.100      0.000      0.011      0.011      0.000 #--------

## <L-F5>
DIM POS68= LOCATION OF CIRCLE CIR_D31.9  UNITS=MM
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
D      31.900      0.100     -0.100     32.159      0.259      0.159 -------->

## <L-F16>
DIM CONCEN10= CONCENTRICITY FROM CIRCLE CIR_D31.9 TO CIRCLE CIR_D34.1  UNITS=MM
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
M       0.000      0.100      0.000      0.223      0.223      0.123 -------->
```

```
## <L-F17>
DIM POS65= POSITION OF PLANE PLN_47.4  UNITS=MM
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
Z     -47.400                                     -47.361      0.039
TP        RFS      0.120                 0.000      0.079      0.079      0.000 -----#---

## <L-F8>
DIM POS66= POSITION OF PLANE PLN_46.65  UNITS=MM
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
Z     -46.650                                     -46.620      0.030
TP        RFS      0.200                 0.000      0.059      0.059      0.000 --#------

## <L-F1>
DIM POS67= LOCATION OF POINT PNT_D54.3  UNITS=MM
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
Z       -8.300      0.300     -0.300     -7.617      0.683      0.383 -------->


### Detail H
## <H-F7> (x3)
DIM POS69= POSITION OF POINT PNT_0.9_1  UNITS=MM
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
Y       0.900                                       0.948      0.048
TP        RFS      0.300                 0.000      0.096      0.096      0.000 --#------

DIM POS70= POSITION OF POINT PNT_0.9_2  UNITS=MM
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
Y       0.900                                       0.945      0.045
TP        RFS      0.300                 0.000      0.090      0.090      0.000 --#------

DIM POS71= POSITION OF POINT PNT_0.9_3  UNITS=MM
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
Y       0.900                                       0.939      0.039
TP        RFS      0.300                 0.000      0.079      0.079      0.000 --#------

## <H-F8> (x2)
DIM POS73= LOCATION OF POINT R19.5_2  UNITS=MM
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
PR      19.500      0.100     -0.100     19.766      0.266      0.166 -------->

DIM POS74= LOCATION OF POINT R19.5_1  UNITS=MM
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
PR      19.500      0.100     -0.100     19.744      0.244      0.144 -------->

## <H-F10> (x4)
DIM POS75= LOCATION OF POINT R21.5_1  UNITS=MM
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
PR      21.500      0.100     -0.100     21.697      0.197      0.097 -------->

DIM POS76= LOCATION OF POINT R21.5_2  UNITS=MM
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
PR      21.500      0.100     -0.100     21.764      0.264      0.164 -------->

DIM POS77= LOCATION OF POINT R21.5_3  UNITS=MM
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
PR      21.500      0.100     -0.100     21.805      0.305      0.205 -------->

DIM POS78= LOCATION OF POINT R21.5_4  UNITS=MM
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
PR      21.500      0.100     -0.100     21.794      0.294      0.194 -------->

## <H-F5> (x7)
DIM POS79= POSITION OF POINT 0.94_1  UNITS=MM
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
Y       0.000                                       0.052      0.052
TP        RFS      0.300                 0.000      0.104      0.104      0.000 ---#-----
```

```
DIM POS80= POSITION OF POINT 0.94_2  UNITS=MM
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
Y       0.000                                       0.062      0.062
TP        RFS      0.300                 0.000      0.124      0.124      0.000 ---#-----

DIM POS81= POSITION OF POINT 0.94_3  UNITS=MM
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
Y       0.000                                       0.073      0.073
TP        RFS      0.300                 0.000      0.147      0.147      0.000 ----#----

DIM POS82= POSITION OF POINT 0.94_4  UNITS=MM
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
Y       0.000                                       0.070      0.070
TP        RFS      0.300                 0.000      0.140      0.140      0.000 ----#----

DIM POS83= POSITION OF POINT 0.94_5  UNITS=MM
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
Y       0.000                                       0.061      0.061
TP        RFS      0.300                 0.000      0.122      0.122      0.000 ---#-----

DIM POS84= POSITION OF POINT 0.94_6  UNITS=MM
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
Y       0.000                                       0.051      0.051
TP        RFS      0.300                 0.000      0.102      0.102      0.000 ---#-----

DIM POS85= POSITION OF POINT 0.94_7  UNITS=MM
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
Y       0.000                                       0.059      0.059
TP        RFS      0.300                 0.000      0.119      0.119      0.000 ---#-----

## <H-F6> (x5)
DIM POS86= POSITION OF POINT 0_1  UNITS=MM
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
Y       0.000                                      -0.046     -0.047
TP        RFS      0.300                 0.000      0.093      0.093      0.000 --#------

DIM POS87= POSITION OF POINT 0_2  UNITS=MM
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
Y       0.000                                      -0.040     -0.040
TP        RFS      0.300                 0.000      0.079      0.079      0.000 --#------

DIM POS88= POSITION OF POINT 0_3  UNITS=MM
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
Y       0.000                                      -0.044     -0.044
TP        RFS      0.300                 0.000      0.088      0.088      0.000 --#------

DIM POS89= POSITION OF POINT 0_4  UNITS=MM
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
Y       0.000                                      -0.046     -0.046
TP        RFS      0.300                 0.000      0.091      0.091      0.000 --#------

DIM POS90= POSITION OF POINT 0_5  UNITS=MM
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
Y       0.000                                      -0.046     -0.046
TP        RFS      0.300                 0.000      0.092      0.092      0.000 --#------


### Sector view M-M
## <M-F2> (x3)
DIM POS91= LOCATION OF POINT R11.15_1  UNITS=MM
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
PR      11.150      0.150     -0.150     11.077     -0.073      0.000 --#------

DIM POS92= LOCATION OF POINT R11.15_2  UNITS=MM
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
PR      11.150      0.150     -0.150     11.090     -0.060      0.000 --#------

DIM POS93= LOCATION OF POINT R11.15_3  UNITS=MM
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
PR      11.150      0.150     -0.150     11.093     -0.057      0.000 --#------
```

```
## <M-F4>
DIM POS170= LOCATION OF CIRCLE CIR_D30.18  UNITS=MM
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
D       30.180      0.150     -0.150     30.321      0.141      0.000 --------#

## <M-F5>
DIM POS169= POSITION OF CIRCLE CIR_D30.18  UNITS=MM
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
X       0.000                                       0.020      0.020
Y       0.000                                       0.042      0.042
TP        RFS      0.200                 0.000      0.093      0.093      0.000 ----#----


### Detail AG
## <AG-F1>
DIM DIST2= 2D DISTANCE FROM POINT PNT_16.1_2 TO POINT PNT_16.1_1 PAR TO POINT PNT_16.1_1,NO_RADIUS  UNIT
S=MM
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
M       16.100      0.200     -0.200     16.452      0.352      0.152 -------->

## <AG-F2>
DIM POS114= LOCATION OF POINT PNT_16.1_MID  UNITS=MM
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
Y        0.000      0.050     -0.050     -0.072     -0.072      0.022 <--------


### Sector view K-K
## <K-F5>
# CH1
DIM POS115= POSITION OF POINT PNT_CH_1_4  UNITS=MM
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
Z      -5.800                                      -5.901     -0.101
TP        RFS      0.400                 0.000      0.202      0.202      0.000 ----#----

DIM POS116= POSITION OF POINT PNT_CH_1_5  UNITS=MM
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
Z      -5.800                                      -5.895     -0.095
TP        RFS      0.400                 0.000      0.189      0.189      0.000 ----#----

DIM POS117= POSITION OF POINT PNT_CH_1_6  UNITS=MM
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
Z      -5.800                                      -5.874     -0.074
TP        RFS      0.400                 0.000      0.149      0.149      0.000 ---#-----

# CH2
DIM POS118= POSITION OF POINT PNT_CH_2_4  UNITS=MM
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
Z      -5.800                                      -5.818     -0.018
TP        RFS      0.400                 0.000      0.037      0.037      0.000 #--------

DIM POS119= POSITION OF POINT PNT_CH_2_5  UNITS=MM
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
Z      -5.800                                      -5.805     -0.005
TP        RFS      0.400                 0.000      0.010      0.010      0.000 #--------

DIM POS120= POSITION OF POINT PNT_CH_2_6  UNITS=MM
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
Z      -5.800                                      -5.789      0.011
TP        RFS      0.400                 0.000      0.023      0.023      0.000 #--------

# CH3
DIM POS122= POSITION OF POINT PNT_CH_3_4  UNITS=MM
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
Z      -5.800                                      -5.819     -0.019
TP        RFS      0.400                 0.000      0.037      0.037      0.000 #--------
```

```
DIM POS123= POSITION OF POINT PNT_CH_3_5  UNITS=MM
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
Z      -5.800                                      -5.791      0.009
TP        RFS      0.400                 0.000      0.019      0.019      0.000 #--------

DIM POS121= POSITION OF POINT PNT_CH_3_6  UNITS=MM
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
Z      -5.800                                      -5.762      0.038
TP        RFS      0.400                 0.000      0.076      0.076      0.000 -#-------

# CH4
DIM POS124= POSITION OF POINT PNT_CH_4_4  UNITS=MM
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
Z      -5.800                                      -5.781      0.019
TP        RFS      0.400                 0.000      0.037      0.037      0.000 #--------

DIM POS125= POSITION OF POINT PNT_CH_4_5  UNITS=MM
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
Z      -5.800                                      -5.801     -0.001
TP        RFS      0.400                 0.000      0.002      0.002      0.000 #--------

DIM POS126= POSITION OF POINT PNT_CH_4_6  UNITS=MM
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
Z      -5.800                                      -5.818     -0.018
TP        RFS      0.400                 0.000      0.037      0.037      0.000 #--------

# CH5
DIM POS127= POSITION OF POINT PNT_CH_5_4  UNITS=MM
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
Z      -5.800                                      -5.870     -0.070
TP        RFS      0.400                 0.000      0.140      0.140      0.000 ---#-----

DIM POS128= POSITION OF POINT PNT_CH_5_5  UNITS=MM
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
Z      -5.800                                      -5.839     -0.039
TP        RFS      0.400                 0.000      0.078      0.078      0.000 -#-------

DIM POS129= POSITION OF POINT PNT_CH_5_6  UNITS=MM
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
Z      -5.800                                      -5.769      0.031
TP        RFS      0.400                 0.000      0.062      0.062      0.000 -#-------

# CH6
DIM POS130= POSITION OF POINT PNT_CH_6_4  UNITS=MM
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
Z      -5.800                                      -5.791      0.009
TP        RFS      0.400                 0.000      0.017      0.017      0.000 #--------

DIM POS131= POSITION OF POINT PNT_CH_6_5  UNITS=MM
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
Z      -5.800                                      -5.807     -0.007
TP        RFS      0.400                 0.000      0.014      0.014      0.000 #--------

DIM POS132= POSITION OF POINT PNT_CH_6_6  UNITS=MM
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
Z      -5.800                                      -5.812     -0.012
TP        RFS      0.400                 0.000      0.024      0.024      0.000 #--------

## <K-F7>
# CH1
DIM POS133= POSITION OF POINT PNT_CH_1_1  UNITS=MM
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
Y     -43.100                                     -43.085      0.015
TP        RFS      0.100                 0.000      0.030      0.030      0.000 --#------

DIM POS134= POSITION OF POINT PNT_CH_1_2  UNITS=MM
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
Y     -43.100                                     -43.092      0.008
TP        RFS      0.100                 0.000      0.016      0.016      0.000 -#-------
```

```
DIM POS135= POSITION OF POINT PNT_CH_1_3  UNITS=MM
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
Y     -43.100                                     -43.104     -0.004
TP        RFS      0.100                 0.000      0.007      0.007      0.000 #--------

# CH2
DIM POS136= POSITION OF POINT PNT_CH_2_1  UNITS=MM
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
Y     -31.400                                     -31.320      0.080
TP        RFS      0.100                 0.000      0.160      0.160      0.060 -------->

DIM POS137= POSITION OF POINT PNT_CH_2_2  UNITS=MM
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
Y     -31.400                                     -31.325      0.075
TP        RFS      0.100                 0.000      0.149      0.149      0.049 -------->

DIM POS138= POSITION OF POINT PNT_CH_2_3  UNITS=MM
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
Y     -31.400                                     -31.348      0.052
TP        RFS      0.100                 0.000      0.104      0.104      0.004 -------->

# CH3
DIM POS139= POSITION OF POINT PNT_CH_3_1  UNITS=MM
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
Y     -31.400                                     -31.322      0.078
TP        RFS      0.100                 0.000      0.157      0.157      0.057 -------->

DIM POS140= POSITION OF POINT PNT_CH_3_2  UNITS=MM
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
Y     -31.400                                     -31.305      0.095
TP        RFS      0.100                 0.000      0.190      0.190      0.090 -------->

DIM POS141= POSITION OF POINT PNT_CH_3_3  UNITS=MM
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
Y     -31.400                                     -31.283      0.117
TP        RFS      0.100                 0.000      0.235      0.235      0.135 -------->

# CH4
DIM POS142= POSITION OF POINT PNT_CH_4_1  UNITS=MM
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
Y      61.900                                      61.484     -0.416
TP        RFS      0.100                 0.000      0.833      0.833      0.733 -------->

DIM POS143= POSITION OF POINT PNT_CH_4_2  UNITS=MM
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
Y      61.900                                      61.469     -0.431
TP        RFS      0.100                 0.000      0.863      0.863      0.763 -------->

DIM POS144= POSITION OF POINT PNT_CH_4_3  UNITS=MM
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
Y      61.900                                      61.460     -0.440
TP        RFS      0.100                 0.000      0.879      0.879      0.779 -------->

# CH5
DIM POS145= POSITION OF POINT PNT_CH_5_1  UNITS=MM
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
Y      45.700                                      45.854      0.154
TP        RFS      0.100                 0.000      0.308      0.308      0.208 -------->

DIM POS146= POSITION OF POINT PNT_CH_5_2  UNITS=MM
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
Y      45.700                                      45.806      0.106
TP        RFS      0.100                 0.000      0.211      0.211      0.111 -------->

DIM POS147= POSITION OF POINT PNT_CH_5_3  UNITS=MM
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
Y      45.700                                      45.794      0.094
TP        RFS      0.100                 0.000      0.188      0.188      0.088 -------->
```

```
# CH6
DIM POS148= POSITION OF POINT PNT_CH_6_1  UNITS=MM
AX    NOMINAL       +TOL       -TOL       BONUS       MEAS        DEV     OUTTOL
Y      45.700                                       45.557     -0.143
TP        RFS      0.100                 0.000      0.286      0.286      0.186 -------->

DIM POS149= POSITION OF POINT PNT_CH_6_2  UNITS=MM
AX    NOMINAL       +TOL       -TOL       BONUS       MEAS        DEV     OUTTOL
Y      45.700                                       45.576     -0.124
TP        RFS      0.100                 0.000      0.248      0.248      0.148 -------->

DIM POS150= POSITION OF POINT PNT_CH_6_3  UNITS=MM
AX    NOMINAL       +TOL       -TOL       BONUS       MEAS        DEV     OUTTOL
Y      45.700                                       45.611     -0.089
TP        RFS      0.100                 0.000      0.178      0.178      0.078 -------->
```

Zarys profilu powierzchni w NQR

DIM PROF1= PROFILE OF SURFACE OF SET SCN1 FORMANDLOCATION UNITS=MM

AX	NOMINAL	+TOL	-TOL	MEAS	DEV	OUTTOL	
M	0.000	0.300	0.000	0.138	0.138	0.000	----#----

Promienie

DIM POS151= LOCATION OF POINT PNT_R1 UNITS=MM

AX	NOMINAL	+TOL	-TOL	MEAS	DEV	OUTTOL	
PR	9.500	0.150	-0.150	9.344	-0.156	0.006	<--------

DIM POS152= LOCATION OF POINT PNT_R2 UNITS=MM

AX	NOMINAL	+TOL	-TOL	MEAS	DEV	OUTTOL	
PR	9.500	0.150	-0.150	9.337	-0.163	0.013	<--------

DIM POS153= LOCATION OF POINT PNT_R3 UNITS=MM

AX	NOMINAL	+TOL	-TOL	MEAS	DEV	OUTTOL	
PR	9.500	0.150	-0.150	9.343	-0.157	0.007	<--------

DIM POS154= LOCATION OF POINT PNT_R4 UNITS=MM

AX	NOMINAL	+TOL	-TOL	MEAS	DEV	OUTTOL	
PR	9.500	0.150	-0.150	9.371	-0.129	0.000	#--------

DIM POS155= LOCATION OF POINT PNT_R5 UNITS=MM

AX	NOMINAL	+TOL	-TOL	MEAS	DEV	OUTTOL	
PR	9.500	0.150	-0.150	9.385	-0.115	0.000	-#-------

DIM POS156= LOCATION OF POINT PNT_R6 UNITS=MM

AX	NOMINAL	+TOL	-TOL	MEAS	DEV	OUTTOL	
PR	9.500	0.150	-0.150	9.397	-0.103	0.000	-#-------

DIM POS157= LOCATION OF POINT PNT_R7 UNITS=MM

AX	NOMINAL	+TOL	-TOL	MEAS	DEV	OUTTOL	
PR	9.500	0.150	-0.150	9.420	-0.080	0.000	--#------

DIM POS158= LOCATION OF POINT PNT_R8 UNITS=MM

AX	NOMINAL	+TOL	-TOL	MEAS	DEV	OUTTOL	
PR	9.500	0.150	-0.150	9.439	-0.061	0.000	--#------

DIM POS159= LOCATION OF POINT PNT_R9 UNITS=MM

AX	NOMINAL	+TOL	-TOL	MEAS	DEV	OUTTOL	
PR	9.500	0.150	-0.150	9.448	-0.052	0.000	--#------

DIM POS160= LOCATION OF POINT PNT_R10 UNITS=MM

AX	NOMINAL	+TOL	-TOL	MEAS	DEV	OUTTOL	
PR	9.500	0.150	-0.150	9.441	-0.059	0.000	--#------

DIM POS161= LOCATION OF POINT PNT_R11 UNITS=MM

AX	NOMINAL	+TOL	-TOL	MEAS	DEV	OUTTOL	
PR	9.500	0.150	-0.150	9.423	-0.077	0.000	--#------

DIM POS162= LOCATION OF POINT PNT_R12 UNITS=MM

AX	NOMINAL	+TOL	-TOL	MEAS	DEV	OUTTOL	
PR	9.500	0.150	-0.150	9.409	-0.091	0.000	-#-------

DIM POS163= LOCATION OF POINT PNT_R13 UNITS=MM

AX	NOMINAL	+TOL	-TOL	MEAS	DEV	OUTTOL	
PR	9.500	0.150	-0.150	9.396	-0.104	0.000	-#-------

DIM POS164= LOCATION OF POINT PNT_R14 UNITS=MM

AX	NOMINAL	+TOL	-TOL	MEAS	DEV	OUTTOL	
PR	9.500	0.150	-0.150	9.386	-0.114	0.000	-#-------

DIM POS165= LOCATION OF POINT PNT_R15 UNITS=MM

AX	NOMINAL	+TOL	-TOL	MEAS	DEV	OUTTOL	
PR	9.500	0.150	-0.150	9.388	-0.112	0.000	-#-------

DIM POS166= LOCATION OF POINT PNT_R16 UNITS=MM

AX	NOMINAL	+TOL	-TOL	MEAS	DEV	OUTTOL	
PR	9.500	0.150	-0.150	9.401	-0.099	0.000	-#-------

```
DIM POS167= LOCATION OF POINT PNT_R17  UNITS=MM
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
PR       9.500      0.150     -0.150      9.403     -0.097      0.000 -#-------

DIM POS168= LOCATION OF POINT PNT_R18  UNITS=MM
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
PR       9.500      0.150     -0.150      9.414     -0.086      0.000 -#-------
```