Valeo	PART NAME : Overmolded body	kwietnia 21, 2021	20:56
	DRAWING REV: F	DRAWING No: V29123229_001	STATS COUNT : 9
	MEASUREMENT MADE BY : PAM_Jakubiec S.	COMMENT : cav.1	

```
Current Temperatures: X=21.42 Y=21.278 Z=21.616 P=21.109
Temperature Compensation is ON

#### SHEET 1/2
### Left view
## <T-C6>
DIM POS3= POSITION OF PLANE PLN_H3  UNITS=MM
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
Z      30.380                                      29.880     -0.500
TP        RFS      0.500                 0.000      1.000      1.000      0.500 -------->

## <T-C15> (x2)
DIM POS1= POSITION OF PLANE PLN_S1  UNITS=MM
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
Z     -17.720                                     -18.246     -0.526
TP        RFS      0.500                 0.000      1.053      1.053      0.553 -------->

DIM POS2= POSITION OF PLANE PLN_S2  UNITS=MM
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
Z     -17.720                                     -17.698      0.022
TP        RFS      0.500                 0.000      0.045      0.045      0.000 #--------

## <T-C12>
DIM PLAN1= FLATNESS OF PLANE PLN_N  UNITS=MM
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
M        0.000      0.200      0.000      0.065      0.065      0.000 --#------

## <T-C13>
DIM POS4= POSITION OF PLANE PLN_N  UNITS=MM
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
Y       3.620                                       3.712      0.092
TP        RFS      0.400                 0.000      0.184      0.184      0.000 ----#----


### Section view A-A
## <A-C5> (x3)
DIM POS18= LOCATION OF CIRCLE CIR_D48.8_GX_1  UNITS=MM
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
D       48.800      0.100     -0.100     48.652     -0.148      0.048 <--------

DIM POS5= LOCATION OF CIRCLE CIR_D48.8_GX_2_F  UNITS=MM
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
D       48.800      0.100     -0.100     48.668     -0.132      0.032 <--------

DIM POS19= LOCATION OF CIRCLE CIR_D48.8_GX_3  UNITS=MM
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
D       48.800      0.100     -0.100     48.642     -0.158      0.058 <--------

## <A-F10>
DIM POS22= POSITION OF CIRCLE CIR_D48.8_GX_2_F  UNITS=MM
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
Z     -34.300                                     -34.262      0.038
TP        RFS      0.200                 0.000      0.077      0.077      0.000 ---#-----

## <A-F11>
DIM PERP1= PERPENDICULARITY OF CYLINDER CYL_D48.8_F,RFS TO LINE LIN_B,RFS EXTENDLENGTH=0.000  UNITS=MM
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
M        0.000      0.100      0.000      0.075      0.075      0.000 ------#--
```

```
## <A-F12>
DIM POS94= POSITION OF CIRCLE CIR_D48.8_GX_2_F  UNITS=MM
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
X       0.000                                       0.060      0.060
TP        RFS      0.200                 0.000      0.120      0.120      0.000 -----#---

## <A-C3>
DIM POS6= LOCATION OF CYLINDER CYL_D55  UNITS=MM
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
D       55.000      0.200     -0.200     54.885     -0.116      0.000 -#-------

## <A-C13>
DIM CILTÁ1= CYLINDRICITY OF CYLINDER CYL_D55  UNITS=MM
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
M        0.000      0.400      0.000      0.192      0.192      0.000 ----#----

## <A-C14>
DIM POS95= POSITION OF CYLINDER CYL_D55  USE AXIS=AVERAGE  REF LENGTH=0.000  UNITS=MM
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
X       0.000                                       0.089      0.089
Z     -52.620                                     -52.502      0.118
TP        RFS      0.500                 0.000      0.296      0.296      0.000 -----#---

## <A-F18>
DIM POS7= LOCATION OF CIRCLE CIR_D26  UNITS=MM
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
D       26.000      0.100     -0.100     26.153      0.153      0.053 -------->

## <A-F19>
DIM CONCEN1= CONCENTRICITY FROM CIRCLE CIR_D26 TO LINE LIN_B  UNITS=MM
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
M        0.000      0.100      0.000      0.162      0.162      0.062 -------->

## <A-C20>
DIM POS72= POSITION OF CIRCLE CIR_D48.8_GX_2_F  UNITS=MM
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
X      53.180                                      53.371      0.191
Y     -27.780                                     -27.714      0.066
TP        RFS      2.000                 0.000      0.404      0.404      0.000 -#-------

## <A-C21>
DIM POS172= POSITION OF CYLINDER CYL_D55  USE AXIS=AVERAGE  REF LENGTH=0.000  UNITS=MM
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
X      53.180                                      53.316      0.136
Y     -27.780                                     -27.614      0.166
TP        RFS      2.000                 0.000      0.429      0.429      0.000 -#-------


### Section view B-B
## <B-C4>
DIM POS8= POSITION OF PLANE PLN_N1'  UNITS=MM
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
Z     -10.000                                      -9.927      0.073
TP        RFS      2.000                 0.000      0.145      0.145      0.000 #--------

## <B-F2>
DIM PERP2= PERPENDICULARITY OF CYLINDER CYL_M6-6H_Q,RFS TO PLANE PLN_N,RFS EXTENDLENGTH=0.000  UNITS=MM
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
M        0.000      0.200      0.000      0.083      0.083      0.000 ---#-----

## <B-C3>
DIM POS9= POSITION OF CIRCLE M6-6H_Q  UNITS=MM
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
PR     60.000                                      60.194      0.194
PA     80.000                                      79.919     -0.081
TP        RFS      0.600                 0.000      0.424      0.424      0.000 ------#--
```

```
### Section view C-C
## <C-C3> (x2)
# H2
DIM POS12= POSITION OF PLANE PLN_H2  UNITS=MM
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
Z     -20.320                                     -20.353     -0.033
TP        RFS      0.500                 0.000      0.066      0.066      0.000 -#-------

# H5
DIM POS11= POSITION OF PLANE PLN_H5  UNITS=MM
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
Z     -20.320                                     -20.322     -0.002
TP        RFS      0.500                 0.000      0.004      0.004      0.000 #--------

## <C-F1> (x2)
# H2 - cylinder
DIM POS10= LOCATION OF CYLINDER CYL_D9.15_H2  UNITS=MM
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
D        9.000      0.050     -0.050      6.908     -2.092      2.042 <--------

## 1.5 mm from plane S
DIM POS99= LOCATION OF CIRCLE CIR_D9.15_H2_1.5  UNITS=MM
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
D        9.150      0.050     -0.050      6.867     -2.283      2.233 <--------

## 10 mm from plane S
DIM POS100= LOCATION OF CIRCLE CIR_D9.15_H2_10  UNITS=MM
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
D        9.150      0.050     -0.050      6.910     -2.240      2.190 <--------

## 18.5 mm from plane S
DIM POS101= LOCATION OF CIRCLE CIR_D9.15_H2_18.5  UNITS=MM
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
D        9.000      0.050     -0.050      6.930     -2.070      2.020 <--------

# H5 - cylinder
DIM POS13= LOCATION OF CYLINDER CYL_D9.15_H5  UNITS=MM
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
D        9.150      0.050     -0.050      6.911     -2.239      2.189 <--------

## 1.5 mm from plane S
DIM POS102= LOCATION OF CIRCLE CIR_D9.15_H5_1.5  UNITS=MM
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
D        9.150      0.050     -0.050      6.873     -2.277      2.227 <--------

## 10 mm from plane S
DIM POS103= LOCATION OF CIRCLE CIR_D9.15_H5_10  UNITS=MM
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
D        9.150      0.000     -0.050      6.909     -2.241      2.191 <--------

## 18.5 mm from plane S
DIM POS104= LOCATION OF CIRCLE CIR_D9.15_H5_18.5  UNITS=MM
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
D        9.150      0.000     -0.050      6.938     -2.212      2.162 <--------

## <C-C2> (x2)
# H2
DIM POS14= POSITION OF CYLINDER CYL_D9.15_H2  USE AXIS=AVERAGE  REF LENGTH=0.000  UNITS=MM
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
X      80.578                                      80.933      0.355
Y     -59.623                                     -59.720     -0.097
TP        RFS      0.400                 0.000      0.736      0.736      0.336 -------->

# H5
DIM POS15= POSITION OF CYLINDER CYL_D9.15_H5  USE AXIS=AVERAGE  REF LENGTH=0.000  UNITS=MM
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
X      28.660                                      28.768      0.108
Y       6.320                                       6.357      0.037
TP        RFS      0.400                 0.000      0.228      0.228      0.000 -----#---
```

```
### Section view J-J
## <J-F2> - cylinder
DIM POS16= LOCATION OF CYLINDER CYL_D8.19_H3  UNITS=MM
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
D        8.160      0.040     -0.040      8.160      0.000      0.000 ----#----

## <J-F2> (x3)
## 1.5 mm
DIM POS96= LOCATION OF CIRCLE CIR_D8.19_1  UNITS=MM
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
D        8.160      0.040     -0.040      8.321      0.161      0.121 -------->

## 6 mm
DIM POS97= LOCATION OF CIRCLE CIR_D8.19_2  UNITS=MM
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
D        8.160      0.040     -0.040      8.288      0.128      0.088 -------->

## 12 mm
DIM POS98= LOCATION OF CIRCLE CIR_D8.19_3  UNITS=MM
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
D        8.160      0.040     -0.040      8.278      0.118      0.078 -------->

## <J-C3>
DIM POS17= POSITION OF CYLINDER CYL_D8.19_H3  USE AXIS=AVERAGE  REF LENGTH=0.000  UNITS=MM
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
X      24.760                                      24.673     -0.087
Y     -58.710                                     -59.339     -0.629
TP        RFS      0.400                 0.000      1.270      1.270      0.870 -------->

## <J-F5>
DIM POS171= LOCATION OF CIRCLE CIR_D9.7  UNITS=MM
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
D        9.700      0.150     -0.150      9.700      0.000      0.000 ----#----


### Section view AE-AE
## <AE-C4>
DIM POS20= POSITION OF PLANE PLN_N2'  UNITS=MM
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
Z     -10.000                                      -9.989      0.011
TP        RFS      0.500                 0.000      0.023      0.023      0.000 #--------

## <AE-C2>
DIM POS21= POSITION OF CYLINDER CYL_M6-6H_R  USE AXIS=AVERAGE  REF LENGTH=0.000  UNITS=MM
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
X      84.680                                      84.790      0.110
TP        RFS      1.000                 0.000      0.221      0.221      0.000 -#-------
```

```
#### SHEET 2/2
### Detail F
## <F-V1>  (GG) x3
DIM POS23= LOCATION OF CIRCLE CIR_D12.03_3  UNITS=MM
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
D       12.030      0.042     -0.042     12.042      0.012      0.000 -----#---

DIM POS105= LOCATION OF CIRCLE CIR_D12.03_2  UNITS=MM
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
D       12.030      0.042     -0.042     12.058      0.028      0.000 -------#-

DIM POS106= LOCATION OF CIRCLE CIR_D12.03_1  UNITS=MM
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
D       12.030      0.042     -0.042     12.086      0.056      0.014 -------->

## <F-V8>
DIM CONCEN2= CONCENTRICITY FROM CIRCLE CIR_D12.03_3 TO LINE LIN_B  UNITS=MM
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
M        0.000      0.050      0.000      0.092      0.092      0.042 -------->

## <F-F7> (x2)
DIM POS24= LOCATION OF CIRCLE CIR_D8.5_3  UNITS=MM
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
D        8.500      0.100     -0.100      8.545      0.045      0.000 ------#--

DIM POS25= LOCATION OF CIRCLE CIR_D8.5_4  UNITS=MM
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
D        8.500      0.100     -0.100      8.530      0.030      0.000 -----#---

## <F-F12>(x2)
DIM CONCEN3= CONCENTRICITY FROM CIRCLE CIR_D8.5_3 TO LINE LIN_B  UNITS=MM
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
M        0.000      0.100      0.000      0.089      0.089      0.000 --------#

DIM CONCEN4= CONCENTRICITY FROM CIRCLE CIR_D8.5_4 TO LINE LIN_CZ_B  UNITS=MM
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
M        0.000      0.100      0.000      0.089      0.089      0.000 --------#

## <F-F9>
DIM POS107= POSITION OF POINT PNT_7.2  UNITS=MM
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
Z      -7.200                                     -7.201     -0.001
TP        RFS      0.300                 0.000      0.001      0.001      0.000 #--------

## <F-F13>
DIM POS108= LOCATION OF CIRCLE CIR_D18.1  UNITS=MM
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
D       18.100      0.150     -0.150     18.111      0.011      0.000 ----#----

## <F-F14>
DIM CONCEN15= CONCENTRICITY FROM CIRCLE CIR_D18.1 TO LINE LIN_B  UNITS=MM
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
M        0.000      0.200      0.000      0.038      0.038      0.000 -#-------

## <F-F11>
DIM POS109= POSITION OF PLANE PLN_16.7  UNITS=MM
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
Z     -16.700                                    -16.724     -0.024
TP        RFS      0.100                 0.000      0.048      0.048      0.000 ----#----


### Detail Q
## <Q-F2>
DIM POS26= LOCATION OF CIRCLE CIR_D14.2  UNITS=MM
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
D       14.200      0.100     -0.100     14.373      0.173      0.073 -------->
```

```
### Section view D-D
## <D-F7> (x6)
DIM PLAN2= FLATNESS OF PLANE PLN_A1  UNITS=MM
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
M        0.000      0.200      0.000      0.013      0.013      0.000 #--------

DIM PLAN3= FLATNESS OF PLANE PLN_A2  UNITS=MM
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
M        0.000      0.200      0.000      0.028      0.028      0.000 -#-------

DIM PLAN4= FLATNESS OF PLANE PLN_A3  UNITS=MM
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
M        0.000      0.200      0.000      0.006      0.006      0.000 #--------

DIM PLAN5= FLATNESS OF PLANE PLN_A4  UNITS=MM
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
M        0.000      0.200      0.000      0.000      0.000      0.000 #--------

DIM PLAN6= FLATNESS OF PLANE PLN_A5  UNITS=MM
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
M        0.000      0.200      0.000      0.010      0.010      0.000 #--------

DIM PLAN7= FLATNESS OF PLANE PLN_A6  UNITS=MM
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
M        0.000      0.200      0.000      0.025      0.025      0.000 -#-------

## <D-F8>
DIM PLAN8= FLATNESS OF PLANE PLN_A  UNITS=MM
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
M        0.000      0.350      0.000      0.054      0.054      0.000 -#-------

## <D-V1> (x3)
DIM POS27= LOCATION OF CIRCLE CIR_D13.945_1  UNITS=MM
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
D       13.945      0.042     -0.042     13.983      0.038      0.000 --------#

DIM POS28= LOCATION OF CIRCLE CIR_D13.945_2  UNITS=MM
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
D       13.945      0.042     -0.042     13.984      0.039      0.000 --------#

DIM POS29= LOCATION OF CIRCLE CIR_D13.945_3  UNITS=MM
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
D       13.945      0.042     -0.042     13.961      0.016      0.000 ------#--

## <D-F10>
DIM CILTÁ2= CYLINDRICITY OF CYLINDER CYL_D13.945  UNITS=MM
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
M        0.000      0.050      0.000      0.073      0.073      0.023 -------->

## <D-F5>
DIM PERP4= PERPENDICULARITY OF LINE LIN_CZ_B,RFS TO PLANE PLN_A,RFS EXTENDLENGTH=0.000  UNITS=MM
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
M        0.000      0.300      0.000      0.062      0.062      0.000 -#-------

## <D-V6>
DIM RETTIL1= STRAIGHTNESS OF LINE LIN_CZ_B  UNITS=MM
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
M        0.000      0.150      0.000      0.033      0.033      0.000 --#------

## <D-V2> (x2)
DIM POS30= LOCATION OF CIRCLE CIR_D10.945_1  UNITS=MM
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
D       10.945      0.042     -0.042     10.982      0.037      0.000 --------#

DIM POS31= LOCATION OF CIRCLE CIR_D10.945_2  UNITS=MM
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
D       10.945      0.042     -0.042     10.977      0.032      0.000 -------#-
```

```
## <D-F11>
DIM CILTÁ3= CYLINDRICITY OF CYLINDER CYL_D10.945  UNITS=MM
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
M       0.000      0.050      0.000      0.021      0.021      0.000 ---#-----

## <D-F9>
DIM POS32= POSITION OF PLANE PLN_H  UNITS=MM
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
Z     -86.920                                     -86.834      0.086
TP       RFS      0.260                 0.000      0.171      0.171      0.000 -----#---

## <D-F12>
DIM POS110= POSITION OF PLANE PLN_J  UNITS=MM
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
Z     -79.520                                     -79.541     -0.021
TP       RFS      0.300                 0.000      0.042      0.042      0.000 -#-------


### Detail G
## <G-F3> (x2)
DIM POS33= LOCATION OF CIRCLE CIR_D8.2_1  UNITS=MM
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
D       8.500      0.100     -0.100      8.623      0.123      0.023 -------->

DIM POS34= LOCATION OF CIRCLE CIR_D8.2_2  UNITS=MM
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
D       8.500      0.100     -0.100      8.580      0.080      0.000 --------#

## <G-F15> (x2)
DIM CONCEN5= CONCENTRICITY FROM CIRCLE CIR_D8.2_1 TO LINE LIN_B  UNITS=MM
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
M       0.000      0.100      0.000      0.094      0.094      0.000 --------#

DIM CONCEN6= CONCENTRICITY FROM CIRCLE CIR_D8.2_2 TO LINE LIN_B  UNITS=MM
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
M       0.000      0.100      0.000      0.127      0.127      0.027 -------->

## <G-V1> - cylinder (GG)
DIM POS35= LOCATION OF CYLINDER CYL_D21  UNITS=MM
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
D      21.000      0.050     -0.050     20.996     -0.004      0.000 ----#----

## <G-V1> (GG) x3
DIM POS111= LOCATION OF CIRCLE CIR_D21_1  UNITS=MM
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
D      21.000      0.050     -0.050     21.004      0.004      0.000 ----#----

DIM POS112= LOCATION OF CIRCLE CIR_D21_2  UNITS=MM
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
D      21.000      0.050     -0.050     20.981     -0.019      0.000 --#------

DIM POS113= LOCATION OF CIRCLE CIR_D21_3  UNITS=MM
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
D      21.000      0.050     -0.050     20.966     -0.034      0.000 -#-------

## <G-V12>
DIM CONCEN7= CONCENTRICITY FROM CYLINDER CYL_D21 TO LINE LIN_B  UNITS=MM
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
M       0.000      0.100      0.000      0.075      0.075      0.000 ------#--

## <G-F13>
DIM CILTÁ4= CYLINDRICITY OF CYLINDER CYL_D21  UNITS=MM
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
M       0.000      0.050      0.000      0.040      0.040      0.000 -------#-

## <G-F2>
DIM POS36= LOCATION OF CIRCLE CIR_15.2  UNITS=MM
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
D      15.500      0.100     -0.100     15.642      0.142      0.042 -------->
```

```
## <G-F14>
DIM CONCEN8= CONCENTRICITY FROM CIRCLE CIR_15.2 TO LINE LIN_B  UNITS=MM
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
M       0.000      0.100      0.000      0.013      0.013      0.000 -#-------

## <G-F16>
DIM POS37= POSITION OF PLANE PLN_M  UNITS=MM
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
Z       2.450                                      2.318     -0.132
TP        RFS      0.200                 0.000      0.264      0.264      0.064 -------->

## <G-F17>
DIM POS38= POSITION OF PLANE PLN_7.5  UNITS=MM
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
Z       7.500                                      7.295     -0.205
TP        RFS      0.100                 0.000      0.409      0.409      0.309 -------->

## <G-F18>
DIM POS39= POSITION OF PLANE PLN_3.8  UNITS=MM
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
Z      -3.800                                     -3.814     -0.014
TP        RFS      0.200                 0.000      0.028      0.028      0.000 -#-------


### Section view E-E
## <E-F8>
DIM POS40= POSITION OF CIRCLE CIR_D5_TMP  UNITS=MM
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
Z      -5.150                                     -4.982      0.168
TP        RFS      0.400                 0.000      0.335      0.335      0.000 -------#-

## <E-F1> (x3)
DIM POS41= LOCATION OF CIRCLE CIR_D4.955_1  UNITS=MM
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
D       4.955      0.029     -0.029      4.980      0.025      0.000 --------#

DIM POS42= LOCATION OF CIRCLE CIR_D4.955_2  UNITS=MM
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
D       4.955      0.029     -0.029      4.982      0.027      0.000 --------#

DIM POS43= LOCATION OF CIRCLE CIR_D4.955_3  UNITS=MM
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
D       4.955      0.029     -0.029      4.989      0.034      0.005 -------->

## <E-F5>
DIM POS44= POSITION OF CIRCLE CIR_D4.955_2  UNITS=MM
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
X      32.050                                     32.066      0.016
TP        RFS      0.120                 0.000      0.033      0.033      0.000 --#------

## <E-F6>
DIM PERP5= PERPENDICULARITY OF LINE LIN_C,RFS TO PLANE PLN_K,RFS EXTENDLENGTH=0.000  UNITS=MM
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
M       0.000      0.200      0.000      0.075      0.075      0.000 ---#-----

## <E-F2>
DIM POS45= LOCATION OF CIRCLE CIR_D5.15  UNITS=MM
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
D       5.150      0.050     -0.050      5.174      0.024      0.000 ------#--

## <E-F7>
DIM CONCEN9= CONCENTRICITY FROM CIRCLE CIR_D5.15 TO LINE LIN_C  UNITS=MM
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
M       0.000      0.100      0.000      0.027      0.027      0.000 --#------
```

```
### Section view N-N
## <N-F8>
DIM POS46= POSITION OF PLANE PLN_L  UNITS=MM
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
Z      -1.600                                      -1.603     -0.003
TP        RFS      0.300                 0.000      0.005      0.005      0.000 #--------

## S1 ##
## <N-V4> (x2)
DIM POS47= LOCATION OF CIRCLE CIR_D3.7_L1_1  UNITS=MM
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
D        3.200      0.050     -0.050      3.225      0.025      0.000 ------#--

DIM POS48= LOCATION OF CIRCLE CIR_D3.7_L1_2  UNITS=MM
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
D        3.200      0.050     -0.050      3.234      0.034      0.000 -------#-

## <N-V7> (x2)
DIM POS49= POSITION OF CIRCLE CIR_D3.7_L1_1  UNITS=MM
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
PR     20.400                                      20.426      0.026
PA     75.000                                      75.182      0.182
TP        RFS      0.200                 0.000      0.140      0.140      0.000 ------#--

DIM POS50= POSITION OF CIRCLE CIR_D3.7_L1_2  UNITS=MM
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
PR     20.400                                      20.341     -0.059
PA     75.000                                      75.147      0.147
TP        RFS      0.200                 0.000      0.158      0.158      0.000 -------#-

## S2 ##
## <N-V4> (x2)
DIM POS51= LOCATION OF CIRCLE CIR_D3.7_L2_1  UNITS=MM
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
D        3.200      0.050     -0.050      3.201      0.001      0.000 ----#----

DIM POS52= LOCATION OF CIRCLE CIR_D3.7_L2_2  UNITS=MM
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
D        3.200      0.050     -0.050      3.198     -0.002      0.000 ----#----

## <N-V7> (x2)
DIM POS53= POSITION OF CIRCLE CIR_D3.7_L2_1  UNITS=MM
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
PR     20.400                                      20.424      0.024
PA    -90.000                                     -90.121     -0.121
TP        RFS      0.200                 0.000      0.099      0.099      0.000 ----#----

DIM POS54= POSITION OF CIRCLE CIR_D3.7_L2_2  UNITS=MM
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
PR     20.400                                      20.371     -0.029
PA    -90.000                                     -90.095     -0.095
TP        RFS      0.200                 0.000      0.089      0.089      0.000 ---#-----


### Back view (J7)
## <V-F2>
DIM POS56= LOCATION OF CIRCLE CIR_D4.98  UNITS=MM
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
D        4.980      0.050     -0.050      4.978     -0.002      0.000 ----#----

## <V-F12>
DIM POS55= POSITION OF POINT PNT_D  UNITS=MM
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
PR     52.500                                      52.475     -0.025
PA     64.900                                      64.809     -0.091
TP        RFS      0.200                 0.000      0.174      0.174      0.000 -------#-
```

```
### Detail P
## <P-V4> (x3)
## 49.3 mm from plane L
DIM POS57= LOCATION OF CIRCLE CIR_D9.975_1  UNITS=MM
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
D        9.975      0.025     -0.025     10.034      0.059      0.034 -------->

## 50.3 mm from plane L
DIM POS58= LOCATION OF CIRCLE CIR_D9.975_2  UNITS=MM
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
D        9.975      0.025     -0.025     10.023      0.048      0.023 -------->

## 51.3 mm from plane L
DIM POS59= LOCATION OF CIRCLE CIR_D9.975_3  UNITS=MM
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
D        9.975      0.025     -0.025     10.000      0.025      0.000 --------#

## <P-V4> cylinder (GX)
DIM POS60= LOCATION OF CYLINDER CYL_D9.975_GX  UNITS=MM
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
D        9.975      0.025     -0.025     10.000      0.025      0.000 --------#

## <P-F1>
DIM POS61= LOCATION OF CIRCLE CIR_D11.1  UNITS=MM
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
D       11.100      0.150     -0.150     11.177      0.077      0.000 ------#--


### Section view L-L
## <L-V3>
DIM POS62= LOCATION OF CIRCLE CIR_D34.1  UNITS=MM
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
D       34.100      0.050     -0.050     34.118      0.018      0.000 ------#--

## <L-V13>
DIM POS63= POSITION OF LINE LIN_E  UNITS=MM
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
X      24.100                                     24.091     -0.009
TP        RFS      0.100                 0.000      0.017      0.017      0.000 -#-------

## <L-F15>
DIM POS64= POSITION OF LINE LIN_E  UNITS=MM
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
X      24.100                                     24.091     -0.009
Y       0.000                                     -0.003     -0.003
TP        RFS      0.100                 0.000      0.018      0.018      0.000 -#-------

## <L-F14>
DIM PERP6= PERPENDICULARITY OF LINE LIN_E,RFS TO PLANE PLN_A,RFS EXTENDLENGTH=0.000  UNITS=MM
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
M        0.000      0.150      0.000      0.023      0.023      0.000 -#-------

## <L-F20>
DIM RETTIL2= STRAIGHTNESS OF LINE LIN_CZ_E  UNITS=MM
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
M        0.000      0.100      0.000      0.006      0.006      0.000 #--------

## <L-F5>
DIM POS68= LOCATION OF CIRCLE CIR_D31.9  UNITS=MM
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
D       31.900      0.100     -0.100     32.143      0.243      0.143 -------->

## <L-F16>
DIM CONCEN10= CONCENTRICITY FROM CIRCLE CIR_D31.9 TO CIRCLE CIR_D34.1  UNITS=MM
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
M        0.000      0.100      0.000      0.111      0.111      0.011 -------->
```

```
## <L-F17>
DIM POS65= POSITION OF PLANE PLN_47.4  UNITS=MM
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
Z     -47.400                                     -47.379      0.021
TP        RFS      0.120                 0.000      0.041      0.041      0.000 ---#-----

## <L-F8>
DIM POS66= POSITION OF PLANE PLN_46.65  UNITS=MM
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
Z     -46.650                                     -46.629      0.021
TP        RFS      0.200                 0.000      0.043      0.043      0.000 -#-------

## <L-F1>
DIM POS67= LOCATION OF POINT PNT_D54.3  UNITS=MM
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
Z       -8.300      0.300     -0.300     -8.320     -0.020      0.000 ----#----


### Detail H
## <H-F7> (x3)
DIM POS69= POSITION OF POINT PNT_0.9_1  UNITS=MM
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
Y       0.900                                       0.961      0.061
TP        RFS      0.300                 0.000      0.123      0.123      0.000 ---#-----

DIM POS70= POSITION OF POINT PNT_0.9_2  UNITS=MM
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
Y       0.900                                       0.963      0.063
TP        RFS      0.300                 0.000      0.125      0.125      0.000 ---#-----

DIM POS71= POSITION OF POINT PNT_0.9_3  UNITS=MM
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
Y       0.900                                       0.955      0.055
TP        RFS      0.300                 0.000      0.109      0.109      0.000 ---#-----

## <H-F8> (x2)
DIM POS73= LOCATION OF POINT R19.5_2  UNITS=MM
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
PR      19.500      0.100     -0.100     19.754      0.254      0.154 -------->

DIM POS74= LOCATION OF POINT R19.5_1  UNITS=MM
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
PR      19.500      0.100     -0.100     19.743      0.243      0.143 -------->

## <H-F10> (x4)
DIM POS75= LOCATION OF POINT R21.5_1  UNITS=MM
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
PR      21.500      0.100     -0.100     21.740      0.240      0.140 -------->

DIM POS76= LOCATION OF POINT R21.5_2  UNITS=MM
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
PR      21.500      0.100     -0.100     21.825      0.325      0.225 -------->

DIM POS77= LOCATION OF POINT R21.5_3  UNITS=MM
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
PR      21.500      0.100     -0.100     21.868      0.368      0.268 -------->

DIM POS78= LOCATION OF POINT R21.5_4  UNITS=MM
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
PR      21.500      0.100     -0.100     21.850      0.350      0.250 -------->

## <H-F5> (x7)
DIM POS79= POSITION OF POINT 0.94_1  UNITS=MM
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
Y       0.000                                      -0.133     -0.133
TP        RFS      0.300                 0.000      0.265      0.265      0.000 -------#-
```

```
DIM POS80= POSITION OF POINT 0.94_2  UNITS=MM
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
Y       0.000                                      -0.131     -0.131
TP        RFS      0.300                 0.000       0.262      0.262      0.000 -------#-

DIM POS81= POSITION OF POINT 0.94_3  UNITS=MM
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
Y       0.000                                      -0.132     -0.132
TP        RFS      0.300                 0.000       0.264      0.264      0.000 -------#-

DIM POS82= POSITION OF POINT 0.94_4  UNITS=MM
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
Y       0.000                                      -0.128     -0.128
TP        RFS      0.300                 0.000       0.256      0.256      0.000 -------#-

DIM POS83= POSITION OF POINT 0.94_5  UNITS=MM
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
Y       0.000                                      -0.129     -0.129
TP        RFS      0.300                 0.000       0.259      0.259      0.000 -------#-

DIM POS84= POSITION OF POINT 0.94_6  UNITS=MM
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
Y       0.000                                      -0.142     -0.142
TP        RFS      0.300                 0.000       0.285      0.285      0.000 --------#

DIM POS85= POSITION OF POINT 0.94_7  UNITS=MM
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
Y       0.000                                      -0.153     -0.153
TP        RFS      0.300                 0.000       0.306      0.306      0.006 -------->

## <H-F6> (x5)
DIM POS86= POSITION OF POINT 0_1  UNITS=MM
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
Y       0.000                                       0.052      0.052
TP        RFS      0.300                 0.000       0.104      0.104      0.000 ---#-----

DIM POS87= POSITION OF POINT 0_2  UNITS=MM
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
Y       0.000                                       0.058      0.058
TP        RFS      0.300                 0.000       0.117      0.117      0.000 ---#-----

DIM POS88= POSITION OF POINT 0_3  UNITS=MM
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
Y       0.000                                       0.058      0.058
TP        RFS      0.300                 0.000       0.117      0.117      0.000 ---#-----

DIM POS89= POSITION OF POINT 0_4  UNITS=MM
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
Y       0.000                                       0.059      0.059
TP        RFS      0.300                 0.000       0.117      0.117      0.000 ---#-----

DIM POS90= POSITION OF POINT 0_5  UNITS=MM
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
Y       0.000                                       0.062      0.062
TP        RFS      0.300                 0.000       0.124      0.124      0.000 ---#-----


### Sector view M-M
## <M-F2> (x3)
DIM POS91= LOCATION OF POINT R11.15_1  UNITS=MM
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
PR      11.150      0.150     -0.150     11.114     -0.036      0.000 ---#-----

DIM POS92= LOCATION OF POINT R11.15_2  UNITS=MM
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
PR      11.150      0.150     -0.150     11.124     -0.026      0.000 ---#-----

DIM POS93= LOCATION OF POINT R11.15_3  UNITS=MM
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
PR      11.150      0.150     -0.150     11.125     -0.025      0.000 ---#-----
```

```
## <M-F4>
DIM POS170= LOCATION OF CIRCLE CIR_D30.18  UNITS=MM
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
D       30.180      0.150     -0.150     30.308      0.128      0.000 --------#

## <M-F5>
DIM POS169= POSITION OF CIRCLE CIR_D30.18  UNITS=MM
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
X       0.000                                     -0.021     -0.021
Y       0.000                                      0.006      0.006
TP        RFS      0.200                 0.000      0.044      0.044      0.000 -#-------


### Detail AG
## <AG-F1>
DIM DIST2= 2D DISTANCE FROM POINT PNT_16.1_2 TO POINT PNT_16.1_1 PAR TO POINT PNT_16.1_1,NO_RADIUS  UNIT
S=MM
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
M       16.100      0.200     -0.200     16.464      0.364      0.164 -------->

## <AG-F2>
DIM POS114= LOCATION OF POINT PNT_16.1_MID  UNITS=MM
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
Y        0.000      0.050     -0.050     -0.037     -0.037      0.000 -#-------
```

```
### AFTER WELDING ###  according to drawing V433770_001 Rev.A
### Concentricity of nozzle
## Inner diameter Ø48 (x3)
DIM CONCEN11= CONCENTRICITY FROM CIRCLE CIR_D48_1 TO CIRCLE CIR_D48.8_GX_2_F  UNITS=MM
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
M        0.000      0.050      0.000      0.217      0.217      0.167 -------->

DIM CONCEN12= CONCENTRICITY FROM CIRCLE CIR_D48_2 TO CIRCLE CIR_D48.8_GX_2_F  UNITS=MM
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
M        0.000      0.050      0.000      0.295      0.295      0.245 -------->

DIM CONCEN13= CONCENTRICITY FROM CIRCLE CIR_D48_3 TO CIRCLE CIR_D48.8_GX_2_F  UNITS=MM
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
M        0.000      0.050      0.000      0.254      0.254      0.204 -------->

## Outer diameter ø55
DIM CONCEN14= CONCENTRICITY FROM CIRCLE CIR_D55 TO CIRCLE CIR_D48.8_GX_2_F  UNITS=MM
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
M        0.000      0.050      0.000      0.449      0.449      0.399 -------->
```

```
### Sector view K-K
## <K-F5>
# CH1
DIM POS115= POSITION OF POINT PNT_CH_1_4  UNITS=MM
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
Z      -5.800                                       -5.823     -0.023
TP        RFS      0.400                 0.000      0.046      0.046      0.000 -#-------

DIM POS116= POSITION OF POINT PNT_CH_1_5  UNITS=MM
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
Z      -5.800                                       -5.806     -0.006
TP        RFS      0.400                 0.000      0.012      0.012      0.000 #--------

DIM POS117= POSITION OF POINT PNT_CH_1_6  UNITS=MM
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
Z      -5.800                                       -5.812     -0.012
TP        RFS      0.400                 0.000      0.025      0.025      0.000 #--------

# CH2
DIM POS118= POSITION OF POINT PNT_CH_2_4  UNITS=MM
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
Z      -5.800                                       -5.788      0.012
TP        RFS      0.400                 0.000      0.024      0.024      0.000 #--------

DIM POS119= POSITION OF POINT PNT_CH_2_5  UNITS=MM
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
Z      -5.800                                       -5.789      0.011
TP        RFS      0.400                 0.000      0.023      0.023      0.000 #--------

DIM POS120= POSITION OF POINT PNT_CH_2_6  UNITS=MM
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
Z      -5.800                                       -5.793      0.007
TP        RFS      0.400                 0.000      0.014      0.014      0.000 #--------

# CH3
DIM POS122= POSITION OF POINT PNT_CH_3_4  UNITS=MM
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
Z      -5.800                                       -5.809     -0.009
TP        RFS      0.400                 0.000      0.019      0.019      0.000 #--------

DIM POS123= POSITION OF POINT PNT_CH_3_5  UNITS=MM
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
Z      -5.800                                       -5.808     -0.008
TP        RFS      0.400                 0.000      0.015      0.015      0.000 #--------

DIM POS121= POSITION OF POINT PNT_CH_3_6  UNITS=MM
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
Z      -5.800                                       -5.808     -0.008
TP        RFS      0.400                 0.000      0.015      0.015      0.000 #--------

# CH4
DIM POS124= POSITION OF POINT PNT_CH_4_4  UNITS=MM
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
Z      -5.800                                       -5.750      0.050
TP        RFS      0.400                 0.000      0.101      0.101      0.000 --#------

DIM POS125= POSITION OF POINT PNT_CH_4_5  UNITS=MM
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
Z      -5.800                                       -5.731      0.069
TP        RFS      0.400                 0.000      0.139      0.139      0.000 ---#-----

DIM POS126= POSITION OF POINT PNT_CH_4_6  UNITS=MM
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
Z      -5.800                                       -5.723      0.077
TP        RFS      0.400                 0.000      0.154      0.154      0.000 ---#-----
```

```
# CH5
DIM POS127= POSITION OF POINT PNT_CH_5_4  UNITS=MM
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
Z      -5.800                                      -5.772      0.028
TP        RFS      0.400                 0.000      0.057      0.057      0.000 -#-------

DIM POS128= POSITION OF POINT PNT_CH_5_5  UNITS=MM
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
Z      -5.800                                      -5.754      0.046
TP        RFS      0.400                 0.000      0.092      0.092      0.000 --#------

DIM POS129= POSITION OF POINT PNT_CH_5_6  UNITS=MM
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
Z      -5.800                                      -5.742      0.058
TP        RFS      0.400                 0.000      0.117      0.117      0.000 --#------

# CH6
DIM POS130= POSITION OF POINT PNT_CH_6_4  UNITS=MM
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
Z      -5.800                                      -5.829     -0.029
TP        RFS      0.400                 0.000      0.058      0.058      0.000 -#-------

DIM POS131= POSITION OF POINT PNT_CH_6_5  UNITS=MM
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
Z      -5.800                                      -5.839     -0.039
TP        RFS      0.400                 0.000      0.078      0.078      0.000 -#-------

DIM POS132= POSITION OF POINT PNT_CH_6_6  UNITS=MM
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
Z      -5.800                                      -5.864     -0.064
TP        RFS      0.400                 0.000      0.128      0.128      0.000 --#------

## <K-F7>
# CH1
DIM POS133= POSITION OF POINT PNT_CH_1_1  UNITS=MM
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
Y     -43.100                                     -43.152     -0.052
TP        RFS      0.100                 0.000      0.104      0.104      0.004 -------->

DIM POS134= POSITION OF POINT PNT_CH_1_2  UNITS=MM
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
Y     -43.100                                     -43.152     -0.052
TP        RFS      0.100                 0.000      0.103      0.103      0.003 -------->

DIM POS135= POSITION OF POINT PNT_CH_1_3  UNITS=MM
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
Y     -43.100                                     -43.152     -0.052
TP        RFS      0.100                 0.000      0.103      0.103      0.003 -------->

# CH2
DIM POS136= POSITION OF POINT PNT_CH_2_1  UNITS=MM
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
Y     -31.400                                     -31.332      0.068
TP        RFS      0.100                 0.000      0.136      0.136      0.036 -------->

DIM POS137= POSITION OF POINT PNT_CH_2_2  UNITS=MM
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
Y     -31.400                                     -31.343      0.057
TP        RFS      0.100                 0.000      0.114      0.114      0.014 -------->

DIM POS138= POSITION OF POINT PNT_CH_2_3  UNITS=MM
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
Y     -31.400                                     -31.357      0.043
TP        RFS      0.100                 0.000      0.086      0.086      0.000 -------#-

# CH3
DIM POS139= POSITION OF POINT PNT_CH_3_1  UNITS=MM
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
Y     -31.400                                     -31.302      0.098
TP        RFS      0.100                 0.000      0.195      0.195      0.095 -------->
```

```
DIM POS140= POSITION OF POINT PNT_CH_3_2  UNITS=MM
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
Y     -31.400                                     -31.281      0.119
TP        RFS      0.100                 0.000      0.238      0.238      0.138 -------->

DIM POS141= POSITION OF POINT PNT_CH_3_3  UNITS=MM
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
Y     -31.400                                     -31.270      0.130
TP        RFS      0.100                 0.000      0.260      0.260      0.160 -------->

# CH4
DIM POS142= POSITION OF POINT PNT_CH_4_1  UNITS=MM
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
Y      61.900                                      61.431     -0.469
TP        RFS      0.100                 0.000      0.938      0.938      0.838 -------->

DIM POS143= POSITION OF POINT PNT_CH_4_2  UNITS=MM
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
Y      61.900                                      61.423     -0.477
TP        RFS      0.100                 0.000      0.954      0.954      0.854 -------->

DIM POS144= POSITION OF POINT PNT_CH_4_3  UNITS=MM
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
Y      61.900                                      61.427     -0.473
TP        RFS      0.100                 0.000      0.946      0.946      0.846 -------->

# CH5
DIM POS145= POSITION OF POINT PNT_CH_5_1  UNITS=MM
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
Y      45.700                                      45.858      0.158
TP        RFS      0.100                 0.000      0.316      0.316      0.216 -------->

DIM POS146= POSITION OF POINT PNT_CH_5_2  UNITS=MM
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
Y      45.700                                      45.828      0.128
TP        RFS      0.100                 0.000      0.255      0.255      0.155 -------->

DIM POS147= POSITION OF POINT PNT_CH_5_3  UNITS=MM
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
Y      45.700                                      45.811      0.111
TP        RFS      0.100                 0.000      0.222      0.222      0.122 -------->

# CH6
DIM POS148= POSITION OF POINT PNT_CH_6_1  UNITS=MM
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
Y      45.700                                      45.621     -0.079
TP        RFS      0.100                 0.000      0.158      0.158      0.058 -------->

DIM POS149= POSITION OF POINT PNT_CH_6_2  UNITS=MM
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
Y      45.700                                      45.653     -0.047
TP        RFS      0.100                 0.000      0.094      0.094      0.000 --------#

DIM POS150= POSITION OF POINT PNT_CH_6_3  UNITS=MM
AX    NOMINAL       +TOL       -TOL      BONUS       MEAS        DEV     OUTTOL
Y      45.700                                      45.686     -0.014
TP        RFS      0.100                 0.000      0.028      0.028      0.000 --#------
```

```
### Zarys profilu powierzchni w NQR
### <S-24> (x18)
DIM POS151= LOCATION OF POINT PNT_R1  UNITS=MM
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
PR       9.000      2.000      0.000      9.191      0.191      0.000 #--------

DIM POS152= LOCATION OF POINT PNT_R2  UNITS=MM
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
PR       9.000      2.000      0.000      9.128      0.128      0.000 #--------

DIM POS153= LOCATION OF POINT PNT_R3  UNITS=MM
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
PR       9.000      2.000      0.000      9.080      0.080      0.000 #--------

DIM POS154= LOCATION OF POINT PNT_R4  UNITS=MM
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
PR       9.000      2.000      0.000      9.041      0.041      0.000 #--------

DIM POS155= LOCATION OF POINT PNT_R5  UNITS=MM
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
PR       9.000      2.000      0.000      9.000      0.000      0.000 #--------

DIM POS156= LOCATION OF POINT PNT_R6  UNITS=MM
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
PR       9.000      2.000      0.000      8.982     -0.018      0.018 <--------

DIM POS157= LOCATION OF POINT PNT_R7  UNITS=MM
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
PR       9.000      2.000      0.000      8.980     -0.020      0.020 <--------

DIM POS158= LOCATION OF POINT PNT_R8  UNITS=MM
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
PR       9.000      2.000      0.000      8.987     -0.013      0.013 <--------

DIM POS159= LOCATION OF POINT PNT_R9  UNITS=MM
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
PR       9.000      2.000      0.000      9.012      0.012      0.000 #--------

DIM POS160= LOCATION OF POINT PNT_R10  UNITS=MM
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
PR       9.000      2.000      0.000      9.000      0.000      0.000 #--------

DIM POS161= LOCATION OF POINT PNT_R11  UNITS=MM
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
PR       9.000      2.000      0.000      8.978     -0.022      0.022 <--------

DIM POS162= LOCATION OF POINT PNT_R12  UNITS=MM
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
PR       9.000      2.000      0.000      8.973     -0.027      0.027 <--------

DIM POS163= LOCATION OF POINT PNT_R13  UNITS=MM
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
PR       9.000      2.000      0.000      8.986     -0.014      0.014 <--------

DIM POS164= LOCATION OF POINT PNT_R14  UNITS=MM
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
PR       9.000      2.000      0.000      9.010      0.010      0.000 #--------

DIM POS165= LOCATION OF POINT PNT_R15  UNITS=MM
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
PR       9.000      2.000      0.000      9.051      0.051      0.000 #--------

DIM POS166= LOCATION OF POINT PNT_R16  UNITS=MM
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
PR       9.000      2.000      0.000      8.986     -0.014      0.014 <--------

DIM POS167= LOCATION OF POINT PNT_R17  UNITS=MM
AX    NOMINAL       +TOL       -TOL       MEAS        DEV     OUTTOL
PR       9.000      2.000      0.000      8.970     -0.030      0.030 <--------
```

DIM POS168= LOCATION OF POINT PNT_R18 UNITS=MM

AX	NOMINAL	+TOL	-TOL	MEAS	DEV	OUTTOL	
PR	9.000	2.000	0.000	8.971	-0.029	0.029	<--------