


Sustained latency on the MacBook Air M4 — every 15-minute run



Thermal start decides two of these verdicts: hbb-l@320 and hbb-s@320 each breach when preheated and hold from cold. The two gaps agree to within 0.2 ms (+1.25 and +1.45), so the preheating penalty looks like a stable property of the machine rather than a per-model quirk.