

CAR Information

CAR Number	PSC-2026-025	Status	PIC Accepted
Vessel	—	Target Date	16 Feb 2026
Inspection Type	PSC	Inspection Date	09 Feb 2026
Port	Tokyo	Created	09 Feb 2026 11:39

Deficiency Details

Deficiency Code	10103
Description	Radar equipment found non-operational during inspection. Display unit showing intermittent signal loss requiring immediate repair and calibration.
Action Code	16
Cleared	No

Root Cause Analysis

CLC Codes:

#	CLC Code / Custom Cause
1	CLC Item 2-1

Root Cause Summary:

The radar display unit failure was caused by use of defective equipment that had exceeded its recommended service life. Regular maintenance was not performed per the planned maintenance schedule, leading to gradual signal degradation and eventual failure during inspection.

Corrective Actions

#	Type	Description	Due Date	Completed	Status
1	Immediate	Replace faulty radar display unit and perform signal calibration	—	No	Pending
2	Long Term	Implement preventive maintenance schedule for all navigation equipment including quarterly calibration checks	—	No	Pending

Evidence

#	Type	File Name	Description	Uploaded
1	Before	test_before.jpg	Photo showing faulty radar display with intermittent signal loss before repair	09 Feb 2026 17:37
2	After	test_after.jpg	Photo showing radar display operating normally after replacement and calibration	09 Feb 2026 17:38

Review / Approval History

Date	Event	Performed By
09 Feb 2026 17:51	CAR PSC-2026-025 accepted by PIC	Alice J.
09 Feb 2026 17:48	CAR PSC-2026-025 submitted for review	John Smith
09 Feb 2026 17:38	AFTER evidence uploaded for CAR PSC-2026-025	John Smith
09 Feb 2026 17:37	BEFORE evidence uploaded for CAR PSC-2026-025	John Smith
09 Feb 2026 11:39	CAR PSC-2026-025 created for deficiency 10103	John Smith