PRODUCT PERFORMANCE FEEDBACK REPORT



IFAD MOTORS LTD **Head Office**

DMS NO:

3272

IFAD Tower Plot-7(New), Teigoan Industrial Area, Dhaka-1208

If AD Tower, Flot 7(New), Telaculi III addition to the						
Ref.No:	Dhaka/May/25	F.R SI NO#	25	Date:	19.05.2021	
Zone Name:	Dhaka 1	Engineer Name:	Engineer Name: Milon Hossain		Mchanic Name: Md.Yousuf	

Approved by: Prabir Biswas (Head of Service, Spare Parts & Production)

						T		
Customer Name:	Akter Hossain				Mobile No:	01883-1805	1883-180546	
Address:	Sirajdikhan, Mun	shiganj			Dealer Name:	Mayer Dowa Tvs Center		
Customer Compla	iin:-	CH NO Full #	I NO Full # MD6M14CA3J4L09359		9359 /	Present Kms	5098	
Front Shockabsorber Oil Leakage		EN NO Full #	AK4LJ4893346		Model#	TVS King Deluxe		
		Sale Date #	19.12.2020					
		Date of Comp#	17.05.2021		1St PS Date 1st PS Kms			
		Date of Repair#						
Ÿ.		w. P	Free service information					
, a		1St Free Service 2nd		Free Service	3rd Free Service			
		Date	KMs	Date	KMs	Date	KMs	
		22.01.2021	1034	05.03.2023	3,019	17.05.2021	5098	

Observation:-


we checked &found that front Shockabsorber oil Leakage . .

Action Taken:- Require to replace this parts under warranty for your kind approval.

Failure Particular								
SL	Part NO.	Part Name	Qty	Vendor code	Approved	Rejected		
1	G4100180	SHOCK ABSORBER FRONT	1 /	/				

2 3 4 5

For Head Office Use **Failure Parts Photo** DMS Engineer **Head of Service**



3/05/2021

Alpha box