PRODUCT PERFORMANCE FEEDBACK REPORT

IFAD MOTORS LTD

Head Office

Ref.I	io: IML/My	mensingh 017		F.R SI NO#	17	Date:	17.08.20
Zone Nan	ie: Mymens	shing		[Ingineer Name	: Md Jahid Hasan	
Approved	y: Probir B	iswas (Head of Servi	e & Spare	Parts)			
		77 TO THE STATE OF					
ustomar Name	: Eusuf Al		1	1 1 19	Mobile No:	01713-151660	Olma spow service serv
ddress:	dress: Madhupur		Dealer Name:		Jerin Motors		
Customar Complain:-		CH NO Full #	MD6MI4CA6K4K00203				
ack shock absorber oil		EN NO Full#	/\K4KK4703673				
kage.		Sale Date #	04.06.20			Present Kms #	2739+
		Date of Comp#	1.7.08.20				TVS KING
		Date of Repair #	17.08.20	a			Deluxe
			***************************************	Free Cupon	service informa	ation	1
		1St Free Service		2nd Free Service		3rd Free Service	
		Date	KMs	Date	KMs	Date	KMs
		7.07.20	2739+				
		ock absorber replace		Back shock at	osorber oil likag	ge.	
					osorber oil likag	ge.	
tion Taken:-B	oth Back sho	ock absorber replace	Failure	Particular		e.	
tion Taken:-B	oth Back sho	ock absorber replace Part Nan	Failure	Particular Qty	Vendor code	Approved	Rejected
tion Taken:-B SL Pa 1 G20	oth Back sho	ock absorber replace	Failure	Particular			Rejected
tion Taken:-B L Pa 1 G20	oth Back sho	ock absorber replace Part Nan	Failure	Particular Qty			Rejected
tion Taken:-B SL Pa 1 G20 2	oth Back sho	ock absorber replace Part Nan	Failure	Particular Qty			Rejected
SL Pa 1 G20 2 3	oth Back sho	ock absorber replace Part Nan	Failure	Particular Qty			Rejected
Stion Taken:-B SL Pa 1 G20 2 3 4	oth Back sho	ock absorber replace Part Nan	Failure	Particular Qty			Rejected
tion Taken:-B SL Pa 1 G20 2 3 4	oth Back sho	ock absorber replace Part Nan	Failure	Particular Qty			Rejected
Stion Taken:-B SL Pa 1 G20 2 3	oth Back sho	ock absorber replace Part Nan	Failure	Particular Qty	Vendor code		Rejected