


PRODUCT PERFORMANCE FEEDBACK REPORT



DMS JOB NO

01761815902

IFAD TOWER, 07 Tejgaon I/A, Dhaka-1208.

27.10.2020 286 Date: F.R SI NO# Ref.No: Sylhet/Oct/27/286 Tisu Barua **Engineer Name:** Zone Name: Sylhet ,Sadar

Prabir Biswas, GM -Head of Service & Spare Parts. Approved by:

Sahab Uddin **Sustomar Name: Shahporan Motors** Dealer Name: Bishonath, Sylhet. Address: Present Kms # 7,953 MD6M14CA1K4K00528 CH NO Full # **Customar Complain:-**14.141 Tvs King Deluxe AK4KK4612795 Dil leakage from Front shock EN NO Full # Model# lpg 14 07.06.2020 Sale Date # ibsorber. 1st PS Kms 1St PS Date 22.10.2020 Date of Comp# No Date of Repair # Pending

> Free service information 3rd Free Service 2nd Free Service 1St Free Service **KMs** Date KMs Date **KMs** Date 30.08.2020 5360 3145 790 25.07.2020

Mobile No:

Obserbation:- We checked & found that front shock absorber Oil leakage

Action Taken:- Require to replace this parts under warranty for your approval.


29.06.2020

Failure Particular

SL	Part NO	Part Name	Qty_	Vendor code	Approved	Rejected
1	G4100180	Front shock absorber	$\left(\begin{array}{c}1\end{array}\right)$	Gabrial		
2		×				
2						
4				ONIN		
5				CO.7		
6				145		

Failure Parts Photo

For Head Office Use



Instroas Coltiforo

HOLL. Mami

Service Engineer IFAD MOTORS LTD