


PRODUCT PERFORMANCE FEEDBACK REPORT





IFAD MOTORS LTD **Head Office**

DMS IOB NO

IFAD TOWER .07 Teigaon I/A, Dhaka-1208.


		11/10/10/11	.,	9				
Ref.No:	June-233		<u>_</u>	F.R SI NO#	233	Date:	08.07.2020	
Zone Name:				Engineer Name:		Md.Pabel Sarker		
Approved by: Prabir Biswas, GM -Head of Service				& Spare Parts.				
					9			
Customar Name: Monir Hosen					Mobile No:	01817926261		
	Kuti-Cho	nowhmoni, Kosba, B. Baria.			Dealer Name:	Modina Motors		
Customar Comp	plain:-	CH NO Full #	MD6M14	CA8KA0022		Present Kms #	(2,500)	
Rear shock absorb		EN NO Full#	AK4KK45	A0022		Model #	Tvs King Deluxe	
2		Sale Date #	17.05.202	20 :			lpg	
		Date of Comp#	07.07.202	20		1St PS Date	1st PS Kms	
		Date of Repair #	07.07.202	20				
Free service information								
		1St Free Service		2nd Free Service		3rd Free Service		
de .		Date	KMs	Date	KMs	Date	KMs	
		17.06.2020	1100	07.07.2020				
Obserbation:- we	checked	&found that Rear	Shock Ab	sorber has rig	tht oil leakage &	nose.		

Action Taken:- Require to replace this parts under warranty for approval

	Failure Particular											
SL	Part NO	Part Name	Qty	Vendor code	Approved	Rejected						
1	G2090100	Rear Shock Absorber	(01 /	Gabrial	a a							
2		N N			(a) (a) (b) (c) (c) (c) (c) (c) (c) (c) (c) (c) (c							
3												
4												
5	4.				20							
6	A											

Failure Parts Photo

For Head Office Use



m8200