PRODUCT PERFORMANCE FEEDBACK REPORT IFAD MOTORS LTD DMS NO: **Head Office** 311 IFAD Tower, Plot-7(New), Tejgoan Industrial Area, Dhaka-1208 Ref.No: Mym-32 F.R SI NO# 32 Date: 15.02.2021 Zone Name: Mymensingh Engineer Name:Md Jahid Hasan Mchanic Name: Md Forhad Mia Approved by: Prabir Biswas (Head of Service, Spare Parts & Production) Customer Name: | Ifad Motors Ltd(Jerin Motors) Mobile No: 01714766147 Address: cecuya, Mymensingh Dealer Name: **Jerin Motors** Customer Complain:-CH NO Full # MD6M14CAXL4F00007 Present Km Steering coloum thred broken EN NO Full # AK4FL4202346 TVS King Duramax Model# Sale Date # 00.00.00 Date of Comp# 15.02.2021 1St PS Date 1st PS Kms Date of Repair# Pending N/A N/A Free service information 1St Free Service 2nd Free Service **3rd Free Service** Date **KMs** Date **KMs** Date 21.11.20 1679 Observation:-By Mechanic we checked and find that the steering coloum thred broken.

18893

KMs

Action Taken:- Please to be replace the Steering colom with steering coloum cone kit top & Bottom by new one under warranty.

<u>Failure Particular</u>								
SL	Part NO.	Part Name	Qty	Vendor code	Approved	Rejected		
1	G2150010	Steering coloum	1			,		
2	G5320510	Steering cone top	1					
3	G5320500	Steering cone bottom	1 1					
4		*						

Head of Service Engineer DMS On har hard and	<u>Failure Parts Photo</u>	For Head Office Use			
100 1 20 V		Head of Service	Engineer	DMS	
		Mangar 2021	Medoan	12/09/	