TVS

IFAD MOTORS LTD

PRODUCT RESPONMENCE FEADBACK REPORT

0MS 108 NO

IFAD				OTORS LTD d Office			2852	
		IFAD TOWER	,07 Tejg	aon I/A, DI	hako-1208.			
Ref.No: Habîgani/Nov/329			F.R SI NO#	329	Date:	21.11.2020		
Zone Name: Habiganj Zone			E	ngineer Name:	Md. Abdu	llah Al Zabed		
		vas (Head of Service	e & Spare P	Acres and a second control	3	Anna ay a samura da a a a a a a a a a a a a a a a a a	· · · · · · · · · · · · · · · · · · ·	
				w./				
Customar Name:	Md. Arjan	Miah -329	1	Mobile No:	01791481351			
Address:	Nasirnagar	r, Bì Badia			Dealer Name:	Shahjalal Au	utomobile 🔿	
Customar Complain:		CH NO Full # MD6M14		CA0J4A07952		The second secon	9840	
Front Shock absorber has broken.		EN NO Full #	Ak4AJ4723205		/	Model#	TVS King Deluxe CNG/LPG	
		Sale Date #	13.07.2020					
		Date of Comp#	17.11.2020			1St PS Date	1st PS Kms	
		Date of Repair #	17.11.2020					
				free se	rvice informatio	n		
		15t Free Service		2nd Free Service		3rd Free Service		
		Date	KMs	Date	KMs	Date	KMs	
		24.08.2020	1010	07.10.2020	3860	17.11.2020	9840	
ACHON TAKES IV	ew one from si	iuck absorber replai	/		**************************************			
-	Failure Pa				ticular Africa Africa			
St	Part NO Part Name		me	Qty	Vendor code	Approved	Rejected	
1	54100100 J	Front shock absorber			Gabriel 60000297 04 18 08	351		
2	-1 -1 -	<b></b>			<u> </u>			
3		\\\\						
4		<u> </u>						
5	**************************************							
6			mana ay e spaniana ay s			.1	_L	
` Failure Parts Photo					For Head Office Use			
				Secretario de la constante de		nas		

JI | I | Zo Zo

Ashammad Abdullah Al Zahed
Senior Service Engineer
IFAD MOTORS LTD.
Cell: 01701-227974

25/14/2020