PRODUCT PERFORMANCE FEEDBACK REPORT IFAD MOTORS LTD DMS NO: Head Office IFAD Tower, Plot-7(New), Tejgoan Industrial Area, Dhaka-1208 F.R SI NO# Date: 25.03.2021 Ref.No: March-277 Engineer Name: Md.Pabel Sarker Mchanic Name: Sumon Dali Zone Name: Cumilla Approved by: Prabir Biswas (Head of Service, Spare Parts & Production) Mobile No: 01310663917 Customer Name: Rabiul Hasan Akhaora, B.Baria Dealer Name: Modina Motors Address: MD6M14CA4K4KA0003 Customer Complain:-CH NO Full # Present Km 5432 -Front shock absorber oil leakage. EN NO Full # AK4KK45A0003 TVS King Deluxe Model# Sale Date # 03.09.2020 ~ Date of Comp# 25.03.2021 1St PS Date 1st PS Kms Date of Repair# Free service information 1St Free Service 2nd Free Service 3rd Free Service KMs Date KMs Date KMs Date 07.10.2020 07.01.2021 4,211 Observation:we checked &found that front shock absorber oil lekage. Action Taken:- Require to replace this parts under warranty for approval. Failure Particular Part NO. Approved Rejected SL Part Name Qty Vendor code G4100180 Front Shock Absorber 01 3 4 Failure Parts Photo For Head Office Use DMS Head of Service Engineer