

PRODUCT PERFORMANCE FEEDBACK REPORT



IFAD MOTORS LTD **Head Office**

DMS JOB NO

IFAD TOWER ,07 Tejgaon I/A, Dhaka-1208.

MOTORSUMITED	:	man I/A Dhaka-1208.	20.2020
	IFAD TOWER ,07 Tej	gaon I/A, Dhaka-1208.	Date: 10.08.2020
		F.R SI NO#	Tabeα
	iganj/August/314	Engineer Name:	
Zone Name: Ha	biganj Zone (Head of Service & Spa	re Parts)	
Approved by: Pra	biganj Zone bir Biswas (Head of Service & Spa	Factile No. 0	1704901179
		Mobile No: 0	- La Lamobile

Zone Name:	Haniga	1 of Sorvi	ice & Spare	Parts)			
Approved by:	Prabir Bi	swas (Head of Serv	ice di si			01704901179	
Дррготез.					Mobile No:	01704901173	- mobile
	Md. Wa	h Miah			Dealer Name:	Shahjalal Au	COMODITE
				2	Dealer Marries	Descent Kms #	2695
	Baniach	ong, Habiganj	MD6M14C	1214406830)	Present Kins	TVS KING DELUXE
Andress.		CLINO Full #	MD6W14C	7537130		Model#	CNG
Customar Compl	ann	EN NO Full #	AK4AJ4913			1	
Front Shock absorbe			22.06.2020			1St PS Date	1st PS Kms
1		Sale Date "	10.08.2020			150.15	
broken.		Date of Comp.		^			
		Date of Repair #	10.08.2020	<u> </u>	ervice information	on	
		Date		Free Se	S wise	3rd Fr	ee Service
		· · · · · · · · · · · · · · · · · · ·	rvice	2nd F	ree Service	Date	KMs
r		1St Free Se	I VICE	Date	KMs	- Butte	
		Date	KMs		0 2695		
		18.07.2020	970 ~	10.08.202	1009-100-0		
18.07.2020 the shaper has broken.							

Obserbation:- we checked & found that Front Shock absorber has broken.

Action Taken:- New one Front Shock absorber replaced.

Action ia	Kem 11-	•				3	
		Failure	Particular		Ammroyed	Rejected	જે.
	8		Qty	Vendor code	Approved		
- CI T	Part NO	Part Name		Gabrial	8-		
SL				(60000297)			. 2
	G2100010	Front shock absorbe	1	02.02.17 H		1	
	021000	(+				
1		V		20			4
2							
3	, 4 ₁		8	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1			
4				For H	lead Office Use		
				FOLI	icau Citt		

Failure Parts Photo

