PRODUCT PERFORMANCE FEEDBACK REPORT IFAD MOTORS LTD DMS NO: **Head Office** IFAD Tower, Plot-7(New), Tejgoan Industrial Area, Dhaka-1208 F.R SI NO 314 Date: 13/12/2020 Ref.No: Engineer Name: Md Farhad Hosse Mchanic Name: Md Faruk Zone Name: Chittagong Approved by: Prabir Biswas (Head of Service, Spare Parts & Production) Mobile No: **Customer Name:** Saifur Rahaman 01890857328 Dealer Name: **Ekota Motors** Address: Pancori, kagracori **Customer Complain:-**CH NO Full # **Present Kms** MD6M14LA5K4P00157 2456 Bad noise from rear **EN NO Full #** AK4PK4900163 Tvs king Deluxe Model# shockabsorber Sale Date # 10/14/2020 Date of Comp# 12/12/2020 1St PS Date 1st PS Kms Date of Repair# 12/12/2020 Free service information 1St Free Service 2nd Free Service **3rd Free Service** KMs Date **KMs** Date Date **KMs** 20/11/20 1024 Observation:-We Checked and found that Rear Shockabsørber oil leakage. Ministernaci Action Taken:- New one Rear shockabsorber Replace. **Failure Particular** SL Part NO. Part Name Vendor code **Approved** Rejected G2090100 SHOCK ABSORBER ASSY REAR 1 2 3 4 For Head Office Use Failure Parts Photo **Head of Service** Engineer **DMS** M182/2020