PRODUCT PERFORMANCE FEEDBACK REPORT IFAD MOTORS LTD DM8 NO: 3171 **Head Office** IFAD Tower, Plot-7(New), Tejgoan Industrial Area, Dhaka-1208 Ref.No: F.R SI NO#-320 25/2/2021 Engineer Name: Md Farhad H Mchanic Name: Faruk Zone Name: Chittagong (Kagracori) Approved by: Prabir Biswas (Head of Service, Spare Parts & Production) Received person :- Mosarof Hossen -01701204633 **Customer Name: Abdul Hamid** Mobile No: 01828877556 Address: Khagrachori Dealer Name: **Ekota Motors** Customer Complain:-CH NO Full # MD6M14CA2J4L08932 Present Kms # 9024 Noise from rear shockabsorber EN NO Full # AK4LJ4689818 **Tvs King Deluxe** Model# Sale Date # 20-Jul-20 Date of Comp# 24/2/2021 1St PS Date 1st PS Kms Date of Repair# 25/2/2021 Free service information 1St Free Service 2nd Free Service **3rd Free Service** Date **KMs** Date KMs Date **KMs** 2/8/2020 1045 25/9/21 4,240 10/12/2021 8670 / Observation:- Rear shockabsorber oil leakage. Action Taken:- New one Rear shockabsorber replace.

Failure Particular SL Part NO. Part Name Qty Vendor code **Approved** Rejected 1 Shockabsorber Assy Rear G2090100 Badve 2 3 4 **Failure Parts Photo**

Failure Parts Photo

Head of Service

Engineer

DMS

Analysis of Service Engineer

DMS