

## PRODUCT PERFORMANCE FEEDBACK REPORT





## IFAD MOTORS LTD Head Office

DMS No: 2557

IFAD TOWER, 07 Tejgaon I/A, Dhaka-1208.

| Ref.No:                          | Mym-20                             |                                |                   | F.R SI NO#       | Mym-20                        | Date:            | 26.09.20 |  |  |  |
|----------------------------------|------------------------------------|--------------------------------|-------------------|------------------|-------------------------------|------------------|----------|--|--|--|
|                                  | Mymenshing                         |                                |                   | E                | Engineer Name: Md Jahid Hasan |                  |          |  |  |  |
|                                  |                                    | was (Head of Servic            | e & S/Parts)      |                  |                               |                  | 7        |  |  |  |
|                                  |                                    |                                |                   |                  | _                             |                  |          |  |  |  |
| Customar Name:                   | Md Shoel Mia(Dealer Sadiya Motors) |                                |                   |                  | Mobile No:                    | 01714766147      |          |  |  |  |
| Address:                         | Mymensin                           | mensingh                       |                   |                  | Dealer Name:                  | Sadiya Motors    |          |  |  |  |
| Customar Complain:- CH NO Full # |                                    |                                | MD6M14CL6K4P00217 |                  |                               |                  |          |  |  |  |
| Bendix drive assy. has bad       |                                    | EN NO Full #                   | OL4PK4600178      |                  |                               |                  |          |  |  |  |
| sound.(Dealer complain)          |                                    | Sale Date #                    | 00.00.00          | PDI              | , su                          | Present Kms #    |          |  |  |  |
| •                                |                                    | Date of Comp#                  | 26.09.20          |                  | 99R                           |                  | TVS KING |  |  |  |
|                                  |                                    | Date of Repair #               | Pending           |                  | 4×#1                          |                  | Duramax  |  |  |  |
|                                  |                                    | Free Cupon service information |                   |                  |                               |                  |          |  |  |  |
|                                  |                                    | 1St Free Service               |                   | 2nd Free Service |                               | 3rd Free Service |          |  |  |  |
|                                  |                                    | Date                           | KMs               | Date             | KMs                           | Date             | KMs      |  |  |  |
|                                  |                                    |                                |                   |                  |                               |                  |          |  |  |  |

Observation: (By mechanic) We checked and found that Bendix drive assy. three teeth has broken.vehicle was not delivery for bendix drive assy.

Action Taken:Please to be replace the Bendix drive assy. by new one under warranty.

| Failure Particular |           |                    |     |   |  |          |  |  |  |  |
|--------------------|-----------|--------------------|-----|---|--|----------|--|--|--|--|
| SL                 | Part NO   | Part Name          | Qty | Vendor code   | Approved                               | Rejected |  |  |  |  |
| 1                  | G4320570  | Bendix Drive Assy. | 1   | South Control of the |  |          |  |  |  |  |
| 2                  | G 4060170 | Starter Motor ner  | 1   | TVS   |  |          |  |  |  |  |
| 3                  |           |                    |     |   |  | ,        |  |  |  |  |
| 4                  |           |                    |     | 1. N. P.  | ************************************** | *        |  |  |  |  |
| 5                  |           |                    |     | and a special control of the special control | 45 G                                   |          |  |  |  |  |
| 6                  |           | 9                  |     | process process   |  |          |  |  |  |  |
|                    |           |                    |     | al Land   |  |          |  |  |  |  |

Failure Parts Photo

For Head Office Use

Approval given by Debasish
Babu (Back page mail attached)
miswas

Ality Schar Stone