MOTORS INSTER

PRODUCT PERFORMANCE FEEDBACK REPORT OPS GYSLOM Problem IFAD MOTORS LTD



DMS NO:

3409

	Head C	(1)			
	IFAD Tower, Plot-7(New), To	ejgoan I	ndustrial Area	a, Dhaka-1	.208
Ref.No:	IML/Chapi/-02/01/22	F.R SI NO	Jan-01	Date:	02.01.22
Zone Name:	Rajshahi	Engineer N	ame:Safayet Hossain	Mchanic Nam	ne: Ujjal Hosen
Approved by:	Prabir Biswas (Head of Service, Spare Part	s & Produ	iction) Kaush	ik Sank	cere +000 IFAD GROU
Customer Name:	Nobin		Mobile No:	01601-342	402
Address:	Chapainawabganj		Dealer Name:	Friend Tra	ding

Customer Name:	Nobin			Mobile No:	01601-342402		
Address:	Chapainawabganj			Dealer Name:	Friend Trading		
Customer Complain:-		CH NO Full #	MD6M14CL3K4P00157		Present Km		
Radiator leakage causes coolant to		EN NO Full #	0L4PK4X00450		Model #	TVS King Duramax Plus	
leak out, causing the engine to overheat.		Sale Date #	9/10/2020				
		Date of Comp#	1/2/2022		1St PS Date	1st PS Kms	
		Date of Repair#		_			
		Free service information					
		1St Free Service 2nd		Free Service	3rd Free Service		
		Date	KMs	Date	KMs	Date	KMs
The state of the s	9			, , , , , , , , , , , , , , , , , , ,	and the second s		
Observation: We o	hearward that the						

Observation: We observed that there was a tube leak in the radiator of the vehicle and the coolant was coming out. The engine is overheating.So it should be replace undre warranty.

Action Taken:- Replace the defective parts.

Failure Parts Photo

Failure Particular							
SL	Part NO.	Part Name	Qty	Vendor code	Approved	Rejected	
1	G4181080	Radiator	1		1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	nejecteu .	
2						open.	
3		Allacione				a.	
4							
						Car.	

Failure Parts Photo	For Head Office Use				
	Head of Service	Engineer	, DMS		
	111122	Approved by Mail	Only Job sared		