## IFAD Ref.No: Mym-40 Zone Name: Mymensingh Approved by: Prabir Bisw

## PRODUCT PERFORMANCE FEEDBACK REPORT



## **Head Office**

IFAD MOTORS LTD

3212

nedd Ojjice

IFAD Tower, Plot-7(New), Tejgoan Industrial Area, Dhaka-1208

Ref.No: Mym-40

F.R SI NO# 40

Date: 23.02.21

Engineer Name: Md Jahid Hasan Mchanic Name: Md Forhad Mia

Approved by: Prabir Biswas (Head of Service, Spare Parts & Production)

Customer Name:	Md Azizul Haq			Mobile No:	1781257219		
Address:	Cecuya, Mymensingh	Dealer Name:			Jerin Motors		
<b>Customer Complai</b>	n:-	CH NO Full #	MD6M	114CL4K4P00	149	Present Kms # 6732	
Steering coloum lose		EN NO Full #	OL4PK4800457			TVS Kir	TVS King Duramax
		Sale Date #	29.10.2020			Model#	
		Date of Comp#	20.02.21			1St PS Date	1st PS Kms
		Date of Repair#	Pending			N/A	N/A
Free service information							
A CONTRACTOR OF THE CONTRACTOR		1St Free Service		2nd Free Service		3rd Free Service	
		Date	KMs	Date	KMs	Date	KMs
		26.11.2020	1198	30.12.20	2,543	27.01.21	5290

Observation:-We checked and found that the steering coloum lose .

Action Taken:- Please to be replace the steering coloum with steerint coloum cone kit top & bottom by new one under warranty.

Failure Particular						
SL	Part NO.	Part Name	Qty	Vendor code	Approved	Rejected
1	G2150010	Steering coloum	1			
		Steering coloum cone			2.96	
2	G5320510	kit top	1			
		Steering coloum cone				
3	G5320500	kit bottom	1		= 81	4
4			A			

Failure Parts Photo	For Head Office Use				
	Head of Service	Engineer	DMS		
	Babu Miswas  16/3/204	16/12/2004	Proposition of the Constitution of the Constit		