

Action Taken:- Please to be replace the steering coloum with steerint coloum cone kit top & bottom by new one under warranty.

Failure Particular								
SL	Part NO.	Part Name	Qty	Vendor code	Approved	Rejected		
1	G2150010	Steering coloum	1					
2 -	<del>Q5320510</del>	Steering coloum cone kit top	1_	V /W RO	1 0x 0	may my		
<u>3</u> 4	G5320500	Steering coloum cone kit bottom	1	9×60	0.			

Failure Parts Photo	For Head Office Use			
	Head of Service	Engineer	DMS	
	105/2091	24105/2021	States States	