

PRODUCT PERFORMANCE FEEDBACK REPORT





IFAD MOTORS LTD Head Office

DMS JOB NO: 2132 DMS Complete

	Ref.No:	IML/lal/Ju	ne /2020/08/06		F.R SI NO#	10.00	Date:	6/8/2020
Zone Name: Nilphama		ri.		Engineer Name		: Md.Kayem Uddin		
Ар	proved by:	Probir Bisv	was (Head of Servi	ice ,S/Parts	& Production)		5 52 4	
						× - 230	7.	
ustomar Name: Md.Eyashin A		Ali			Mobile No:	01701623836		
ddress: Nilphama			1	ı	Dealer Name	: Habib Enterpri	bib Enterprise.	
Customar Complain:-			CH NO Full #	MD6M14LA6K4P00040				ed
peedometer Assy doesn't			EN NO Full #	AK4PK4500068				
ork.			Sale Date #	21/07/202			Present Kms #	9
			Date of Comp#	21/07/20		2.0 h	Model #	TVS KING
			Date of Repair #	21/07/20				Deluxe
						service inform		
			1St Free Se	rvice	2nd Fr	ee Service	· 3rd Fre	e Service
			Date	KMs	Date	KMs	Date	KMs
	8		21/07/2020	9			gi e Pagira	<u></u>
	y repair it. S	Whal	he vehicles and fou	feen	/e /] [/	ringum.	'
ready	y repair it. S	Ohal	s change under wa	rranty.	e Particular		læder	St work
ready	y repair it. S Part	NO	s change under wa	Failure	Particular Qty	Vendor code	,, ,	'
SL 1	y repair it. S	NO	s change under wa	Failure	e Particular	Vendor code	læder	St work
SL 1 2	y repair it. S Part	NO	s change under wa	Failure	Particular Qty	Vendor code	læder	St work
SL 1 2 3	y repair it. S Part	NO	s change under wa	Failure	Particular Qty	Vendor code	læder	St work
SL 1 2 3 4	y repair it. S Part	NO	s change under wa	Failure	Particular Qty	Vendor code	læder	St work
SL 1 2 3 4 5 5	y repair it. S Part	NO	s change under wa	Failure	Particular Qty	Vendor code	læder	St work
SL 1 2 3 4	y repair it. S Part	NO	s change under wa	Failure	Particular Qty	Vendor code	læder	St work
SL 1 2 3 4 5	y repair it. S Part	NO 0150	s change under wa	Failure	Particular Qty	Vendor code TVS	læder	St work
SL 1 2 3 4 5	y repair it. S Part	NO 0150	Part Nai Speedomete	Failure	Particular Qty	Vendor code TVS	Approved	St work
SL 1 2 3 4 5	y repair it. S Part	NO 0150	Part Nai Speedomete	Failure	Particular Qty	Vendor code TVS	Approved	St work
SL 1 2 3 4 5	y repair it. S Part	NO 0150	Part Nai Speedomete	Failure	Particular Qty	Vendor code TVS	Approved ead Office Use	Rejected
SL 1 2 3 4 5	y repair it. S Part	NO 0150	Part Nai Speedomete	Failure	Particular Qty	Vendor code TVS	Approved ead Office Use	Rejected
SL 1 2 3 4 5	y repair it. S Part	NO 0150	Part Nai Speedomete	Failure	Particular Qty	Vendor code TVS	Approved ead Office Use	Rejected
SL 1 2 3 4 5	y repair it. S Part	NO 0150	Part Nai Speedomete	Failure	Particular Qty	Vendor code TVS	Approved ead Office Use	Rejected
SL 1 2 3 4 5	y repair it. S Part	NO 0150	Part Nai Speedomete	Failure	Particular Qty	Vendor code TVS	Approved ead Office Use	Rejected
SL 1 2 3 4 5	y repair it. S Part	NO 0150	Part Nai Speedomete	Failure	Particular Qty	Vendor code TVS	Approved	Rejected
SL 1 2 3 4 5	y repair it. S Part	NO 0150	Part Nai Speedomete	Failure	Particular Qty	Vendor code TVS	Approved ead Office Use	Rejected

Billing