## TVS

## PRODUCT PERFORMANCE FEEDBACK REPORT

FAD

## IFAD MOTORS LTD Head Office

DMS DO: DMS 10B NO 2725

IFAD TOWER, 07 Teigaon I/A, Dhako-1208.

	***************************************	ITAD TOVEL	, or rejyuon iya, bi	10KU-12U0.			
Ref.No:	Habiganj/C	oct/325	F.R SI NO#	325	Date:	27.10.2020	
Zone Name:	Habiganj Zone		E	Engineer Name:		Md. Abdullah Al Zabed	
Approved by:	Prabir Bisw	as (Head of Service	e & Spare Parts)		for the second		
Customar Name:	Muhammo	luhammod Miah			01751119979,01972339444		
Address:	Suraboi, Ha	uraboi, Habiganj			Shahjalal Automobile		
Customar Complain:-		CH NO Full #	MD6M14CA2J4A08021		Present Kms #	8760	
Front Shock absorber has broken.		EN NO Full #	Ak4AJ4023334		Model#	Tvs King Deluke	
		Sale Date #	29.07.2020	.2020 —		CNG/LPG	
		Date of Comp#	25.10.2020		1St PS Date	1st PS Kms	
		Date of Repair #	25.10.2020			100	

 1St Free Service
 2nd Free Service
 3rd Free Service

 Date
 KMs
 Date
 KMs
 Date
 KMs

 24.08.2020
 760
 28.09.2020
 3820
 25.10.2020
 8760

Free service information

Obserbation:- we checked & found that front Shock absorber has broken

Action Taken:- New one front shock absorber replaced.

		Failure P	Failure Particular			7,00 A.S.		
SL	Part NO	Part Name	Qty	Vendor code	Approved	Rejected .		
	G4100180	Front shock absorber	FA	Gabrial (60000297)-04	1/(1/1/24)			
1		/	0	01 8H	l and the second	4-16		
2						- 9		
3		/ 1						
4					- Code			
5								
6								

For Head Office Use

m82000

Alphammad Abdullah Al Zahed Senior Service Engineer IFAD MOTORS LTD. Cell: 61701-227974

Failure Parts Photo

Molyman Hossain Sr. Service Engineer (Trainer IFAD Motors 1 to 01.11.2020

DNS complete.