PRODUCT PERFORMANCE FEEDBACK REPORT

TVS

IFAD MOTORS LTD

DMS JOB NO

Zone Name: Sylhet/Kulaura Engineer Name: Ruhul Amin Approved by: Prabir Biswas, GM - Head of Service & Spare Parts. Sustomar Name: Tajul Islam Mobile No: O1715-310312 Customar Complain: CH NO Full # Dealer Name: AJ MOTORS Customar Complain: CH NO Full # OK4AH4675030 Dil leakage from Front hock absorber. Sale Date # 25-06-2020					не	aa Office		The state of the s			
Zone Name: Sylhet/Kulaura Engineer Name: Ruhul Amin Approved by: Prabir Biswas, GM - Head of Service & Spare Parts. Customar Name: Tajul Islam Mobile No: Dealer Name: Shorip pur, Kulaura Dealer Name: AJ MOTORS Customar Complain: CH NO Full # MD6M14CK3H4A13988 Present Kms # 6,254 Dil leakage from Front Honck absorber. Dil leakage from Front Honck absorber. Date of Compl# 23-09-2020 Model # Tive King Defux honce of Compl# 23-09-2020 Model # Tive King Defux hon				IFAD TOWE	R ,07 Te	jgaon I/A,	Dhak	a-1208	v same		
Approved by: Prabir Biswas, GM-Head of Service & Spare Parts. Customar Name: Tajul Islam	Ref.No: Kulaura/Sep/30/01				F.R SI NO#	(001	Date:	30.09.2020		
Address: Shorip pur, Kulaura Dealer Names: AJ MOTORS Customar Complain: CH NO Full # MD6M14CK3H4A13988 Present Kms # 6,254 Model # Tvs King Defux Shock absorber. Dil leakage from Front Sale Date # 25-06-2020 Work Model # Tvs King Defux Shock absorber. Date of Comp# 23-09-2020 Work Model # Tvs King Defux Date of Repair # 26-09-2020 No	Zone Name: Sylhet/Kulaura				Engineer Name:			Ruhul Amin			
Address: Shorip pur, Kulaura Dealer Names: AJ MOTORS Customar Complain: CH NO Full # MD6M14CK3H4A13988 Present Kms # 6,254 Model # Tvs King Delux Shock absorber. EN NO Full # OKAAH4675030 Model # Tvs King Delux Shock absorber. EN NO Full # OKAAH4675030 Model # Tvs King Delux Shock absorber. Date of Comp# 23-09-2020 Us St PS Date	A	pproved by:	Prabir B	iswas, GM -Head o	of Service 8	& Spare Parts.		W. comba	. 20		
Address: Shorip pur, Kulaura Dealer Names: AJ MOTORS Customar Complain:- CH NO Full # MD6M14CK3H4A13988 Present Kms # 6,254 Model # Tvs King Deflux shock absorber. EN NO Full # DKAAH4675030 Model # Tvs King Deflux place of Comp# 23-09-2020	, je	2						e properte			
Customar Complain: CH NO Full # MD6M14CK3H4A13988 Present Kms # 6,254 Dil leakage from Front shock absorber. EN NO Full # OKAAH4675930 Model # Tvs King Defux pg Date of Comp# 23-09-2020 Jst PS Date	Customar Name: Tajul Islam					Mobile No:			01715-310312		
Dil leakage from Front shock absorber. Sale Date # 25-06-2020 V S	Address: Shorip pur, Kulaura				Dealer Name			AJ MOTORS			
Dil leakage from Front shock absorber. Sale Date # 25-06-2020 VS				·		CK3H4A13988		Present Kms #	6,254		
Sale Date # 25-06-2020								Model #			
Date of Repair # 26-09-2020 No No No Free Service information 1St Free Service	shock absorber.			Sale Date #	25-06-20	20	V2 IDD	IVIOGEI #	Tpg .		
St. Part NO Part Name Qtr Vendor code Approved Rejected Approved Rejected Approved Rejected Approved Rejected Approved Appro				Date of Comp#	23-09-20	20 ,	1:des	elis	1St PS Date	1st PS Kms	
1st Free Service Date KMs Date KMs Date KMs Date KMs 15.07.20 960 18.08.20 5014 Obserbation:- We checked & found that front shock absorber Oil leakage. Action Taken:- Require to replace this parts under warranty for your approval. Failure Particular St. Part NO Part Name Qty Vendor code Approved Rejected Gabrial				Date of Repair #	26-09-2020				No .	No	
Date KMs Date KMs Date KMs Date KMs 15.07.20 960 18.08.20 5614 Action Taken:- Require to replace this parts under warranty for your approval. Failure Particular St. Part NO Part Name Qtw Vendor code Approved Rejected Gestriat 2 001 G14100180 Failure Parts Photo For Head Office Use Failure Parts Photo For Head Office Use										4 ⁴ .	
15.07.20 960 18.08.20 5614 Obserbation:- We checked & found that front shock absorber Oil leakage Action Taken:- Require to replace this parts under warranty for your approval. Failure Particular St. Part NO Part Name Oth Vendor code Approved Rejected Gabrial Gazinoolo Front shock absorber Gabrial A ANTONO Failure Parts Photo For Head Office Use St. No. 2 Amanyona St. No. 2 S				1St Free Service		2nd Free Service			3rd Free Service		
Obserbation:- We checked & found that front shock absorber Oil leakage Action Taken:- Require to replace this parts under warranty for your approval. Failure Particular St. Part NO Part Name Oty Vendor code Approved Rejected G2100010 Front shock absorber 1 Gabrial 2 001/G14100180 3					KMs	Date			Date	KMs	
Action Taken:- Require to replace this parts under warranty for your approval. Failure Particular St. Part NO Part Name Oty Vendor code Approved Rejected Gabrial Gabrial Anyone Failure Parts Photo For Head Office Use Rejected For Head Office Use			1	1	1			614			
St. Part NO Part Name Oty Vendor code Approved Rejected 1 G2100010 Front shock absorber Gabrial 2 0011,G14100180 3 4 5 6 Failure Parts Photo For Head Office Use St. No. 2	roxwerene orronemen				Failur	re Particular		Service and the service and th			
Failure Parts Photo For Head Office Use Starting and the starting and th	SI	Part I	NO.	Part Nan			Vendo	or code	Approved	Rejected	
Failure Parts Photo For Head Office Use Stolzozo. Stolzozo.	+				······	12/			2° 5 °		
Failure Parts Photo For Head Office Use Stropport St									Section 1.		
Failure Parts Photo For Head Office Use Annews Annews Annews Annews Annews Annews							All		1		
Failure Parts Photo For Head Office Use St. No. 2 Amount St. Old 2020. St. Old 2020.			0		***************************************		03	11/201			
Failure Parts Photo For Head Office Use Story 2 Anna 2 Anna 2 Anna 2 Anna 4 Ann					·····			1/1		9	
Failure Parts Photo For Head Office Use Stolzozo All All All All All All Al											
81,No 2 Ministras approv 9/11/				1				- 1660 41 47			
8/10/2020. approv	Failure Parts Photo					For Head Office Use					
	WW 12020					Tres 1	Trs AB reheale				

0/10/2020