PRODUCT PERFORMANCE FEEDBACK REPORT IFAD MOTORS LTD DMS NO: **Head Office** IFAD Tower, Plot-7(New), Tejgoan Industrial Area, Dhaka-1208 Ref.No: March-268 F.R SI NO# 268 Date: 18.03.2021 Engineer Name: Md.Pabel Sarker Mchanic Name: Sumon Dali Zone Name: Cumilla Approved by: Prabir Biswas (Head of Service, Spare Parts & Production) Customer Name: Md Shahin mia Mobile No: 01884406055 **Modina Motors** Kosba, B. baria Dealer Name: Address: CH NO Full # MD6M14CA9K4KA0062 **Customer Complain:-**Present Km 4217 Rear Shock absorber Oil leakage. EN NO Full # AK4KK46A0062 **TVS King Deluxe** Model# Sale Date # 09/10/2020 16.03.2021 Date of Comp# 1St PS Date 1st PS Kms Date of Repair# Free service information 1St Free Service 2nd Free Service **3rd Free Service** Date **KMs** Date **KMs** Date **KMs** 09.11.2020 998 | 14.02.2021 3,954 Observation:we checked &found that Rear Shock absorber oil leakage. Action Taken:- Require to replace this parts under warranty for approval.

<u>Failure Particular</u>							
SL	Part NO.	Part Name	Qty	Vendor code	Approved	Rejected	
1	G2090100	Rear Shock Absorber	01				
2						_	
3		•				China	
4							

<u>Failure Parts Photo</u>	For Head Office Use			
	Head of Service	Engineer	DMS	
	mona) 22/3/2021		Sept.	