TVS		PRODUCT PERFORMANCE FEEDBACK REPORT						
]
WEAD.		IFAD MOTORS LTD						DMS NO:
MOTORSLIMITED		Head Office						3321 -
		IFAD Tower	. Plot-7(New).	Plot-7(New), Tejgoan Industrial Area, Dhaka-1208				
	Pof No:		,	. 0100	F.R SI NO#	65	Date:	29.05.21
Ref.No: Mym-65								
Zone Name: Mymensingh					Engineer Name:Md Jahid Hasan		Mchanic Name:Md Forhad Mia	
	Approved by:	Prabir Biswas (He	ead of Service,Spar	e Parts	& Production	1)		
Customer Name: Md Shahidul Islan			n		Mobile No:	1	721781323	
Address: madargong, Jama			lpur Dealer Nam			Dealer Name:	Bismillah Motors	
Customer Complain:-					114CL6L4N00		Present Kn	
Steering coloum lose			EN NO Full # OL4NL4600233			TVS King Duramax		
			Sale Date # 11.02.21		***	Model#	plus	
**			Date of Comp# 27.05.21			1St PS Date	1st PS Kms	
			Date of Repair# Pending			N/A	N/A	
,			Free service information					12.7
# #					ee Service	3rd	3rd Free Service	
			Date	KMs	Date	KMs	Date	KMs
			02.03.21	1283	05.04.21	3,285	12.05.21	6329
Observation:-By Mechanic we checked and find that the steering coloum lose.								
Action Taken:- Please to be replace the steering coloum with steerint coloum cone kit top & bottom by new one under								
warranty.								new one under
Failure Particular								
SL	Р	Part NO. Part Name			Qty	Vendor code	Approved	Rejected
1	G2150010		Steering coloum		1	vendor code	Approved	Rejected
			Steering coloum cone					
2	2 G5320510		kit top		1			
***************************************			Steering coloum cone					· ·
3	3 G5320500		kit bottom		1		2	
4				2				-
.,	,			/			1.	
Failure Parts Photo For Head Office Use								
	<u>ranure Pa</u>	rts Photo	For Head Office Use					
			Head of Service		ce Engine		er	DMS
•		N. E. S.					as s	
					2001	Mado of the		stitubaha 23/06/2021 Ones 1. to
						(J		Onis lete