Note: - Sparce Parits Not issue at DMB PRODUCT PERFORMANCE FEEDBACK REPORT IFAD MOTORS LTD DMS NO: 3302 **Head Office** IFAD Tower, Plot-7(New), Tejgoan Industrial Area, Dhaka-1208 F.R SI NO Ref.No: Sylhet/Jun/01/304 304 Date: 01.06.2021 Sylhet Sadar **Engineer Name: Tisu Barua** Mchanic Name: Moin Uddin **Zone Name:** Approved by: Prabir Biswas (Head of Service, Spare Parts & Production) Abdul Gofur **Customer Name:** Mobile No: 01758494392 Dealer Name: Address: Companygonj, Sylhet. **Tawsif Motors** Customer Complain:-CH NO Full # MD6M4CLXK4P00222 Present Kms # 8695 Oil leakage from front shock absorber EN NO Full # OL4PK4500180 Model# TVS King Duramax Sale Date # 09.11.2020 Date of Comp# 23.05.2021 1St PS Date 1st PS Kms Date of Repair# Free service information **1St Free Service 2nd Free Service 3rd Free Service** Date **KMs** KMs Date **Date KMs** 02.12.2020 1236 | 13.01.21 3;265 26.02.21 4965 Obserbation:- We checked & found that oil leakege front shock absorber. Action Taken:- Require to replace this parts under warranty for your approvals Failure Particular SL Part NO. Part Name Qty Vendor code Approved Rejected 1 G4100180 Front shock absorber Gabrial 2 3 4 **Failure Parts Photo For Head Office Use Head of Service** Engineer **DMS**