TVS

PRODUCT PERFORMANCE FEEDBACK REPORT

IFAD MOTORS LTD

Head Office

2933

	Martin Co., 4 (14) (15) (15) (15) (15) (15) (15) (15) (15				mb-1-200	Y
IFAD Tower	Plot-7/New	i. Teigoan	Industrial	Area,	Duakarizuc	

Date: 20.12.2020 F.R SI NO# 336 Ref.No: Habiganj/Dce/336 Engineer Name: Mrd. Abdullah Al Mchanic Name; Md. Shippin Alam Zone Name: Habigari Zone Approved by Prabir Biswas (Head of Service, Spare Parts & Production)

	1				Mobile No:	017469424	40
Customer Name:					Dealer Name:	Shahjalal Automobile	
Address:	Nabiganj, Habiganj	- 1 · · · · · · · · · · · · · · · · · ·	Teancean	4CA7J4A079	k	Present Km	9460
Customer Comple	iin:	CH NO Full #			and the second		Tys King Deluxe
		EN NO Full #	AK4AJ4	323250	<u> </u>	- Model#	CNG/LPG
Front Shock absorber has been broken. EN NO Full # ARAAJ4323250							
		Date of Comp#	19.12.2020			15t PS Date	1st PS Kms
		Date of Repair# 19.12.2020					
		100000 NO 100000000000000000000000000000		Free se	ervice informat		
		1St Free Service 2nd F		ee Service	3rd Free Service		
			KMs	Date	KMs	Date	KMs
		Date		28.11.2020	2.760	19.12.2020	9460
		08.10.2020	970	1 20.11.6VEA	American Commence	4	A

Observation:- We checked & found that front Shock absorber has been broken

Action Taken: New one front shock absorber replaced.

		Failure Partic	Failure Particular			
		Part Name	Qty	Vendor code	Approved	Rejected
SL	Part NO.			60000297		
	22.22.22.2	_Front shock absorber	101	G21000		
1	<u> </u>	Z	1 1	04008		
		- V				
2	G210000					
3	and the second s	· · · · · · · · · · · · · · · · · · ·	······································			

			rts Pho		
9					
		A			
		烈			
	To		4	•	
	Y		1		
		1. 84	1377	C	
			-	लुक	

Head of Service

For Head Office Use

Engineer

Mohammad Abdullah Al Zahed Senior Service Engineer IFAD MOTORS LTD. Cell: 01701-227974