
I FAD MOTORSLIMITED

PRODUCT PERFORMANCE FEEDBACK REPORT





DMS NO:



2930

IFAD Tower, Plot-7(New), Tejgoan Industrial Area, Dhaka-1208

Ref.No:	Mym-25	F.R SI No	25	Date:	19.12.20
Zone Name:	Mymensingh	Engineer Name:Md Jahid Hasa		Mchanic Nam	e:Md Rofiqul Islam

Approved by: Prabir Biswas (Head of Service, Spare Parts & Production)

Customer Name:	Md Forhad			Mobile No:	01740845815			
Address:	Cecuya, Mymensingh				Dealer Name:	Jerin Motors		
Customer Complain:-		CH NO Full #	MD6M14CL5K4P00127		Present Km	5619 🕌		
Steering coloum lose		EN NO Full #	OL4PK4800423 🥌		Model #	TVS King Duramax \		
		Sale Date #	27.10.20			4		
		Date of Comp#	15.12.20		1St PS Date	1st PS Kms		
		Date of Repair#	Pending		N/A	N/A		
		Free service information						
		1St Free Serv	ervice 2nd F		ree Service	3rd Free Service		
		Date	KMs	Date	KMs	Date	KMs	
		24-11-20	3182					

Observation:-By Mechanic we checked and find that the sreering coloum lose & recer set are damage.

Action Taken:- Please to be replace the recer top & bottom by new one under warranty.

Failure Particu				_		- "
	lar	CII	****	ובע	IIro	Fall
	ıaı	Cu	LIV		uic	ı an

SL	Part NO.	Part Name	Qty	Vendor code	Approved	Rejected
1	G5320510 ¸	Steering cone kit bot	1 ,			
2	G5320500	Steering cone kit Top	1			
3						
4						

Failure Parts Photo	For Head Office Use					
	Head of Service	Engineer	DMS			
	2012/2020 2012/2020	B02.20	My ported of the solution of t			