PRODUCT PERFORMANCE FEEDBACK REPORT DMS NO: IFAD MOTORS LTD **Head Office** IFAD Tower, Plot-7(New), Tejgoan Industrial Area, Dhaka-1208 24.02.2021 Date: F.R SI NO# Mchanic Name: Md. Shipon Alom Engineer Name: Md. Abdullah Al Ref.No: Habiganj/Feb/346 Zone Name: Habiganj Zone Approved by: Prabir Biswas (Head of Service, Spare Parts & Production) 01782758531 Mobile No: Shahjalal Automobile Md. Juyel Miah Customer Name: Dealer Name: Present Km Mirpur,Bahubole, Habiganj MD6M14CA5J4A07963 Tys King Deluxe Address: CH NO Full # Model# Customer Complain:-AK4AJ4223210 CNG/LPG EN NO Full # Front Shock absorber has been 08.09.2020 1st PS Kms Sale Date # 1St PS Date 23.02.2021 broken. Date of Comp# 23.02.2021 Date of Repair# Free service information 3rd Free Service 2nd Free Service 1St Free Service **KMs** Date KMs Date KMs 8250 23.02.2021 Date 4,120 01.12..2020 970 13.10.2020 Observation:- We checked & found that front Shock absorber has been broken... Action Taken: New one front shock absorber replaced. Failure Particular Rejected Approved Vendor code Qty Part Name 6000297 Part NO. SL G2100010 Front shock absorber 01 26.12.17 H G4100180 1 2 For Head Office Use Engineer Failure Parts Photo Head of Service