PRODUCT PERFORMANCE FEEDBACK REPORT IFAD MOTORS LTD **Head Office** IFAD Tower, Plot-7(New), Tejgoan Industrial Area, Dhaka-1208 Ref.No: Habiganj/Feb/345 F.R SI NO# 345 Date: 18.02.2021 Engineer Name: Md. Abdullah Al Mchanic Name: Md. Shipon Alom Zone Name: Habiganj Zone Zabed Approved by: Prabir Biswas (Head of Service, Spare Parts & Production) **Customer Name:** Md. Anam Miah Mobile No: 01737409155, 01781477431 Address: Lakhai, Habiganj Dealer Name: Shahjalal Automobile Customer Complain:-CH NO Full # MD6M14CA0J4A07899 Present Km Front Shock absorber has been broken. EN NO Full # AK4AJ4022717 Tvs King Deluxe Model# Sale Date # 01.11.2020 Date of Comp# 17.02.2021 1St PS Date 1st PS Kms Date of Repair# 17.02.2021 Free service information 1St Free Service 2nd Free Service **3rd Free Service** Date KMs Date **KMs** Date 05.12.2020 870 19.01.2021 3,830 17.02.2021 Observation:- We checked & found that front Shock absorber has been broken..

6055

CNG/LPG

KMs

6055

Action Taken:- New one front shock absorber replaced.

		Failure Parti	cular	3	- The	•
SL	Part NO.	Part Name	Qty	Vendor code	Approved	Rejected
				60000297	0	9
1	G4100180	Front shock absorber	01	G2100010		2.00
			a, tect	26/12/17H	and the second	
2	G2100010 AM	810				
3						
4						- 9 1 19

<u>Failure Parts Photo</u>	For Head Office Use				
	Head of Service	Engineer	DMS		
	misses 14/3/2021		Der Gours		