PRODUCT PERFORMANCE FEEDBACK REPORT IFAD MOTORS LTD DMS NO: Head Office 3269 IFAD Tower, Plot-7(New), Tejgoan Industrial Area, Dhaka-1208 Ref.No: Dhaka/May/28 F.R SI NO# 28 Date: 19.05.2021 Zone Name: Dhaka 1 Engineer Name: Milon Hossain Mchanic Name: Md.Yousuf Approved by: Prabir Biswas (Head of Service, Spare Parts & Production) **Customer Name:** Md.Faisal Ahmed Mobile No: 01928-429612 Address: Mirpur, Dhaka Dealer Name: Customer Complain:-Satata As Center CH NO Full # MD6M14CA1J4L09540 Front Shockabsorber Oil Leakage Present Kms 7540 EN NO Full # AK4LJ4994138 Sale Date # 28.12.2020 Model# TVS King Deluxe Date of Comp# 18.05.2021 1St PS Date 1st PS Kms Date of Repair# Free service information 1St Free Service 2nd Free Service 3rd Free Service Date **KMs** Date **KMs** Date **KMs** 04.02.2021 987 28.03.2021 Observation:-2,890 28.04.2021 4798 we checked &found that front Shockabsorber oil Leakage Action Taken:- Require to replace this parts under warranty for your kind approval. Failure Particular SL Part NO. Part Name Qty Vendor code 1 Approved Rejected G4100180 SHOCK ABSORBER FRONT 2 3 4 5 **Failure Parts Photo** For Head Office Use **Head of Service**

