PRODUCT PERFORMANCE FEEDBACK REPORT

IFAD MOTORS LTD

Head Office

DMS NO

3033.

IFAD Tower, Plot-7(New), Tejgoan Industrial Area, Dhaka-1208 Ref.No: Habiganj/Jan/340 F.R SI NO# 340 Date: 21.01.2021 Mid Abdullah Al Zone Name: Habigani Zone Mchanic Name: Mr. Shipon Alom Approved by: Prabir Biswas (Head of Service, Spare Parts & Production)

Customer Name: Md. Mokhlish Miah 81731441282,017572691 Mobile No: Baniachong , Habiganj Dealer Name Shahjalal Automobile Customer Complain:-CH NO Full # MD6M14CA4J4A07954 Present Km 6950 Front Shock absorber has been broken. EN NO Full H AK4AJ4323073 Tvs King Deluxe Model # Sale Date # 22.09.2020 CNG/LPG Date of Comp# 20.01.2021 ISt PS Date Date of Repair# 20.01.2021 Free service information 15t Free Service 2nd Free Service

990

Observation:- We checked & found that front Shock absorber has been broken...

Action Taken:- New one front shock absorber replaced

	Failure Particular						
St.	Part NO.	Part Name		Vendor code	Approved	Rejected	
			1	60000297			
	-104	Front shock absorber	(01	/ G2100010 :	N 3		
	6121000106	4,		Q30118 H			
2				100 m on 1 d o 0.000 m o 41 doc 1 doc 1 doc 1 doc 1		(
1						According to a policy of account	
4							

Head of Service

Failure Parts Photo

Engineer

For Head Office Use

Date

20101 2021

Mohammad Abdullah Al Zahed Semor Service Engineer IFAD MOTORS LID.

Cell: 01701-221974