PRODUCT PERFORMANCE FEEDBACK REPORT IFAD MOTORS LTD DMS NO: 319 **Head Office** IFAD Tower, Plot-7(New), Tejgoan Industrial Area, Dhaka-1208 23.02.21 F.R SI NO# 41 Date: Ref.No: Mym-41 Mchanic Name:Md Rofiqul Islam Engineer Name: Md Jahid Hasan Zone Name: Tangail Approved by: Prabir Biswas (Head of Service, Spare Parts & Production) 1722391321 Mobile No: **Customer Name:** Md Shadat Hossain Mama vagina Engineering **Dealer Name:** Tangail sadar Address: Present Km 9763+ MD6M14LA0K4A19844 CH NO Full # **Customer Complain:-TVS King Deluxe** Front shock absorber oil leakage EN NO Full # AK4AK4536232 Model# 20.07.2020 Sale Date # 19.02.21 1St PS Date 1st PS Kms Date of Comp# N/A N/A Date of Repair# Pending Free service information **1St Free Service 2nd Free Service 3rd Free Service KMs Date KMs Date KMs Date** 23.08.2020 2133 Observation:-By Mechanic we checked and find that the shock absorber fr oil leakage Action Taken:- Please to be replace the shock absorber fr by new one under warranty. Failure Particular Vendor code Approved Rejected Part NO. Part Name SL Shock absorber fr G4100180 03/204 3 4 Failure Parts Photo For Head Office Use **DMS Head of Service Engineer**